



**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS,
BALLOONS, & AIRSHIPS**

BIWEEKLY 2005-02

This electronic copy may be printed and used in lieu of the FAA biweekly paper copy.

U.S. Department of Transportation
Federal Aviation Administration
Regulatory Support Division
Delegation and Airworthiness Programs Branch, AIR-140
P. O. Box 26460
Oklahoma City, OK 73125-0460
FAX 405-954-4104

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; - See AD for additional information;			
Biweekly 2005-01			
2004-26-09		Rolls-Royce Corporation	Engine: 250-B17, -B17B, -B17C, -B17D, -B17E, 250-C20, -C20B, -C20F, -C20J, -C20S, and -C20W Series Turboprop and Turboshaft
2004-26-11 2005-01-04	S 98-15-13	Bell Helicopter Textron Canada Raytheon Aircraft Company	Rotorcraft: 222, 222B, 222U, 230, 430 65-90, 65-A90, B90, C90, C90A, C90B, E90, F90, H90, 100, A100, A100-1, (RU-21J), B100, 200, 200C, 200CT, 200T, A200, A200C, A200CT, B200, B200C, B200CT, B200T, 300, B300, B300C, 99, 99A, A99,, A99A, B99, C99
2005-01-10 2005-01-11	S 74-06-01	The New Piper Aircraft, Inc Pilatus Aircraft Ltd.	PA-23-235, PA-23-250, and PA-E23-250 PC-12 and PC-12/45
Biweekly 2005-02			
98-20-38 R1	R	Raytheon Aircraft Company	Beech 200 (A100-1 (U-21J)), Beech 200C, Beech 200CT, Beech 200T, Beech A200 (C-12A) or (C-12C), Beech A200C (UC-12B), Beech A200CT (C-12D), (FWC-12D), (RC-12D), (C-12F), (RC-12G), (RC-12H), (RC-12K), or (RC-12P), B200CT, and B200T
2005-01-14 2005-01-17 2005-01-18	S 2002-21-16 S 98-03-14 S 93-25-07	Bombardier-Rotax GmbH EXTRA Flugzeugbau GmbH Raytheon Aircraft Company	Engine: 912 F, 912 S, and 914 F Series Reciprocating EA-300 and EA-300/S A100-1 (U-21J), 200, B200, A200 (C-12A), A200 (C-12C), A200C (UC-12B), A200CT (C-12D), A200CT (FWC-12D), A200CT (RC-12D), A200CT (C-12F), A200CT (RC-12G), A200CT (RC-12H), A200CT (RC-12K), A200CT (RC-12P), A200CT (RC-12K), 200C, B200C, 200CT, 200T, B200C (C-12F), B200C (UC-12F), B200C (UC-12M), B200CT, 300, B300, B300C, and B300C
2005-01-19 2005-02-01	S 2004-10-15	GARMIN International Inc The Lancair Company	Appliance: GTX 33, GTX 33D, GTX 330, and GTX 330D Mode S Transponders LC40-550FG and LC42-550FG

**RAYTHEON AIRCRAFT COMPANY
AIRWORTHINESS DIRECTIVE
REVISION**

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

98-20-38 R1 Raytheon Aircraft Company: Amendment 39-13946; Docket No. FAA-2004-19078; Directorate Identifier 98-CE-17-AD.

When Does This AD Become Effective?

(a) This AD becomes effective on February 18, 2005.

What Other ADs Are Affected by This Action?

(b) This AD revises AD 98-20-38, Amendment 39-10806.

What Airplanes Are Affected by This AD?

(c) This AD affects the following airplane models, all serial numbers, that are certificated in any category:

- (1) Beech 200 (A100-1 (U-21J)).
- (2) Beech 200C.
- (3) Beech 200CT.
- (4) Beech 200T.
- (5) Beech A200 (C-12A) or (C-12C).
- (6) Beech A200C (UC-12B).
- (7) Beech A200CT (C-12D), (FWC-12D), (RC-12D), (C-12F), (RC-12G), (RC-12H), (RC-12K), or (RC-12P).
- (8) B200CT.
- (9) B200T.

Note 1: The actions of AD 96-09-13 are required for the Beech Models B200 and B200C airplanes.

What Is the Unsafe Condition Presented in This AD?

(d) The actions specified in this AD are intended to minimize the potential hazards associated with operating these airplanes in severe icing condition by providing more clearly defined procedures and limitations.

What Must I Do To Address This Problem?

(e) Within 30 days after November 4, 1998 (the effective date of AD 98-20-38), do the requirements of paragraphs (e)(1) and (e)(2) of this AD, unless already accomplished.

Note 2: Operators should initiate action to notify and ensure that flight crewmembers are apprised of this change.

(1) Revise the FAA-approved Airplane Flight Manual (AFM) by incorporating the following into the Limitations Section of the AFM. This may be accomplished by inserting a copy of this AD in the AFM.

"Warning

Severe icing may result from environmental conditions outside of those for which the airplane is certificated. Flight in freezing rain, freezing drizzle, or mixed icing conditions (supercooled liquid water and ice crystals) may result in ice build-up on protected surfaces exceeding the capability of the ice protection system, or may result in ice forming aft of the protected surfaces. This ice may not be shed using the ice protection systems, and may seriously degrade the performance and controllability of the airplane.

- During flight, severe icing conditions that exceed those for which the airplane is certificated shall be determined by the following visual cues. If one or more of these visual cues exists, immediately request priority handling from Air Traffic Control to facilitate a route or an altitude change to exit the icing conditions.

–Unusually extensive ice accumulation on the airframe and windshield in areas not normally observed to collect ice.

–Accumulation of ice on the upper surface of the wing, aft of the protected area.

–Accumulation of ice on the engine nacelles and propeller spinners farther aft than normally observed.

- Since the autopilot, when installed and operating, may mask tactile cues that indicate adverse changes in handling characteristics, use of the autopilot is prohibited when any of the visual cues specified above exist, or when unusual lateral trim requirements or autopilot trim warnings are encountered while the airplane is in icing conditions.

- All wing icing inspection lights must be operative prior to flight into known or forecast icing conditions at night. [Note: This supersedes any relief provided by the Master Minimum Equipment List (MMEL).]"

(2) Revise the FAA-approved AFM by incorporating the following into the Normal Procedures Section of the AFM. This may be accomplished by inserting a copy of this AD in the AFM.

"The Following Weather Conditions May Be Conducive to Severe In-Flight Icing

- Visible rain at temperatures below 0 degrees Celsius ambient air temperature.
- Droplets that splash or splatter on impact at temperatures below 0 degrees Celsius ambient air temperature.

Procedures for Exiting the Severe Icing Environment

These procedures are applicable to all flight phases from takeoff to landing. Monitor the ambient air temperature. While severe icing may form at temperatures as cold as -18 degrees Celsius, increased vigilance is warranted at temperatures around freezing with visible moisture present. If the visual cues specified in the Limitations Section of the AFM for identifying severe icing conditions are observed, accomplish the following

- Immediately request priority handling from Air Traffic Control to facilitate a route or an altitude change to exit the severe icing conditions in order to avoid extended exposure to flight conditions more severe than those for which the airplane has been certificated.
- Avoid abrupt and excessive maneuvering that may exacerbate control difficulties.
- Do not engage the autopilot.
- If the autopilot is engaged, hold the control wheel firmly and disengage the autopilot.
- If an unusual roll response or uncommanded roll control movement is observed, reduce the angle-of-attack.
- Do not extend flaps when holding in icing conditions. Operation with flaps extended can result in a reduced wing angle-of-attack, with the possibility of ice forming on the upper surface further aft on the wing than normal, possibly aft of the protected area.
- If the flaps are extended, do not retract them until the airframe is clear of ice.
- Report these weather conditions to Air Traffic Control."

(f) As an alternative method of compliance to the actions required by paragraph (e)(2) of this AD, revise the Abnormal Procedures Section or Emergency Procedures Section of the AFM instead of the Normal Procedures section of the AFM. Insert the information presented in paragraph (e)(2) of this AD into the applicable AFM section.

(g) The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may incorporate the AFM revisions required by this AD. Enter this information into the aircraft records showing compliance with this AD following section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).

May I Request an Alternative Method of Compliance?

(h) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Standards Office, Small Airplane Directorate, FAA. For information on any already approved alternative methods of compliance, contact Mr. Paul Pellicano, Aerospace Engineer (Icing Specialist), Atlanta Aircraft Certification Office, FAA, One Crown Center, 1895 Phoenix Boulevard, Suite 450, Atlanta, Georgia 30349; telephone: (770) 703-6064; facsimile: (770) 703-6097.

May I Get Copies of the Documents Referenced in This AD?

(i) You may view the AD docket at the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC, or on the Internet at <http://dms.dot.gov>.

Issued in Kansas City, Missouri, on January 11, 2005.

Michael K. Dahl,
Acting Manager, Small Airplane Directorate, Aircraft Certification Service.
[FR Doc. 05-895 Filed 1-18-05; 8:45 am]
BILLING CODE 4910-13-P

BW 2005-02

**BOMBARDIER-ROTAX GMBH
AIRWORTHINESS DIRECTIVE
ENGINE**

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

2005-01-14 Bombardier-Rotax GmbH: Amendment 39-13939. Docket No. 2002-NE-33-AD. Supersedes AD 2002-21-16 (Amendment 39-12923).

Effective Date

(a) This airworthiness directive (AD) becomes effective February 15, 2005.

Affected ADs

(b) This AD supersedes AD 2002-21-16.

Applicability

(c) This AD applies to Bombardier-Rotax GmbH 912 F, 912 S, and 914 F series reciprocating engines. These engines are installed on, but not limited to, Diamond Aircraft Industries, DA20-A1, Diamond Aircraft Industries GmbH Model HK 36 TTS, Model HK 36TTC, and Model HK 36 TTC-ECO, Iniziative Industriali Italiane S.p.A. Sky Arrow 650 TC and Sky Arrow 650 TCN, Aeromot-Industria Meccanico Metalurgica lta., Models AMT-300 and AMT-200S, and Stemme S10-VT aircraft.

Unsafe Condition

(d) This AD results from the manufacturer discovering that under certain circumstances, the oil level in the oil tank can fall below the minimum level required to sustain proper engine lubrication. The actions specified in this AD are intended to prevent damage to the engine valve train due to inadequate venting of the lubrication system, which can result in an in-flight engine failure and forced landing.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

Initial Venting and Inspection for Correct Venting

(f) Before the next engine start, for all Bombardier-Rotax GmbH 912 F, 912 S, and 914 F series reciprocating engines that have not been operated since doing any of the actions identified in section 1.5(a) of Rotax Mandatory Service Bulletin (MSB) SB-912-036/SB-914-022, Revision 1, dated August 2002, do the following:

(1) Perform venting of the lubrication system; and

(2) Perform inspection for correct venting of the hydraulic valve tappets. Use Section 3.1.1 through section 3.1.4 of the Accomplishment Instructions of Rotax MSB SB-912-036/SB-914-022, Revision 1, dated August 2002 to do the venting and inspection.

Inspection of Engine Valve Train

(g) Before the next engine start, for all Bombardier-Rotax GmbH 912 F, 912 S, and 914 F series reciprocating engines that have been operated for 50 hours or less on the effective date of this AD since doing any of the actions identified in section 1.5 (b) of Rotax MSB SB-912-036/SB-914-022, Revision 1, dated August 2002, do the following:

- (1) Disassemble and perform inspection of the engine valve train; and
- (2) Reassemble, vent the lubrication system, and inspect for correct venting of the hydraulic valve tappets. Use Section 3.1.5 through Section 3.1.7 of the Accomplishment Instructions of Rotax MSB SB-912-036/SB-914-022, Revision 1, dated August 2002.

Repetitive Venting of the Lubrication System

(h) Thereafter, for all Bombardier-Rotax GmbH 912 F, 912 S, and 914 F series reciprocating engines, after doing any of the actions in the following paragraphs (h)(1) through (h)(4), vent the lubrication system and inspect for correct venting of the hydraulic valve tappets before starting the engine. Use section 3.1.1 through section 3.1.4 of the Accomplishment Instructions of Rotax MSB SB-912-036/SB-914-022, Revision 1, dated August 2002 to do the venting and inspecting.

- (1) The installation of a new or overhauled engine.
- (2) The oil system has been opened allowing air to enter the valve train (e.g. oil pump, oil cooler, oil suction line removed which allows oil to drain from the engine oil galleries).
- (3) The engine oil was changed using procedures other than those included in section 1.2 of Rotax MSB SB-912-036/SB-914-022 Revision 1, dated August 2002.
- (4) The propeller was turned more than one turn in the wrong direction of rotation.

Removal of Existing Oil Dipstick From Service

(i) At the next oil change or within 100 hours time-in-service after the effective date of this AD, whichever is later, remove the oil dipstick, part number (P/N) 956150, from service, and install a dipstick that has a different P/N. Information on removing oil dipstick P/N 956150 from service can be found in Rotax MSB SB-912-040/SB-914-026, Revision 1, dated August 2003.

Prohibition of Oil Dipstick, P/N 956150

(j) After the effective date of this AD, do not use dipstick P/N 956150 after complying with paragraph (i) of this AD.

Alternative Methods of Compliance

(k) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Special Flight Permits

- (l) Special flight permits are not allowed.

Material Incorporated by Reference

(m) You must use Bombardier-Rotax GmbH Mandatory Service Bulletin SB-912-036/SB-914-022 Revision 1, dated August 2002, to perform the venting and inspecting required by this AD. The Director of the Federal Register previously approved the incorporation by reference of this Mandatory Service Bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51, on October 23, 2002 (67 FR 65033). You can get a copy from Bombardier-Rotax GmbH, Gunskirchen, Austria; telephone 7246-601-423; fax 7246-601-760. You can review a copy at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to:

http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Related Information

(n) Austro Control airworthiness directives No. 113R1, dated August 30, 2002, and No. 116, dated September 15, 2003, and Rotax Service Instruction SI-04-1997, Revision 3, dated September 2002 also address the subject of this AD.

Issued in Burlington, Massachusetts, on January 3, 2005.

Francis A. Favara,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 05-486 Filed 1-10-05; 8:45 am]

BILLING CODE 4910-13-P

BW 2005-02

**EXTRA FLUGZEUGBAU GMBH
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2005-01-17 EXTRA Flugzeugbau GmbH: Amendment 39-13942; Docket No. FAA-2004-19443; Directorate Identifier 2004-CE-32-AD; Supersedes AD 98-03-14; Amendment 39-10307.

When Does This AD Become Effective?

(a) This AD becomes effective on February 28, 2005.

What Other ADs Are Affected by This Action?

(b) This AD supersedes AD 98-03-14, Amendment 39-10307.

What Airplanes Are Affected by This AD?

(c) This AD affects the following airplane models and serial numbers that:

(1) Are certificated in any category; and

(2) Have not had the left-hand (LH) and right-hand (RH) upper longeron cutout-bridge inspected and modified following EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB-300-3-93, Issue: A, Date: January 12, 1994.

Model	Serial Nos.
EA-300	VI and 01 through 50.
EA-300/S	01 through 17.

What Is the Unsafe Condition Presented in This AD?

(d) This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Germany. The actions specified in this AD are intended to detect and correct cracks in the upper longeron cutout-bridge, which could cause the upper longeron cutout-bridge to fail resulting in structural damage to the fuselage. This condition could lead to loss of control of the airplane.

What Must I Do To Address This Problem?

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
(1) Inspect the LH and RH upper longeron cutout-bridge, part number (P/N) PC-23102.IX), for cracks.	Upon accumulating 1,000 hours time-in-service (TIS) on the upper longeron or within the next 100 hours TIS after March 16, 1998 (the effective date of AD 98-03-14), whichever occurs later, unless already done.	Follow EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB-300-3-93, Issue: A, Date: January 12, 1994; or EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB-300-3-93, Issue: B, Date: June 10, 1998.
(2) If you find any cracks in the upper longeron cutout-bridge during the inspection required in paragraph (e)(1) of this AD, do the following: (i) repair any cracks; and (ii) modify the upper longeron cutout-bridge.	Before further flight after the inspection required in paragraph (e)(1) of this AD, unless already done.	Follow EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB-300-3-93, Issue: A, Date: January 12, 1994; or EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB-300-3-93, Issue: B, Date: June 10, 1998.
(3) If you do not find any cracks in the upper longeron cutout-bridge during the inspection required in paragraph (e)(1) of this AD, you must still modify the upper longeron cutout-bridge.	Before further flight after the inspection required in paragraph (e)(1) of this AD, unless already done.	Follow EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB300-3-93, Issue: A, Date: January 12, 1994; or EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB-300-3-93, Issue: B, Date: June 10, 1998.
(4) If you modified the upper longeron cutout-bridge following EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB-300-3-93, Issue: A, Date: January 12, 1994, or EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB-300-3-93, Issue: B, Date: June 10, 1998, Procedure I, you do not need to do any further actions.	As of February 28, 2005 (the effective date of this AD).	As stated in EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB-300-3-93, Issue: A, Date: January 12, 1994, or EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB-300-3-93, Issue: B, Date: June 10, 1998.
(5) If you modified the upper longeron cutout-bridge following Procedure II of EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB-300-3-93, Issue: B, Date: June 10, 1998, you must replace the new internal bridges every 1,000 hours TIS.	As of February 28, 2005 (the effective date of this AD).	As stated in EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB-300-3-93, Issue: B, Date: June 10, 1998.

May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Standards Office, Small Airplane Directorate, FAA. For information on any already approved alternative methods of compliance, contact Karl Schletzbaum, Aerospace Engineer, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, MO 64106; telephone: (816) 329-4146; facsimile: (816) 329-4090.

Is There Other Information That Relates to This Subject?

(g) German AD Number D-1994-043R1, dated May 17, 2004, also addresses the subject of this AD.

Does This AD Incorporate Any Material by Reference?

(h) You must do the actions required by this AD following the instructions in EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB-300-3-93, Issue: A, Date: January 12, 1994; or EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB-300-3-93, Issue: B, Date: June 10, 1998.

(1) On March 16, 1998 (63 FR 5881, February 5, 1998) and in accordance with 5 U.S.C. 552(a) and 1 CFR part 51, the Director of the Federal Register approved the incorporation by reference of EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB-300-3-93, Issue: A, Date: January 12, 1994.

(2) As of February 28, 2005, and in accordance with 5 U.S.C. 552(a) and 1 CFR part 51, the Director of the Federal Register approved the incorporation by reference of EXTRA Flugzeugbau GmbH Service Bulletin EA-300 & EA-300/S Doc: SB-300-3-93, Issue: B, Date: June 10, 1998.

(3) To get a copy of this service information, contact EXTRA Flugzeugbau GmbH, Flugplatz Dinslaken, D-46569 H[uuml]nxe, Germany. To review copies of this service information, go to the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, go to:

http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html or call (202) 741-6030. To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001 or on the Internet at *<http://dms.dot.gov>*. The docket number is FAA-2004-19443.

Issued in Kansas City, Missouri, on January 5, 2005.

William J. Timberlake,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-607 Filed 1-18-05; 8:45 am]

BILLING CODE 4910-13-P

**RAYTHEON AIRCRAFT COMPANY
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

CORRECTION: There are typos in the superseded AD# reference in the Compliance section of AD 2005-01-18, paragraph (e), page 2943, published today, January 19, 2005 in the Federal Register (FR). The superseded AD# of AD 2005-01-18 should be 93-25-07. GPO (Government Printing Office) will issue a correction to the FR. We've corrected this copy and added *revision marks* to the "pdf" copy for clarity.

2005-01-18 Raytheon Aircraft Company: Amendment 39-13943; Docket No. 2004-CE-01-AD.

When Does This AD Become Effective?

(a) This AD becomes effective on March 1, 2005.

What Other ADs Are Affected by This Action?

(b) This AD supersedes AD 93-25-07, Amendment 39-8773.

What Airplanes Are Affected by This AD?

(c) This AD affects the following Beech airplane models and serial numbers that are certificated in any category:

Model	Serial Nos.
(1) A100-1 (U-21J)	BB-3 through BB-5
(2) 200 and B200	BB-2 and BB-6 through BB-1462.
(3) A200 (C-12A) and A200 (C-12C).	BC-1 through BC-75 and BD-1 through BD-30.
(4) A200C (UC-12B)	BJ-1 through BJ-66.
(5) A200CT (C-12D).	BP-1, BP-22, and BP-24 through BP-51.
(6) A200CT (FWC-12D).	BP-7 through BP-11.
(7) A200CT (RC-12D).	GR-1 through GR-13.
(8) A200CT (C-12F)	BP-52 through BP-63.
(9) A200CT (RC-12G).	FC-1 and FC-3.
(10) A200CT (RC-12H).	GR-14 through GR-19.
(11) A200CT (RC-12K).	FE-1 through FE-9.
(12) A200CT (RC-12P).	FE-10 through FE-24.
(13) A200CT (RC-12K).	FE-25 through FE-31.
(14) 200C and B200C	BL-1 through BL-72 and BL-124 through BL-138.
(15) 200CT	BN-1 through BN-4 and B200CT.
(16) 200T	BT-1 through BT-38 and B200T.
(17) B200C (C-12F)	BL-73 through BL-112 and BL-118 through BL-123.

(18) B200C (C-12F)	BP-64 through BP-71.
(19) B200C (UC-12F)	BU-1 through BU-10.
(20) B200C (UC-12M).	BV-1 through BV-12.
(21) B200CT	FG-1 and FG-2.
(22) 300	FA-1 through FA-228.
(23) 300	FF-1 through FF-19.
(24) B300	FL-1 through FL-103.
(25) B300C	FM-1 through FM-8.
(26) B300C	FN-1.

What Is the Unsafe Condition Presented in This AD?

(d) As currently written, AD 93-25-07 allows continued flight if cracks are found in less than five fuselage stringers in the area of the rear pressure bulkhead. In 1996, FAA developed policy to not allow airplane operation when known cracks exist in primary structure, unless the ability to sustain limit and ultimate load with these cracks is proven. The fuselage stringers in the area of the rear pressure bulkhead are considered primary structure. This AD will bring the actions of AD 93-25-07 in compliance with current FAA policy. The actions specified in this AD are intended to detect and correct any cracked fuselage stringers in the rear pressure bulkhead area, which could result in structural damage to the fuselage. This damage could lead to failure of the fuselage with potential loss of control of the airplane.

What Must I Do To Address This Problem?

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
(1) For <i>airplanes that have been known cracks that exist in any of the aft fuselage stringer locations (No. 5 through No. 11 on both the left-hand and right-hand sides)</i> . Either modify or incorporate repairs as specified below. These cracks could have been detected through compliance with AD 93-25-07 and/or Raytheon Mandatory Service Bulletin SB 53-2472, any revision level: (i) Incorporate the applicable modification kit or kits as specified in Raytheon Mandatory Service Bulletin SB 53-2472, Rev. 4, Issued: June, 1993, Revised: July, 2003; or (ii) Incorporate external doubler repairs on all aft fuselage stringer locations (No. 5 through No. 11 on both the left-hand and right-hand sides)	<i>If airplane has less than five known cracked stringers:</i> Within 25 cycles after March 1, 2005 (the effective date of this AD), unless already done. If cycles are unknown, then you may divide hours time-in-service (TIS) by .75 (18.75 hours TIS ÷ .75 = 25 cycles). <i>If airplane has five or more known cracked stringers:</i> Before further flight after March 1, 2005 (the effective date of this AD), unless already done. AD 93-25-07 already required this.	Incorporate the modification kit(s) following The procedures in Raytheon Mandatory Service Bulletin SB 53-2472, Rev. 4, Issued: June, 1993, Revised: July, 2003. Incorporate the external doubler repairs following the procedures in the maintenance manual.

<p>(2) <i>For all airplanes that do not have either the modifications or repairs specified in paragraphs (e)(1)(i) and (e)(1)(ii) of this AD incorporated in all aft fuselage stringer locations (No. 5 through No. 11 on both the left-hand and right-hand sides):</i> Inspect these aft fuselage stringers. If sealant covers the stringers, you must remove it to facilitate the required inspections and then reapplied. You may terminate the repetitive inspections when all aft fuselage stringer locations (No. 5 through No. 11 on both the left-hand and right-hand sides) are modified.</p>	<p><i>For airplanes affected by AD 93–25–07:</i> Initially inspect at the next inspection interval required by AD 93–25–07. Repetitively inspect thereafter at intervals not to exceed 500 cycles. If cycles are unknown, then you may divide TIS by .75 (375 hours TIS ÷ .75 = 500 cycles). <i>For airplanes not affected by AD 93–25–07:</i> Initially inspect upon accumulating 2,500 cycles on the fuselage or within the next 25 cycles after March 1, 2005 (the effective date of this AD), whichever occurs later, unless already done. Repetitively inspect thereafter at intervals not to exceed 500 cycles. If cycles are unknown, then you may divide hours TIS by .75 (1,875 hours TIS ÷ .75 = 2,500 cycles; 375 hours TIS ÷ .75 = 500 cycles; and 18.75 hours TIS ÷ .75 = 25 cycles).</p>	<p>Inspect following the procedures in Raytheon Mandatory Service Bulletin SB 53–2472. Rev. 4, Issued: June, 1993, Revised: July, 2003.</p>
<p>(3) If any cracks are found during any inspection required by this AD, do one of the following:</p> <p>(i) Incorporate the applicable modification kit or kits as specified in Raytheon Mandatory Service Bulletin SB 53–2472, Rev. 4, Issued: June, 1993, Revised: July, 2003; or</p> <p>(ii) Incorporate external doubler repairs on all aft fuselage stringer locations (No. 5 through No. 22 on both the left-hand and right-hand sides)</p>	<p><i>If less than five cracked stringers are found:</i> Within 25 cycles after March 1, 2005 (the effective date of this AD), unless already done. If cycles are unknown, then you may divide hours TIS by .75 (18.75 hours TIS ÷ .75 = 25 cycles). <i>If five or more cracked stringers are found:</i> Before further flight after any inspection where five cracked stringers are found, unless already done.</p>	<p>Incorporate the modification kit(s) following The procedures in Raytheon Mandatory Service Bulletin SB 53–2472, Rev. 4, Issued: June, 1993, Revised: July, 2003. Incorporate the external doubler repairs following the procedures in the maintenance manual.</p>

May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Wichita Aircraft Certification Office (ACO), FAA. For information on any already approved alternative methods of compliance, contact Steven E. Potter, Aerospace Engineer, Wichita Aircraft Certification Office (ACO), FAA, 1801 Airport Road, Wichita, Kansas 67209; telephone: (316) 946-4124; facsimile: (316) 946-4107.

Does This AD Incorporate Any Material by Reference?

(g) You must do the actions required by this AD following the instructions in Raytheon Mandatory Service Bulletin SB 53-2472, Rev. 4, Issued: June, 1993, Revised: July, 2003. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. You may get a copy from Raytheon Aircraft Company, 9709 E. Central, Wichita, Kansas 67201-0085; telephone: (800) 429-5372 or (316) 676-3140. You may review copies at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Kansas City, Missouri, on January 7, 2005.

James E. Jackson,
Acting Manager, Small Airplane Directorate, Aircraft Certification Service.
[FR Doc. 05-716 Filed 1-18-05; 8:45 am]
BILLING CODE 4910-13-P

BW 2005-02

**GARMIN INTERNATIONAL INC.
AIRWORTHINESS DIRECTIVE
APPLIANCE**

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

2005-01-19 GARMIN International Inc.: Amendment 39-13944; Docket No. FAA-2004-18743; Directorate Identifier 2004-CE-23-AD.

When Does This AD Become Effective?

(a) This AD becomes effective on February 23, 2005.

What Other ADs Are Affected by This Action?

(b) This AD supersedes AD 2004-10-15, Amendment 39-13645.

What Airplanes Are Affected by This AD?

(c) This AD affects GARMIN International Inc. GTX 33, GTX 33D, GTX 330, and GTX 330D Mode S transponders that include software versions 3.00, 3.01, 3.02, 3.04, or 3.05 that are installed on, but not limited to, the following airplanes, certificated in any category:

Manufacturer	Model
(1) Aermacchi S.p.A	S.205-18/F, S.205-18/R, S.205-20/R, S.205-22/R, S208, S.208A, F.260, F.260B, F.260C, F.260D, F.260E, F.260F, S.211A.
(2) Aeronautica Macchi S.p.A	AL 60, AL 60-B, AL 60-F5, AL 60-C5, AM-3.
(3) Aerostar Aircraft Corporation	PA-60-600 (Aerostar 600), PA-60-601 (Aerostar 601), PA-60-601P (Aerostar 601P), PA-60-602P (Aerostar 602P), PA-60-700P (Aerostar 700P), 360, 400.
(4) Alexandria Aircraft, LLC	14-19, 14-19-2, 14-19-3, 14-19-3A, 17-30, 17-31, 17-31TC, 17-30A, 17-31A, 17-31ATC
(5) Alliance Aircraft Group LLC	15A, 20, H-250, H-295 (USAFU-10D), HT-295, H391 (USAFYL-24), H391B, H-395 (USAFU-28A or U-10B), H-395A, H-700, H-800, HST-550, HST-550A (USAF AU-24A), 500.
(6) American Champion Aircraft Corp	402, 7GCA, 7GCB, 7KC, 7GCBA, 7GCAA, 7GCBC, 7KCAB, 8KCAB, 8GCBC.
(7) Sky International Inc	A-1, A-1A, A-1B, S-1S, S-1T, S-2, S-2A, S-2S, S-2C.
(8) B-N Group Ltd	BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-8, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B-27, BN-2T, BN-2T-4R, BN-2A MK.III, BN2A MK. III-2, BN2A MK. 111-3.
(9) Bellanca	14-13, 14-13-2, 14-13-3, 14-13-3W.
(10) Bombardier Inc	(Otter) DHC-3, DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300.

(11) Cessna Aircraft Company	170, 170A, 170B, 172, 172A, 172B, 172C, 172D, 172E, 172F (USAF T-41A), 172G, 172H (USAF T041A), 172I, 172K, 172L, 172M, 172N, 172P, 172Q, 172R, 172S, 172RG, P172D, R172E (USAF T-41 B) (USAF T-41 C AND D), R172F (USAF T-41 D), R175G, R172H (USAF T-41 D), R172J, R172K, 175, 175A, 175B, 175C, 177, 177A, 177B, 177RG, 180, 180A, 180B, 180C, 180D, 180E, 180F, 180G, 180H, 180J, 180K, 182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R, 182S, 182T, R182, T182, TR182, T182T, 185, 185A, 185B, 185C, 185D, 185E, A185E, A185F, 190, (LC-126A, B, C) 195, 195A, 195B, 210, 210A, 210B, 210C, 210D, 210E, 210F, T210F, 210G, T210G, 210H, T210H, 210J, T210J, 210K, T210K, 210L, T210L, 210M, T210M, 210N, P210N, T210N, 210R, P210R, T210R, 210-5 (205), 210-5A (205A), 206, P206, P206A, P206B, P206C, P206D, P206E, TP206A, TP206B, TP206C, TU206D, TU206E, TU206F, TU206G, 206H, T206H, 207, 207A, T207, T207A, 208, 208A, 208B, 310, 310A (USAF U-3A), 310B, 310C, 310D, 310E (USAF U-3B), 310F, 310G, 310H, E310H, 310I, 310J, 310J-1, E310J, 310K, 310L, 310N, 310P, T310P, 310Q, T310Q, 310R, T310R, 320, 320A, 320B, 320C, 320D, 320E, 320F, 320-1, 335, 340, 340A, 336, 337, 337A (USAF 02B), 337B, T337B, 337C, 337E, T337E, T337C, 337D, T337D, M337B (USAF 02A), 337F, T337F, T337G, 337G, 337H, P337H, T337H, T337H-SP, 401, 401A, 401B, 402, 402A, 402B, 402C, 411, 411A, 414, 414A, 421, 421A, 421B, 421C, 425, 404, 406, 441.
(12) Cirrus Design Corporation	SR20, SR22.
(13) Commander Aircraft Company	112, 112TC, 112B, 112TCA, 114, 114A, 114B, 114TC.
(14) de Havilland Inc	DHC-2 Mk. I, DHC-2 Mk. II, DHC-2 Mk. III.
(15) Dynac Aerospace Corporation	(Voltaire) 10, (Voltaire) 10A, (Aero Commander) 100, (Aero Commander) 100A, (Aero Commander) 100-180.
(16) Diamond Aircraft Industries	DA 20-A1, DA20-C1, DA 40.
(17) Empresa Brasileira de Aeronautica S.A. EMBRAER.	EMB-110P1, EMB-110P2.
(18) Extra Flugzeugbau Gmbh	EA300, EA300L, EA300S, EA300/200, EA-400.
(19) Fairchild Aircraft Corporation	SA26-T, SA26-AT, SA226-T, SA226-AT, SA226-T(B), SA227-AT, SA227-TT, SA226-TC, SA227-AC (C-26A), SA227-CC, SA227-DC (C-26B).
(20) Global Amphibians, LLC	Colonial C-1, Colonial C-2, Lake LA-4, Lake LA-4A, Lake LA-4P, Lake LA-4-200, Lake Model 250.
(21) Grob-Werke	G115, G115A, G115B, G115C, G115C2, G115D, G115D2, G115EG, G120A.
(22) Lancair Company	LC40-550FG.

(23) LanShe Aerospace, LLC	MAC-125C, MAC-145, MAC-145A, MAC-145B.
(24) Learjet Inc.	23.
(25) Lockheed Aircraft Corporation	18.
(26) Luscombe Aircraft Corporation	11A, 11E.
(27) Maule Aerospace Technology, Inc	Bee Dee M-4, M-4, M-4C, M-4S, M-4T, M-4180C, M-4-180S, M-4-180T, M-4-210, M-4-210C, M-4-210S, M-4-210T, M-4-220, M-4-220S, M-4-220T, M-5-180C, M-5-200, M-5-210C, M-5-210TC, M-5-220C, M-5-235C, M-6-180, M-6-235, M-7-235, MX-7-235, MX-7-180, MX-7-420, MXT-7-180, MT-7-235, M-8-235, MX-7-160, MXT-7-160, MX-7-180A, MXT-7-180A, MX-7-180B, M-7-235B, M-7-235A, M-7-235C, MX-7-180C, M-7-260, MT-7-260, M-7-260C, M-7-420AC, MX-7-160C, MX-7-180AC, M-7-420A, MT-7-420.
(28) Mitsubishi Heavy Industries, Ltd	MU-2B-25, MU-2B-35, MU-2B-26, MU-2B-36, MU-2B-26A, MU-2B-36A, MU-2B-40, MU-2B-60, MU-2B, MU-2B-20, MU-2B-15.
(29) Mooney Airplane Company, Inc	M20, M20A, M20B, M20C, M20D, M20E, M20F, M20G, M20J, M20K, M20L, M20M, M20R, M20S, M22.
(30) Moravan a.s	Z-242L, Z-143L.
(31) Navion Aircraft Company, Ltd	NAVION, Navion (L-17A), Navion (L17B), Navion (L-17C), Navion B, Navion D, Navion E, Navion F, Navion G, Navion H.
(32) New Piper Aircraft, Inc	PA-12, PA-12S, PA-18, PA-18S, PA-18 "105" (Special), PA-18S "105" (Special), PA-18A, PA-18 "125" (Army L-21A), PA-18S "125," PA-18AS "125," PA-18 "135" (Army L-21B), PA-18A "135," PA-18S "135," PA-18 "150," PA-18A "150," PA-18S "150," PA-18AS "150," PA-19 (Army L-18B), PA-19S, PA-20, PA-20S, PA-20 "115," PA-20S "115," PA-20 "135," PA-20S "135," PA-22, PA-22-108, PA-22-135, PA-22S-135, PA-22-150, PA-22S-150, PA-22-160, PA-22S-160, PA-23, PA-23-160, PA-23-235, PA-23-250, PA-E23-250, PA-24, PA-24-250, PA-24-260, PA-24-400, PA-28-140, PA-28-150, PA-28-151, PA-28-160, PA-28-161, PA-28-180, PA-28-235, PA-28S-160, PA-28R-180, PA-28S-180, PA-28-181, PA-28R-200, PA-28R-201, PA-28R-201T, PA-28RT-201, PA-28RT-201T, PA-28-201T, PA-28-236, PA-30, PA-39, PA-40, PA-31P, PA-31T, PA-31T1, PA-31T2, PA-31T3, PA-31P-350, PA-32-260, PA-32-300, PA-32S-300, PA-32R-300, PA-32RT-300, PA-32RT-300T, PA-32R-301 (SP), PA-32R-301 (HP), PA-32R-301T, PA-32-301, PA-32-301T, PA-34-200, PA-34-200T, PA-34-220T, PA-42, PA-42-720, PA-42-1000, PA-42-720R, PA-44-180, PA-44-180T, PA-46-310P, PA-46-350P, PA-46-500TP.
(33) Ostmecklenburgische Flugzeugbau GmgH	OMF-100-160.

(34) Piaggio Aero Industries S.p.A	P-180.
(35) Pilatus Aircraft Ltd	PILATUS PC-12, PILATUS PC-12/45, PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PA-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, PC-6/C1-H2, PC-7.
(36) Prop-Jets, Inc	200, 200A, 200B, 200C, 200D, 400.
(37) Panstwowe Zaklady Lotnicze (PZL)	PZL-104 WILGA 80, PZL-104M WILGA 2000, PZL-WARSZAWA, PZL-KOLIBER 150A, PZL-KOLIBER 160A.
(38) PZL WSK/Mielec Obrsk	PZL M20 03, PZL M26 01.
(39) Raytheon	35-33, 35-A33, 35-B33, 35-C33, 35-C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36, A36TC, B36TC, 35, A35, B35, C35, D35, E35, F35, G35, 35R, F90, 76, 200, 200C, 200CT, 200T, A200, B200, B200C, B200CT, B200T, 300, 300LW, B300, B300C, 1900, 1900C, 1900D, A100-1 (U-21J), A200 (C-12A), A200 (C-12C), A200C (UC-12B), A200CT (C-12D), A200CT (FWC-12D), A200CT (RC-12D), A200CT (C-12F), A200CT (RC-12G), A200CT (RC-12H), A200CT (RC-12K), A200CT (RC-12P), A200CT (RC-12Q), B200C (C-12F), B200C (UC-12F), B200C (UC-12M), B200C (C-12R), 1900C (C-12J), 65, A65, A65-8200, 65-80, 65-A80, 65-A80-8800, 65-B80, 65-88, 65-A90, 70, B90, C90, C90A, E90, H90, 65-A90-1, 65-A90-2, 65-A90-3, 65-A90-4, 95, B95, B95A, D95A, E95, 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B (T-42A), 95-C55, 95-C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 58A, 58P, 58PA, 58TC, 58TCA, 99, 99A, 99A (FACH), A99, A99A, B99, C99, 100, A100 (U-21F), A100A, A100C, B100, 2000, 3000, 390, 19A, B19, M19A, 23, A23, A23A, A23-19, A23-24, B23, C23, A24, A24R, B24R, C24R, 60, A60, B60, 18D, A18A, A18D, S18D, SA18A, SA18D, 3N, 3NM, 3TM, JRB-6, D18C, D18S, E18S, RC-45J (SNB-5P), E18S-9700, G18S, H18, C-45G, TC-45G, C-45H, TC-45H, TC-45J, UC-45J (SNB-5), 50 (L-23A), B50 (L-23B), C50, D50 (L-23E), D50A, D50B, D50C, D50E-5990, E50 (L-23D, RL-23D), F50, G50, H50, J50, 45 (YT-34), A45 (T-34A or B-45), D45 (T-34B).
(40) Rockwell International Corporation	BC-1A, AT-6 (SNJ-2), AT-6A (SNJ-3), AT-6B, AT-6C (SNJ-4), AT-6D (SNJ-5), AT-6F (SNF-6), SNJ-7, T-6G, NOMAD NA-260.
(41) Short Brothers & Harland Ltd	SC-7 Series 2, SC-7 Series 3.
(42) Slingsby Aviation Ltd	T67M260, T67M260-T3A.
(43) SOCATA—Group Aerospatiale	TB9, TB10, TB20, TB21, TB200, TBM 700, M.S. 760, M.S. 760 A, M.S. 760 B, Rallye 100S, Rallye 150ST, Rallye 150T, Rallye 235E, Rallye 235C, MS 880B, MS 885, MS 894A, MS 893A, MS 892A-150, MS 892E-150, MS 893E, MS 894E, GA-7.
(44) Tiger Aircraft LLC	AA-1, AA-1A, AA-1B, AA-1C, AA-5, AA-5A, AA-5B, AG-5B.

(45) Twin Commander Aircraft Corporation	500, 500-A, 500-B, 500-U, 500-S, 520, 560, 560-A, 560-E, 560F, 680, 680E, 680F, 680FL, 680FL(P), 680T, 680V, 680W, 681, 685, 690, 690A, 690B, 690C, 690D, 695, 695A, 695B, 720, 700.
(46) Univair Aircraft Corporation	108, 108-1, 108-2, 108-3, 108-5.
(47) Vulcanair S.p.A	P68, P68B, P68C, P68C-TC, P68 "Observer," P68 "Observer 2," P68TC "Observer," AP68TP300 "Spartacus," AP68TP 600 "Viator".
(48) Zenair Ltd.	CH2000.

What Is the Unsafe Condition Presented in This AD?

(d) This AD is the result of observations that the GTX 33/33D/330/330D may detect, from other airplanes, the S1 (suppression) interrogating pulse below the minimum trigger level (MTL) and, in some circumstances, not reply. The GTX 33/33D/330/330D should still reply even if it detects S1 interrogating pulses below the MTL. The actions specified in this AD are intended to prevent interrogating aircraft from possibly receiving inaccurate replies, due to suppression, from aircraft equipped with the GTX 33/33D/330/330D Mode S transponders when the pulses are below the minimum trigger level (MTL). Software Upgrade Versions 3.03 and 3.06 correct a TAS, TCAD, and TCAS I system "whisper-shout" problem that could potentially lead to the aircraft not being visible at certain ranges. TCAS II systems are not affected. The inaccurate replies could result in reduced vertical separation.

What Must I Do To Address This Problem?

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
Install GTX 33/33D/330/330D Software Upgrade for transponders with software version 3.00, 3.01, 3.02, 3.04, 3.05 to at least version 3.06. If version 3.03 is already installed, no further action is required. This version is no longer available from Garmin. This AD does not apply to software versions past 3.05.	Install the software upgrade within 180 days after February 23, 2005 (the effective date of this AD), unless already accomplished.	Follow GARMIN Mandatory Software Service Bulletin No.: 0304, Rev B, dated June 12, 2003 accomplished. (Software Upgrade 3.03) or GARMIN Mandatory Software Service Bulletin No.: 0409, dated July 19, 2004 (Software Upgrade 3.06).

May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Wichita Aircraft Certification Office (ACO), FAA. For information on any already approved alternative methods of compliance, contact Roger A. Souter, FAA, Wichita Aircraft Certification Office (ACO), 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: 316-946-4134; facsimile: 316-946-4107; email address: roger.souter@faa.gov.

Does This AD Incorporate Any Material by Reference?

(g) You must do the actions required by this AD following the instructions in GARMIN Mandatory Software Service Bulletin No.: 0304, Rev B, dated June 12, 2003 (Software Upgrade 3.03) or GARMIN Mandatory Software Service Bulletin No.: 0409, dated July 19, 2004 (Software Upgrade 3.06). The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. To get a copy of this service information, contact GARMIN International Inc. 1200 East 151st Street, Olathe, KS 66062; telephone: 913-397-8200. To review copies of this service information, go to the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html or call (202) 741-6030. To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001 or on the Internet at <http://dms.dot.gov>. The docket number is FAA-2004-18743.

Issued in Kansas City, Missouri, on January 7, 2005.

James E. Jackson,
Acting Manager, Small Airplane Directorate, Aircraft Certification Service.
[FR Doc. 05-832 Filed 1-18-05; 8:45 am]
BILLING CODE 4910-13-P

BW 2005-02

**THE LANCAIR COMPANY
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2005-02-01 The Lancair Company: Amendment 39-13945; Docket No. FAA-2005-20048; Directorate Identifier 2005-CE-01-AD.

When Does This AD Become Effective?

(a) This AD becomes effective on January 21, 2005.

Are Any Other ADs Affected by This Action?

(b) None.

What Airplanes Are Affected by This AD?

(c) This AD affects the following airplane models and serial numbers that are certificated in any category:

Model	Serial Nos.
LC40-550FG	40004 through 40079.
LC42-550FG	42002 through 42062.

What Is the Unsafe Condition Presented in This AD?

(d) This AD results from flight testing that revealed that the takeoff distance values for the affected airplanes could not be duplicated. We are issuing this AD to prevent potential impact with terrain or obstruction during takeoff due to incorrect takeoff distance values.

What Must I Do To Address This Problem?

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
<p>(1) To address the unsafe condition, do the following:</p> <p>(i) Using pen and ink, make the following notation in the takeoff distance chart (Figure 5–7) in Section 5 of the FAA-approved Airplane Flight Manual (AFM): “Caution: See Service Bulletin SB–05–001 for takeoff performance correction.”</p> <p>(ii) Insert a copy of Lancair Mandatory Service Bulletin SB–05–001, dated January 4, 2005, into Section 5 of the FAA-approved AFM.</p> <p>(2) Lancair will include this information into the next revision of the FAA-approved AFM. Incorporation of the revision that includes this information into Section 5 of the FAA-approved AFM is considered terminating action for paragraphs (e)(1)(i) and (e)(1)(ii) of this AD.</p>	<p>Before further flight after January 21, 2005 (the effective date of this AD).</p> <p>At any time as terminating action</p>	<p>The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may do the flight manual changes requirement of this AD. Make an entry in the aircraft records showing compliance with this portion of the AD following section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).</p> <p>The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may do the flight manual changes requirement of this AD. Make an entry in the aircraft records showing compliance with this portion of the AD following section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).</p>

May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Seattle Aircraft Certification Office, FAA. For information on any already approved alternative methods of compliance, contact Mr. Jeffrey Morfitt, Program Manager, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue, SW., Renton, Washington 98055-4065; telephone: (425) 917-6405; facsimile: (425) 917-6590.

May I Get Copies of the Document Referenced in This AD?

(g) You may obtain the service information referenced in this AD from The Lancair Company 22550 Nelson Road, Bend, Oregon 97701; telephone: (541) 330-4191; e-mail: product_support@lancair.com. To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC, or on the Internet at <http://dms.dot.gov>. This is docket number FAA-2005-20048.

Issued in Kansas City, Missouri, on January 10, 2005.

David R. Showers,
Acting Manager, Small Airplane Directorate, Aircraft Certification Service.
[FR Doc. 05-831 Filed 1-18-05; 8:45 am]
BILLING CODE 4910-13-P