

[Federal Register: April 21, 2009 (Volume 74, Number 75)]
[Rules and Regulations]
[Page 18116-18118]
From the Federal Register Online via GPO Access [wais.access.gpo.gov]
[DOCID:fr21ap09-4]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0126; Directorate Identifier 2009-CE-003-AD; Amendment 39-15884; AD 2009-08-11]

RIN 2120-AA64

Airworthiness Directives; PILATUS AIRCRAFT LTD. Models PC-12 and PC-12/45 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

This Airworthiness Directive (AD) is prompted by some occurrences where the Deice Pressure Regulator has vented too much hot air into the forward compartment damaging the oxygen cylinder ON/OFF cable, the Ram-Air Scoop cable and the Environmental Control System (ECS) firewall shut-off valve cable.

If incorrectly adjusted, or defective, the Deice Pressure Regulator can vent hot air into the forward compartment. This situation can cause overheating and failures of components located inside the forward compartment, which could result in potential loss of several functions essential for safe flight.

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective May 26, 2009.

On May 26, 2009, the Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building, Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the Federal Register on February 13, 2009 (74 FR 7198). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

This Airworthiness Directive (AD) is prompted by some occurrences where the Deice Pressure Regulator has vented too much hot air into the forward compartment damaging the oxygen cylinder ON/OFF cable, the Ram-Air Scoop cable and the Environmental Control System (ECS) firewall shut-off valve cable.

If incorrectly adjusted, or defective, the Deice Pressure Regulator can vent hot air into the forward compartment. This situation can cause overheating and failures of components located inside the forward compartment, which could result in potential loss of several functions essential for safe flight.

For the reason described above, this AD mandates the installation of a flange and scoop in the aircraft skin to vent the hot air from the Deice Pressure Regulator overboard.

You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the AD.

Costs of Compliance

We estimate that this AD will affect 131 products of U.S. registry. We also estimate that it will take about 2 work-hours per product to comply with the basic requirements of this AD. The average

labor rate is \$80 per work-hour. Required parts will cost about \$1,000 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here.

Based on these figures, we estimate the cost of this AD on U.S. operators to be \$151,960, or \$1,160 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD Docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39–AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:



2009-08-11 Pilatus Aircraft Ltd.: Amendment 39-15884; Docket No. FAA-2009-0126; Directorate Identifier 2009-CE-003-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective May 26, 2009.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Models PC-12 and PC-12/45 airplanes, manufacturer's serial numbers (MSN) 101 through MSN 320, certificated in any category.

Subject

- (d) Air Transport Association of America (ATA) Code 30: Ice and Rain Protection.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

This Airworthiness Directive (AD) is prompted by some occurrences where the Deice Pressure Regulator has vented too much hot air into the forward compartment damaging the oxygen cylinder ON/OFF cable, the Ram-Air Scoop cable and the Environmental Control System (ECS) firewall shut-off valve cable.

If incorrectly adjusted, or defective, the Deice Pressure Regulator can vent hot air into the forward compartment. This situation can cause overheating and failures of components located inside the forward compartment, which could result in potential loss of several functions essential for safe flight.

For the reason described above, this AD mandates the installation of a flange and scoop in the aircraft skin to vent the hot air from the Deice Pressure Regulator overboard.

Actions and Compliance

- (f) Unless already done, within the next 3 months after May 26, 2009 (the effective date of this AD), install an overboard vent for the airfoil deice system pressure regulator (Modification Kit Number 500.50.12.332) following the Accomplishment Instructions in PILATUS AIRCRAFT LTD. PC12 Service Bulletin No. 30-011, dated July 9, 2008.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64016; telephone: (816) 329-4059; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2009-0007, dated January 13, 2009; and PILATUS AIRCRAFT LTD. PC12 Service Bulletin No. 30-011, dated July 9, 2008, for related information.

Material Incorporated by Reference

(i) You must use PILATUS AIRCRAFT LTD. PC12 Service Bulletin No. 30-011, dated July 9, 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact PILATUS AIRCRAFT LTD., Customer Service Manager, CH-6371 STANS, Switzerland; telephone: +41 (0)41 619 62 08; fax: +41 (0)41 619 73 11; Internet: <http://www.pilatus-aircraft.com/>, or e-mail: SupportPC12@pilatus-aircraft.com.

(3) You may review copies of the service information incorporated by reference for this AD at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the Central Region, call (816) 329-3768.

(4) You may also review copies of the service information incorporated by reference for this AD at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Kansas City, Missouri, on April 9, 2009.

John Colomy,
Acting Manager, Small Airplane Directorate,
Aircraft Certification Service.