

EMERGENCY AIRWORTHINESS DIRECTIVE



Aircraft Certification Service
Washington, DC

U.S. Department
of Transportation
**Federal Aviation
Administration**

www.faa.gov/aircraft/safety/alerts/

DATE: March 19, 2009

AD #: 2009-07-52

This superseding Emergency Airworthiness Directive (AD) is being issued to correct the applicability of Emergency AD 2009-07-51. We issued Emergency AD 2009-07-51 on March 17, 2009. The Emergency AD requires, before further flight, inspecting each cyclic control lever assembly (lever assembly) to determine if it is correctly installed and properly staked in the lever assembly. Replacing any bearing that is incorrectly installed or improperly staked in the lever assembly is also required before further flight. AD 2009-07-51 was prompted by a Transport Canada AD report of a bearing incorrectly installed in the copilot lever assembly. Investigation revealed that, although the inspection witness marks were applied on the bearing, it had not been properly staked during manufacture of the lever assembly. This condition, if not detected, could result in failure of a bearing, failure of a lever assembly, and subsequent loss of control of the helicopter.

Emergency AD 2009-07-51 applies to all Bell Model 206A series, 206B series, 206L series, 407, and 427 helicopters with a lever assembly, P/N 206-001-401-111, 206-001-400-115, 206-001-400-111, 407-001-320-105 or 407-001-320-109, installed. Since the issuance of Emergency AD 2009-07-51, we have determined that we should have limited the applicability of Emergency AD 2009-07-51 to lever assemblies with less than 50 hours time-in-service (TIS). Therefore, we are issuing this superseding Emergency AD to retain all of the requirements of Emergency AD 2009-07-51 but to reduce the applicability to only those helicopters with lever assemblies that have less than 50 hours TIS that may be affected by the unsafe condition.

The FAA has reviewed Bell Alert Service Bulletin (ASB) No. 206-09-121, No. 206L-09-155, No. 407-09-85, and No. 427-09-23, all dated March 10, 2009. The ASBs specify that a certain bearing was installed incorrectly on the copilot lever assembly. The ASBs specify, before further flight, inspecting certain serial-numbered Bell helicopters for correct installation of the bearing.

Transport Canada, the airworthiness authority for Canada, notified the FAA that an unsafe condition may exist on certain helicopters with less than 50 flight hours or with a lever assembly installed within the last 50 flight hours. Transport Canada advises that "it is possible that an incorrectly installed bearing could be found in any helicopter with a cyclic control lever assembly recently installed." Failure of the lever assembly could lead to loss of control of the helicopter. Transport Canada classified the ASBs as mandatory and issued AD No. CF-2009-10, dated March 12, 2009, to ensure the continued airworthiness of these helicopters in Canada.

These helicopter models are manufactured in Canada and are type certificated for operation in the United States under the provisions of 14 CFR 21.29 and the applicable bilateral agreement. Pursuant to the applicable bilateral agreement, Transport Canada has kept the FAA informed of the situation described above. The FAA has examined the findings of Transport Canada, reviewed all

available information, and determined that AD action is necessary for products of these type designs that are certificated for operation in the United States.

This unsafe condition is likely to exist or develop on other helicopters of the same type designs. Therefore, this AD requires, for those helicopters with lever assemblies that have less than 50 hours TIS, before further flight, inspecting each lever assembly, P/N 206-001-401-111, 206-001-400-115, 206-001-400-111, 407-001-320-105 or 407-001-320-109, to determine if the bearing, P/N 206-301-051-101, is correctly installed and properly staked in the lever assembly. Replacing any bearing that is incorrectly installed or improperly staked in the lever assembly is also required before further flight.

This rule is issued under 49 U.S.C. Section 44701 pursuant to the authority delegated to me by the Administrator, and is effective immediately upon receipt of this emergency AD.

2009-07-52 BELL HELICOPTER TEXTRON CANADA LIMITED: Directorate Identifier 2009-SW-07-AD. Supersedes AD 2009-07-51, Directorate Identifier 2009-SW-06-AD.

Applicability: Bell Model 206A series, 206B series, and 206L series helicopters with a cyclic control lever assembly (lever assembly), part number (P/N) 206-001-401-111, 206-001-400-115, or 206-001-400-111, with less than 50 hours time-in-service (TIS) and Model 407 and 427 helicopters with a lever assembly, P/N 407-001-320-105 or 407-001-320-109, with less than 50 hours TIS, certificated in any category.

Compliance: Before further flight, unless accomplished previously.

To prevent failure of a bearing, failure of the lever assembly, and subsequent loss of control of the helicopter, do the following:

(a) Inspect the lever assembly and determine if the bearing, P/N 206-301-051-101, is correctly installed and properly staked in the lever assembly.

(b) Replace any bearing that is incorrectly installed or improperly staked in the lever assembly.

Note 1: Bell Alert Service Bulletin (ASB) No. 206-09-121 for the Model 206A and 206B series, No. 206L-09-155 for the Model 206L series, No. 407-09-85 for the Model 407, and No. 427-09-23, for the Model 427, pertain to the subject of this AD. All of the ASBs are dated March 10, 2009.

(c) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Manager, Safety Management Group, FAA, ATTN: Sharon Miles, Aviation Safety Engineer, Rotorcraft Directorate, Fort Worth, Texas 76193-0111, telephone (817) 222-5122, fax (817) 222-5961, for information about previously approved alternative methods of compliance.

(d) Special flight permits will not be issued.

(e) Emergency AD 2009-07-52, issued March 19, 2009, becomes effective upon receipt.

Note 2: The subject of this AD is addressed in Transport Canada AD CF-2009-10, dated March 12, 2009.

FOR FURTHER INFORMATION CONTACT: Sharon Miles, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Regulations and Guidance Group, Fort Worth, Texas 76193-0111, telephone (817) 222-5122, fax (817) 222-5961.

Issued in Fort Worth, Texas, on March 19, 2009.

Larry M. Kelly,
Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.