



**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES
LARGE AIRCRAFT**

BIWEEKLY 2009-15

This electronic copy may be printed and used in lieu of the FAA biweekly paper copy.

U.S. Department of Transportation
Federal Aviation Administration
Regulatory Support Division
Delegation and Airworthiness Programs Branch, AIR-140
P. O. Box 26460
Oklahoma City, OK 73125-0460
FAX 405-954-2209

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency

Biweekly 2009-01

2008-25-05	S 93-01-15	McDonnell Douglas	See AD
2008-26-04	S 2007-23-13	Cessna Aircraft Company	560
2008-26-06		Rolls-Royce Corporation	Engine: AE 3007A
2008-26-07		McDonnell Douglas	See AD
2008-26-08		Saab AB, Saab Aerosystems	340A (SAAB/SF340A) and SAAB 340B
2008-26-09		Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 & 440)
2009-01-01		CFM International, S. A	Engine: See AD

Biweekly 2009-02

No Large Aircraft ADs were issued during Biweekly 2009-02.

Biweekly 2009-03

2009-01-02		Boeing	737-600, -700, -700C, -800 and -900
2009-01-03		Bombardier, Inc.	DHC-8-400, DHC-8-401, and DHC-8-402
2009-01-04		Airbus	A318, A319, A320, and A321
2009-01-07		Bombardier, Inc	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D24 (Regional Jet Series 900)
2009-01-10		Bombardier, Inc	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900)
2009-02-03		Lycoming engines, See AD	See AD

Biweekly 2009-04

No Large Aircraft ADs were issued during Biweekly 2009-04.

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency

Biweekly 2009-05

2008-18-02	S 2004-14-07	BAE Systems	Jetstream 4101
2008-24-51		Boeing	737-600, -700, -700C, -800, and -900
2009-01-05		Embraer	EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP
2009-01-06	S 2005-15-16	328 Support Services GmbH	328-300
2009-01-08	S 98-16-11	Airbus	A300, A310, A300-600
2009-01-09	S 2000-26-14	Airbus	A310
2009-02-01		Construcciones Aeronauticas, S.A.	C-212-DF
2009-02-04		Airbus	A300-600
2009-02-05		Boeing	777-200, -200LR, -300, and -300E
2009-02-07	S 98-17-12	BAE Systems	Jetstream 4101
2009-02-09		BAE Systems	BAe 146-100A, -200A, and -300A, Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2009-02-10	S 2008-04-22	Fokker Services	F.28 Mark 0070 and 0100
2009-02-11		Bombardier Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D24 (Regional Jet Series 900)
2009-03-01		Learjet	55, 55B, and 55C
2009-03-02	S 2004-05-20	McDonnell Douglas	DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, DC-10-40F, MD-10-10F, MD-10-30F, MD-11, and MD-11F
2009-03-03		McDonnell Douglas	DC-9-14, DC-9-15, DC-9-15F, DC-9-21, DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC-9-32F, DC-9-33F, DC-9-34, DC-9-34F, DC-9-32F (C-9A, C-9B), DC-9-41, and DC-9-51
2009-04-02		Pratt & Whitney	Engine: PW4090 and PW4090-3
2009-04-03		Rolls-Royce Corporation	Engine: AE 3007A1E and AE 1107C
2009-04-06	S 2004-16-09	Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP
2009-04-07		Airbus	A330-200 and -300; and A340-200, -300, -500, and -600, A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, -313, -541, and -642
2009-04-10	S 2002-07-12	General Electric Company	CF6-80A, CF6-80C2, and CF6-80E1
2009-04-11		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2009-04-12	S 2001-26-19	Boeing	767-200, -300, and -400ER
2009-04-13		Rolls-Royce Deutschland Ltd & Co KG	Engine: BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30
2009-04-15	S 93-08-04	Boeing	737-100, -200, -200C, -300, -400, and -500
2009-04-16	S 2008-10-15	Boeing	747-100, 747-100B, 747-200B, 747-200C, 747-200F, 747-300, 747SR, and 747SP
2009-04-17		General Electric Company	Engine: CF6-45A, CF6-45A2, CF6-50A, CF6-50C, CF6-50CA, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50E, CF6-50E1, CF6-50E2, and CF6-50E2B
2009-05-02		General Electric Company	Engine: See AD
2009-05-03		Boeing	727, 727C, 727-100, 727-100C, 727-200, and 727-200F
2009-05-04		Bombardier Inc	CL-215-6B11 (CL-215T variant), CL-215-6B11 (CL-415 variant)

Biweekly 2009-06

2009-02-06		Boeing	737-300, -400, and -500
2009-05-10		Airbus	A300, A340-200 and A340-300, A330
2009-05-11	S 2008-19-04	Boeing	777-200 and -300
2009-06-12	S 2008-01-04	Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency

Biweekly 2009-07

2009-05-08		Trimble or Freeflight Systems	Appliance: Global positioning system
2009-06-02		Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747SR, and 747SP
2009-06-03		Viking Air Limited	DHC-7-1, DHC-7-100, DHC-7-101, DHC-7-102, and DHC-7-103
2009-06-04		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2009-06-05		Bombardier, Inc.	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A & CL-601-3R), CL-600-2B16 (CL-604)
2009-06-06	S 2006-10-11 and 2005-15-10	Airbus	A310 and A300-600
2009-06-08		Boeing	767-200, -300, -300F, and -400ER
2009-06-09		328 Support Services GMBH	328-100
2009-06-10		Boeing	727-100 and 727-200
2009-06-11		Embraer	ERJ 190-100 STD, -100 LR, -100 IGW, -100ECJ, -200 STD, -200 LR, and -200 IGW
2009-06-13		Airbus	A321-131
2009-06-14		Fokker Services B.V	F.27 Mark 050
2009-06-15		Fokker Services B.V	F.27 Mark 050
2009-06-16		Embraer	ERJ 170-100 LR, -100 SE, -100 STD, -100 SU, -200 LR, -200 STD, and -200 SU airplanes; and Model ERJ 190-100 IGW, -100 LR, -100 STD, -100 ECJ, -200 IGW, -200 LR, and -200 STD
2009-06-17		Bombardier	CL-600-2B19 (Regional Jet Series 100 & 440)
2009-06-18		Bombardier, Inc	CL-600-2C10 (Regional Jet Series 700, 701, & 702)
2009-06-19		Boeing	767-200 and 767-300
2009-06-20		Boeing	757-200, 757-200PF, and 757-300
2009-06-21		Bombardier	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315, DHC-8-400, -401 and -402
2009-06-22		Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-111, -211, -212, -214, -231, -232, -233; and A321-111, -112, -131, -211, -212, -213, -231, and -232
2009-07-01		Rolls-Royce Deutschland Ltd & Co KG	Engine: BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30
2009-07-02	S 96-03-07	Hawker Beechcraft	400, 400A, MU-300-10, MU-300
2009-07-03		General Electric Company	Engine: CF6-80C2 and CF6-80E1

Biweekly 2009-08

2009-04-18		Pratt & Whitney	Engine: JT9D-7, -7A, -7AH, -7H, -7F, and -7J
2009-07-04		McDonnell Douglas	Rotorcraft: MD-90-30
2009-07-05		ATR-GIE Avions de Transport Régional	ATR72-101, -102, -201, -202, -211, -212, and -212A
2009-07-06		McDonnell Douglas	717-200
2009-07-07		General Electric Company	Engine: CF6-80A, CF6-80A1, CF6-80A2, and CF6-80A3
2009-07-10	S 2004-22-05	Boeing	737-300, -400, -500
2009-07-11		General Electric Company	Engine: CF34-1A, -3A, -3A1, -3A2, -3B, and -3B1
2009-07-12	S 2007-07-12	Honeywell, Inc	Navigation computer
2009-08-01		McDonnell Douglas	See AD
2009-08-04		Hawker Beechcraft Corp.	BH.125 series 600A airplanes and Model HS.125 series 700A
2009-08-51	E		

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency

Biweekly 2009-09

2009-08-06		General Electric Company	Engine: CF6-80A
2009-08-07		Honeywell International Inc	Engine: ALF502L-2 and ALF502L-2C
2009-09-01		Airbus	A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-111, A320-211, A320-212, A320-214, A320-231, A320-232, A320-233, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231, and A321-232
2009-09-02		Bombardier, Inc	DHC-8-400, DHC-8-401, and DHC-8-402

Biweekly 2009-10

2009-06-22	C	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-111, -211, -212, -214, -231, -232, -233; and A321-111, -112, -131, -211, -212, -213, -231, and -232
2009-09-05	S 2006-03-10	Airbus	A318-111 and 112; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-111, -211, -212, -214, -231, -232, and -233; and A321-111, -112, -131, -211, -212, -213, -231, and -232
2009-09-06		Boeing	737-100, -200, -200C, -300, -400, and -500
2009-09-07		Boeing	737-100, -200, -200C, -300, -400, and -500
2009-09-08		Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP
2009-10-01	S 2007-17-21	Pratt & Whitney	Engine: JT9D-7R4G2, -7R4E1, -7R4E4, and -7R4H1
2009-10-02	S 2005-19-15	BAE Systems	Jetstream 4101
2009-10-03		328 Support Services	328-100 and -300

Biweekly 2009-11

2009-04-06	S 2004-16-09	Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP
2009-08-51		Rolls-Royce Corporation	Engine: RRC AE 3007A
2009-10-01	S 2007-17-21	Pratt & Whitney	Engine: JT9D-7R4G2, -7R4E1, -7R4E4, and -7R4H1
2009-10-05		Bombardier, Inc	CL-600-2B19 (Regional Jet series 100 and 440)
2009-10-06		Boeing	747-400 and 747-400D
2009-10-07		Airbus	380-841, -842 and 861
2009-10-08		Pratt & Whitney	Engine: PW2037, PW2037(M), and PW2040
2009-10-10		Bombardier Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702), Model CL-600-2D15 (Regional Jet Series 705), Model CL-600-2D24 (Regional Jet Series 900)
2009-10-11		Airbus	A330-300, A340-200, and A340-300
2009-10-12	S 2005-16-06	Boeing	747-100, -100B, -100B SUD, -200B, -200C, -200F, -300, -400F, -400, -400D, 747SP, and 747SR
2009-10-13		Saab AB, Saab Aerosystems	340A and 340B
2009-11-02		CFM International	Engine: CFM56-2, CFM56-3, CFM56-5A, CFM56-5B, CFM56-5C, and CFM56-7B
2009-11-03		Lockheed	382, 382B, 382E, 382F, and 382G

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency

Biweekly 2009-12

2009-11-07		BAE Systems	HS 748 series 2A and series 2B
2009-11-08		Airbus	A330-202, -223, -243, -301, -322 and -342
2009-11-09		Airbus	A310-203, A310-204, A310-221, A310-222, A310-304, A310-322, A310-324, and A310-325 airplanes; and Airbus Model A300 B4-601, A300 B4-603, A300 B4-605R, A300 B4-620, A300 B4-622, A300 B4-622R, A300 C4-605R Variant F, A300 F4-605R and A300 F4-622R
2009-11-11		McDonnell Douglas	MD-90-30
2009-11-13		Learjet	45

Biweekly 2009-13

2009-11-04		Rolls-Royce Corporation	Engine: AE 2100D2, AE 2100D2A, AE 2100D3, and AE 2100J
2009-12-02	S 2007-03-09	Airbus	Model A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F airplanes; and Model A310
2009-12-03		Boeing	757-200, -200CB, and -300
2009-12-04		Construcciones Aeronauticas, S.A.	C-212-CB, C-212-CC, C-212-CD, C-212-CE, C-212-CF, and C-212-DE
2009-12-05		Boeing	737-300, -400, and -500
2009-12-06		Boeing	737-300, -400, and -500, 737-600, -700, -700C, -800, and -900
2009-12-08		Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP
2009-12-09		ATR-GIE Avions De Transport Régional	ATR42-200, ATR42-300, and ATR42-320, ATR42-500, ATR72-101, ATR72-201, ATR72-102, ATR72-202, ATR72-211, ATR72-212, and ATR72-212A
2009-12-10	S 2006-12-09	BAE Systems	BAe 146-100A, -200A, and -300A series airplanes; and Model Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2009-12-11		Airbus	A340-541 and -642
2009-12-13		Bombardier, Inc	DHC-8-400, DHC-8-401, and DHC-8-402
2009-13-07		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343

Biweekly 2009-14

2009-04-18	COR	Pratt & Whitney	Engine: JT9D-7, -7A, -7AH, -7H, -7F, and -7J
2009-13-02	S 98-06-07	Fokker Services B.V	F.28 Mark 0100
2009-13-03		Boeing	747-400 and -400F
2009-13-08		McDonnell Douglas	MD-90-30
2009-13-09		Microturbo SA	Appliance: Auxiliary power units (APU)
2009-13-10		British Aerospace Regional Aircraft	HP.137 Jetstream Mk.1, Jetstream Series 200 and 3101, and Jetstream Model 3201
2009-14-02	S 2002-26-15	Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP
2009-14-08		General Electric Company	Engine: CF6-80C2B5F

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency

Biweekly 2009-15

2009-14-03		Bombardier, Inc.	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A, CL-601-3R), CL-600-2B16 (CL-604)
2009-14-04		Boeing	737-100, -200, -200C, -300, -400, and -500
2009-14-05		Pratt & Whitney	Engine: PW2037, PW2037(M), and PW2040
2009-14-06	S 2007-17-12	Boeing	777
2009-14-07		Dassault Aviation	Mystere-Falcon 20-C5, 20-D5, 20-E5, and 20-F5
2009-14-09		Dassault Aviation	Falcon 2000EX
2009-14-12		Pratt & Whitney Canada Corp	Engine: PW305A and PW305B
2009-15-02		Airbus	A318, A319, A320, and A321
2009-15-03		Bombardier, Inc	BD-700-1A10 and BD-700-1A11
2009-15-04		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343



2009-14-03 Bombardier, Inc. (Formerly Canadair): Amendment 39-15953. Docket No. FAA-2009-0044; Directorate Identifier 2008-NM-132-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective August 12, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to the airplanes listed in Table 1 of this AD, certificated in any category.

Table 1—Applicability

Bombardier model—	Serial Nos.—
CL-600-1A11 (CL-600) airplanes	1004 through 1085 inclusive.
CL-600-2A12 (CL-601) airplanes	3001 through 3066 inclusive.
CL-600-2B16 (CL-601-3A, CL-601-3R) airplanes	5001 through 5194 inclusive.
CL-600-2B16 (CL-604) airplanes	5301 thorough 5665 inclusive.

Note 1: This AD requires revisions to certain operator maintenance documents to include new inspections. Compliance with these inspections is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by these inspections, the operator may not be able to accomplish the inspections described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (g)(1) of this AD. The request should include a description of changes to the required inspections that will ensure the continued operational safety of the airplane.

Subject

(d) Air Transport Association (ATA) of America Code 27: Flight Controls.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

There have been several Stick Pusher Capstan Shaft failures causing the dormant loss or severe degradation of the stick pusher function. This directive is issued to revise the first flight of the day check [in the Airplane Flight Manual] of the stall protection system to detect a degradation of the stick pusher function. It also introduces a new periodic maintenance task [in the Airworthiness Limitations Section of the Instructions for Continuing Airworthiness] to check the structural integrity of the stick pusher capstan shaft.

Dormant loss or severe degradation of the stick pusher function could result in reduced controllability of the airplane.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) Within 30 days after the effective date of this AD: Revise the Normal Procedures section of the applicable airplane flight manual (AFM) by inserting a copy of the applicable TR listed in Table 2 of this AD. Thereafter, operate the airplanes per the procedures specified in the applicable TR, except as provided by paragraph (g)(1) of this AD. If the operator has an AFM that is not listed in Table 2 of this AD, within 30 days after the effective date of this AD, revise the AFM using a method approved by the FAA or Transport Canada Civil Aviation (TCCA) (or its delegated agent).

Table 2—Temporary Revisions to the AFM

For Bombardier model—	Use Canadair temporary provision—	Dated—	To the normal procedures section of—
CL-600-1A11 (CL-600) airplanes	600/23	January 30, 2007	Canadair Challenger CL-600-1A11 AFM.
CL-600-1A11 (CL-600) airplanes	600-1/18	January 30, 2007	Canadair Challenger CL-600-1A11 AFM (Winglets).
CL-600-2A12 (CL-601) airplanes	601/15	January 30, 2007	Canadair Challenger CL-600-2A12 AFM, PSP 601-1B-1.
CL-600-2A12 (CL-601) airplanes	601/16	January 30, 2007	Canadair Challenger CL-600-2A12 AFM, PSP 601-1A-1.
CL-600-2A12 (CL-601) airplanes	601/20	January 30, 2007	Canadair Challenger CL-600-2A12 AFM, PSP 601-1B.
CL-600-2A12 (CL-601) airplanes	601/28	January 30, 2007	Canadair Challenger CL-600-2A12 AFM.
CL-600-2B16 (CL-601-3A and CL-601-3R) airplanes.	601/27	January 30, 2007	Canadair Challenger CL-600-2B16 AFM, PSP 601A-1.
CL-600-2B16 (CL-601-3A and CL-601-3R) airplanes.	601/28	January 30, 2007	Canadair Challenger CL-600-2B16 AFM, PSP 601A-1-1.
CL-600-2B16 (CL-604) airplanes	604/22	January 30, 2007	Canadair Challenger CL-604 AFM, PSP 604-1.

(2) When information identical to that in a TR specified in paragraph (f)(1) of this AD has been included in the general revisions of the applicable AFM, the general revisions may be inserted into the AFM, and the TR may be removed from that AFM.

(3) Within 30 days after the effective date of this AD: Revise the Airworthiness Limitations section of the Instructions for Continued Airworthiness by incorporating the applicable task in the TR listed in Table 3 of this AD. For all tasks identified in the TRs, the initial compliance time starts from the later of the times specified in paragraph (f)(3)(i) and (f)(3)(ii) of this AD. Thereafter, except as provided by paragraph (g)(1) of this AD, no alternative maintenance task intervals may be used.

(i) Within the compliance time specified in the "Check Interval" or "Task Interval," as applicable, after the effective date of this AD.

(ii) Within the compliance time specified in the "Check Interval" or "Task Interval," as applicable, after the date of issuance of the original Canadian airworthiness certificate or the date of issuance of the original Canadian export certificate of airworthiness.

Table 3—Temporary Revisions to the Airworthiness Limitations Section

For Bombardier model—	Use Canadair temporary revision—	Dated—	To the airworthiness limitations section of—
CL-600-1A11 (CL-600) airplanes	5-138	June 26, 2007	Canadair Challenger Time Limits/Maintenance Checks (TLMC), PSP 605, Chapter 5, Section 5-10-30.
CL-600-2A12 (CL-601) airplanes	5-226	June 26, 2007	Canadair Challenger TLMC, PSP 601-5, Chapter 5, Section 5-10-30.
CL-600-2B16 (CL-601-3A and CL-601-3R) airplanes.	5-239	June 26, 2007	Canadair Challenger TLMC, PSP 601A-5, Chapter 5, Section 5-10-30.
CL-600-2B16 (CL-604) airplanes	5-2-32	May 31, 2007	Canadair Challenger CL-604 TLMC, Chapter 5, Section 5-10-40.

(4) When the information in applicable TR listed in Table 3 of this AD has been included in the general revisions of the applicable chapter of the Airworthiness Limitations section, the TR may be removed from the Airworthiness Limitations section of the Instruction for Continued Airworthiness.

FAA AD Differences

Note 2: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Bruce Valentine, Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7328; fax (516) 794-5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

(4) Special Flight Permits: Special flight permits, as described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), are not allowed.

Related Information

(h) Refer to MCAI Canadian Airworthiness Directive CF-2008-12, dated February 8, 2008, and the service information listed in Table 4 of this AD, for related information.

Table 4—All Service Information

Canadair TR—	Dated—	To the—
5-138	June 26, 2007	Canadair Challenger TLMC, PSP 605, Chapter 5, Section 5-10-30.
5-226	June 26, 2007	Canadair Challenger TLMC, PSP 601-5, Chapter 5, Section 5-10-30.
5-239	June 26, 2007	Canadair Challenger TLMC, PSP 601A-5, Chapter 5, Section 5-10-30.
5-2-32	May 31, 2007	Canadair Challenger CL-604 TLMC, Chapter 5, Section 5-10-40.
600/23 .	January 30, 2007	Canadair Challenger CL-600-1A11 AFM.
600-1/18	January 30, 2007	Canadair Challenger CL-600-1A11 AFM (Winglets).
601/15 .	January 30, 2007	Canadair Challenger CL-600-2A12 AFM, PSP 601-1B-1.
601/16 .	January 30, 2007	Canadair Challenger CL-600-2A12 AFM, PSP 601-1A-1.
601/20 .	January 30, 2007	Canadair Challenger CL-600-2A12 AFM, PSP 601-1B.
601/27 .	January 30, 2007	Canadair Challenger CL-600-2B16 AFM, PSP 601A-1.
601/28 .	January 30, 2007	Canadair Challenger CL-600-2A12 AFM.

601/28 .	January 30, 2007	Canadair Challenger CL-600-2B16 AFM, PSP 601A-1-1.
604/22 .	January 30, 2007	Canadair Challenger CL-604 AFM, PSP 604-1.

Material Incorporated by Reference

(i) You must use the service information contained in Table 5 of this AD to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; e-mail thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Table 5—Material Incorporated by Reference

Canadair temporary revision—	Dated—	To the—
5-138	June 26, 2007	Canadair Challenger Time Limits/Maintenance Checks, PSP 605, Chapter 5, Section 5-10-30.
5-226	June 26, 2007	Canadair Challenger Time Limits/Maintenance Checks, PSP 601-5, Chapter 5, Section 5-10-30.
5-239	June 26, 2007	Canadair Challenger Time Limits/Maintenance Checks, PSP 601A-5, Chapter 5, Section 5-10-30.
5-2-32	May 31, 2007	Canadair Challenger CL-604 Time Limits/Maintenance Checks, Chapter 5, Section 5-10-40.
600/23	January 30, 2007	Canadair Challenger CL-600-1A11 Airplane Flight Manual.
600-1/18	January 30, 2007	Canadair Challenger CL-600-1A11 Airplane Flight Manual (Winglets).
601/15	January 30, 2007	Canadair Challenger CL-600-2A12 Airplane Flight Manual, PSP 601-1B-1.
601/16	January 30, 2007	Canadair Challenger CL-600-2A12 Airplane Flight Manual, PSP 601-1A-1.
601/20	January 30, 2007	Canadair Challenger CL-600-2A12 Airplane Flight Manual, PSP 601-1B.

601/27	January 30, 2007	Canadair Challenger CL-600-2B16 AFM Airplane Flight Manual PSP 601A-1.
601/28	January 30, 2007	Canadair Challenger CL-600-2A12 Airplane Flight Manual.
601/28	January 30, 2007	Canadair Challenger CL-600-2B16 Airplane Flight Manual, PSP 601A-1-1.
604/22	January 30, 2007	Canadair Challenger CL-604 Airplane Flight Manual, PSP 604-1.

Issued in Renton, WA, on June 11, 2009.
Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2009-14-04 Boeing: Amendment 39-15954. Docket No. FAA-2008-1116; Directorate Identifier 2007-NM-231-AD.

Effective Date

(a) This airworthiness directive (AD) is effective August 12, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, certificated in any category; as identified in Boeing Service Bulletin 737-28-1241, Revision 1, dated August 31, 2007.

Unsafe Condition

(d) This AD results from reports of uncommanded engine shutdowns and burned and damaged wire bundles associated with the outboard landing lights and engine fuel shutoff valves. This AD also results from reports of damaged and missing grommets and broken and damaged fairleads in the electrical junction boxes of the main wheel well. We are issuing this AD to prevent a hot short between the outboard landing light and fuel shutoff valve circuits, which could result in an uncommanded engine shutdown. We are also issuing this AD to prevent corrosion of the electrical connectors of the wing rear spars, which could result in short circuits and consequent incorrect functioning of airplane systems needed for safe flight and landing.

Compliance

(e) Comply with this AD within the compliance times specified, unless already done.

Deactivating or Modifying the Outboard Landing Lights

(f) For Model 737-300, -400, and -500 series airplanes identified in Boeing Alert Service Bulletin 737-33A1140, dated May 22, 2006: Within 180 days after the effective date of this AD, accomplish the actions specified in either paragraph (f)(1) or (f)(2) of this AD. Accomplishing the applicable actions required by paragraph (g) of this AD terminates the requirements of this paragraph.

(1) Deactivate the outboard landing lights by accomplishing all of the actions specified in Part 1 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-33A1140, dated May 22, 2006.

Note 1: The Master Minimum Equipment List (MMEL) prohibits dispatching an airplane for night operations with deactivated outboard landing lights in the event that either of the inboard landing lights fail. Operators should note that, if the outboard landing lights are deactivated in accordance with Part 1 of Boeing Alert Service Bulletin 737-33A1140, dated May 22, 2006, there is no MMEL relief allowing for this configuration for night operations should any inboard landing light fail.

(2) Modify the wiring to the outboard landing lights by accomplishing all of the actions specified in Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-33A1140, dated May 22, 2006.

Inspection and Replacements

(g) For all airplanes: Within 60 months after the effective date of this AD, do the applicable actions specified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD, by accomplishing all of the applicable actions specified in the Accomplishment Instructions of Boeing Service Bulletin 737-28-1241, Revision 1, dated August 31, 2007. For Model 737-300, -400, and -500 series airplanes identified in Boeing Alert Service Bulletin 737-33A1140, dated May 22, 2006, accomplishing the applicable actions required by this paragraph terminates the requirements of paragraph (f) of this AD.

(1) Replace the wire bundles for the landing lights and fuel shutoff valves with new, redesigned wire bundles, and do the related investigative, other specified, and corrective actions, as applicable. The related investigative, other specified, and corrective actions must be done before further flight after the replacement.

(2) Do a detailed inspection for any broken, damaged, or missing fairleads, any damaged or missing grommets, and any chafed or damaged wires or wire bundles in the four electrical junction boxes of the main wheel well, and do the applicable corrective actions. The corrective actions must be done before further flight after the inspection.

(3) Replace the electrical connectors and backshell clamps with new, improved electrical connectors and backshell clamps, as applicable.

Credit for Actions Done According to Previous Issue of Service Bulletin

(h) For airplanes identified as Groups 1 and 2 in Boeing Service Bulletin 737-28-1241, Revision 1, dated August 31, 2007: Actions done before the effective date of this AD in accordance with Boeing Service Bulletin 737-28-1241, dated April 7, 2006, are acceptable for compliance with the requirements of paragraph (g) of this AD.

(i) For all airplanes: Actions done before the effective date of this AD in accordance with Part 2 of the Accomplishment Instructions of Boeing Service Bulletin 737-28-1241, dated April 7, 2006, are acceptable for compliance with the requirements of paragraph (g)(2) of this AD.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, ATTN: Stephen Oshiro, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle ACO, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6480; fax (425) 917-6590; has

the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(k) You must use Boeing Service Bulletin 737-28-1241, Revision 1, dated August 31, 2007; and Boeing Alert Service Bulletin 737-33A1140, dated May 22, 2006; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, WA, on June 11, 2009.

Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2009-14-05 Pratt & Whitney: Amendment 39-15955. Docket No. FAA-2009-0417; Directorate Identifier 2009-NE-13-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective July 23, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Pratt & Whitney models PW2037, PW2037(M), and PW2040 turbofan engines, with the following high-pressure compressor (HPC) drum rotor disk assemblies installed:

Table 1—Affected HPC Drum Rotor Disk Assemblies

Drum Rotor Disk Assembly Part Number 1B3702; 1B3702- 001; 1B3610; 1B3610-001; or 1B7377 – Serial Number	12th Stage Disk Billet and Heat Number
T62805	T/LALY-4013
R80293	T/LALY-4012
R80289	T/LALY-4010
R80322	T/LALY-4009
R80330	T/LALY-4008
R78394	T/LALY-4007
R80281	T/LALY-4006
R80304	T/LALY-4005
R80343	T/LALY-4004
R80299	T/LALY-4003
R80313	T/LALY-4002
R80333	M1/LALY-4035
R80324	M1/LALY-4034

R80310	M1/LALY-4033
R80326	M1/LALY-4030
R80305	M1/LALY-4026
R80315	M1/LALY-4025
R80309	M1/LALY-4024
R80341	M1/LALY-4023
R80329	M1/LALY-4022
R80312	M1/LALY-4020
R80321	M1/LALY-4019
R80319	M2/LALY-4040
R80358	M2/LALY-4039
R80302	M2/LALY-4038
R80336	M2/LALY-4037

These engines are installed on, but not limited to, Boeing 757-200 and 757-300 airplanes.

Unsafe Condition

(d) This AD results from six HPC 12th stage disks found cracked during HPC module disassembly at overhaul. We are issuing this AD to prevent uncontained failure of the HPC 12th stage disk and airplane damage.

Compliance

(e) You are responsible for having the actions required by this AD performed at the following compliance times:

(1) For PW2040 turbofan engines, within 200 cycles-in-service (CIS) after the effective date of this AD, unless the actions have already been done.

(2) For PW2037 and PW2037(M) turbofan engines, within 400 CIS after the effective date of this AD, unless the actions have already been done.

Non-Destructive Inspection

(f) Have a special eddy-current inspection performed on the 12th stage disks installed in the HPC drum rotor disk assemblies listed in Table 1 of this AD, for cracks. Use paragraph 1 of the Accomplishment Instructions of Pratt & Whitney Alert Service Bulletin No. PW2000 A72-736, dated January 5, 2009, to do the special eddy current inspection.

Alternative Methods of Compliance

(g) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Related Information

(h) Contact Mark Riley, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: mark.riley@faa.gov; telephone (781) 238-7758, fax (781) 238-7199.

Material Incorporated by Reference

(i) You must use Pratt & Whitney Alert Service Bulletin No. PW2000 A72-736, dated January 5, 2009, to have the special eddy current inspections performed by this AD. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Pratt & Whitney, 400 Main Street, East Hartford, CT 06108, for a copy of this service information. You may review copies at the FAA, New England Region, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on June 23, 2009.
Peter A. White,
Assistant Manager, Engine and Propeller Directorate,
Aircraft Certification Service.



2009-14-06 Boeing: Amendment 39-15956. Docket No. FAA-2008-0933; Directorate Identifier 2007-NM-261-AD.

Effective Date

- (a) This AD becomes effective August 12, 2009.

Affected ADs

- (b) This AD supersedes AD 2007-17-12.

Applicability

- (c) This AD applies to all Boeing Model 777 airplanes, certificated in any category.

Unsafe Condition

(d) This AD results from a report of extensive corrosion of a ballscrew in the drive mechanism of the horizontal stabilizer on a Boeing Model 757 airplane, which is similar in design to the ballscrew on Model 777 airplanes. We are issuing this AD to prevent an undetected failure of the primary load path for the ballscrew in the drive mechanism of the horizontal stabilizer and subsequent wear and failure of the secondary load path, which could lead to loss of control of the horizontal stabilizer and consequent loss of control of the airplane.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of Requirements of AD 2007-17-12 With Revised Compliance Times and Updated Service Information

Maintenance Records Check

(f) For airplanes that have received an original airworthiness certificate or original export certificate of airworthiness prior to the effective date of this AD: Within 180 days or 3,500 flight hours after the effective date of this AD, whichever occurs first, perform a maintenance records check or inspect to determine the status of the horizontal stabilizer trim actuator (HSTA) as specified in paragraph (f)(1), (f)(2), (f)(3), or (f)(4) of this AD, as applicable:

- (1) The original HSTA delivered with the airplane has not been removed and is still installed on the airplane;

(2) The original HSTA has been replaced with an HSTA in a known serviceable condition;

(3) The original HSTA has been replaced with an HSTA that is not in a known serviceable condition, and which has not received a detailed inspection and freeplay measurement as described in paragraphs (g) and (h) of this AD since that replacement; or

(4) The original HSTA has been replaced with an HSTA that is not in a known serviceable condition, and which has received a detailed inspection and freeplay measurement as described in paragraphs (g) and (h) of this AD since that replacement.

Note 1: The phrase "known serviceable condition" is defined in section 3.A., Note 6, of Boeing Service Bulletin 777-27A0059, Revision 2, dated January 15, 2009.

Detailed Inspection

(g) Within the compliance times specified in paragraphs (g)(1), (g)(2), (g)(3), and (g)(4) of this AD, as applicable: Perform a detailed inspection for discrepancies of the horizontal stabilizer trim actuator ballnut and ballscrew, in accordance with Part 1 of the Accomplishment Instructions of Boeing Service Bulletin 777-27A0059, Revision 2, dated January 15, 2009. Repeat the detailed inspection thereafter at intervals not to exceed 3,500 flight hours or 12 months, whichever occurs first. If any discrepancy is found during any inspection required by this AD, before further flight, replace the actuator with an actuator in a known serviceable condition, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 777-27A0059, Revision 2, dated January 15, 2009.

(1) For airplanes identified in paragraph (f)(1) of this AD: Before the accumulation of 15,000 total flight hours, or within 18 months after the effective date of this AD, whichever occurs later.

(2) For airplanes identified in paragraph (f)(2) or (f)(4) of this AD: Before the accumulation of 15,000 flight hours since the replacement of the HSTA, or within 18 months after the effective date of this AD, whichever occurs later.

(3) For airplanes identified in paragraph (f)(3) of this AD: Before the accumulation of 3,500 flight hours since the replacement of the HSTA, or within 12 months after the effective date of this AD, whichever occurs later.

(4) For airplanes that have received an original airworthiness certificate or original export certificate of airworthiness on or after the effective date of this AD: Before the accumulation of 15,000 total flight hours, or within 18 months after the issuance of the original airworthiness certificate or original export certificate of airworthiness, whichever occurs later.

Freeplay Measurement (Inspection)

(h) Within the compliance times specified in paragraphs (h)(1), (h)(2), (h)(3), and (h)(4) of this AD, as applicable: Perform a freeplay measurement of the ballnut and ballscrew in accordance with Part 2 of the Accomplishment Instructions of Boeing Service Bulletin 777-27A0059, Revision 2, dated January 15, 2009. Repeat the freeplay measurement thereafter at intervals not to exceed 18,000 flight hours or 60 months, whichever occurs first. If the freeplay is found to exceed the limits specified in the service bulletin during any measurement required by this AD, before further flight, replace the actuator with an actuator in a known serviceable condition, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 777-27A0059, Revision 2, dated January 15, 2009.

(1) For airplanes identified in paragraph (f)(1) of this AD: Before the accumulation of 15,000 total flight hours, or within 18 months after the effective date of this AD, whichever occurs later.

(2) For airplanes identified in paragraph (f)(2) or (f)(4) of this AD: Before the accumulation of 15,000 flight hours since the replacement of the HSTA, or within 18 months after the effective date of this AD, whichever occurs later.

(3) For airplanes identified in paragraph (f)(3) of this AD: Before the accumulation of 3,500 flight hours since the replacement of the HSTA, or within 12 months after the effective date of this AD, whichever occurs later.

(4) For airplanes that have received an original airworthiness certificate or original export certificate of airworthiness on or after the effective date of this AD: Before the accumulation of 15,000 total flight hours, or within 18 months after the issuance of the original airworthiness certificate or original export certificate of airworthiness, whichever occurs later.

Lubrication

(i) Within the compliance times specified in paragraphs (i)(1), (i)(2), (i)(3), and (i)(4) of this AD, as applicable: Lubricate the ballnut and ballscrew in accordance with Part 3 of the Accomplishment Instructions of Boeing Service Bulletin 777-27A0059, Revision 2, dated January 15, 2009. Repeat the lubrication thereafter at intervals not to exceed 2,000 flight hours or 12 months, whichever occurs first.

(1) For airplanes identified in paragraph (f)(1) of this AD: Before the accumulation of 15,000 total flight hours, or within 18 months after the effective date of this AD, whichever occurs later.

(2) For airplanes identified in paragraph (f)(2) or (f)(4) of this AD: Before the accumulation of 15,000 flight hours since the replacement of the HSTA, or within 18 months after the effective date of this AD, whichever occurs later.

(3) For airplanes identified in paragraph (f)(3) of this AD: Before the accumulation of 3,500 flight hours since the replacement of the HSTA, or within 12 months after the effective date of this AD, whichever occurs later.

(4) For airplanes that have received an original airworthiness certificate or original export certificate of airworthiness on or after the effective date of this AD: Before the accumulation of 15,000 total flight hours, or within 18 months after the issuance of the original airworthiness certificate or original export certificate of airworthiness, whichever occurs later.

Credit for Actions Accomplished According to Earlier Issues of the Service Bulletin

(j) Actions performed prior to the effective date of this AD, in accordance with Boeing Alert Service Bulletin 777-27A0059, dated September 18, 2003; or Boeing Alert Service Bulletin 777-27A0059, Revision 1, dated August 18, 2005; are considered acceptable for compliance with the corresponding actions specified in paragraphs (g), (h), and (i) of this AD.

Credit for Hard-Time Replacement of HSTA

(k) Any HSTA overhauled within the compliance times specified in paragraphs (g), (h), and (i) of this AD or before the effective date of this AD—as part of a "hard-time" replacement program that includes removal of the HSTA from the airplane and overhaul of the stabilizer ballscrew in accordance with original equipment manufacturer component maintenance manual instructions—

meets the intent of one detailed inspection, one freeplay inspection, and one lubrication of the HSTA. Therefore, any such HSTA is considered acceptable for compliance with the initial accomplishment of the actions specified in paragraphs (g), (h), and (i) of this AD, and repetitions of those actions may be determined from the performance date of that overhaul.

Parts Installation

(l) As of the effective date of this AD, no person may install, on any airplane, a horizontal stabilizer trim actuator that is not in a "known serviceable condition" as defined in Note 6, section 3.A., of Boeing Alert Service Bulletin 777-27A0059, Revision 2, dated January 15, 2009; unless a detailed inspection, freeplay measurement, and lubrication of that actuator are performed in accordance with paragraphs (g), (h), and (i) of this AD, as applicable.

Alternative Methods of Compliance (AMOCs)

(m)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, ATTN: Kelly McGuckin, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle ACO, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6490; fax (425) 917-6590; has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(n) You must use Boeing Service Bulletin 777-27A0059, Revision 2, dated January 15, 2009, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1, fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, WA, on June 24, 2009.
Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2009-14-07 Dassault Aviation (Formerly Avions Marcel Dassault-Breguet Aviation (AMD/BA)): Amendment 39-15957. Docket No. FAA-2009-0263; Directorate Identifier 2008-NM-137-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective August 12, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Mystere-Falcon 20-C5, 20-D5, 20-E5, and 20-F5 airplanes, certificated in any category, without Dassault Service Bulletin F20-766 implemented.

Subject

(d) Air Transport Association (ATA) of America Code 30: Ice and rain protection.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

This Airworthiness Directive (AD) is issued following the discovery of hot air leaks when operating the wing anti-icing system. The seals Part Number (P/N) MS29513-325, near the de-icing valves (12H1) and (12H2) in frame 33 area, do not have the proper temperature rating.

The consequences, in the area of the hot air leak, are risks of ignition of potential hydraulic leaks.

The purpose of this AD is to verify that seals with correct temperature rating have been installed on Mystere-Falcon 20-()5 airplanes.

The corrective action includes replacing the left and right seals near de-icing valves (12H1) and (12H2) in frame area 33.

Actions and Compliance

(f) Unless already done, within 7 months after the effective date of this AD, perform an inspection for a red line marking on each of the Wiggins couplings that are located near the de-icing valves (12H1) and (12H2), in accordance with Dassault Mandatory Service Bulletin F20-766, Revision 1, dated June 24, 2008. If a red line is not found, prior to further flight, replace the seals to the left and right Wiggins couplings, in accordance with Dassault Mandatory Service Bulletin F20-766, Revision 1, dated June 24, 2008. Inspections and replacements accomplished before the effective date of this AD in accordance with Dassault Service Bulletin F20-766, dated October 31, 2005, are considered acceptable for compliance with the corresponding actions specified in this AD.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2008-0123, dated July 2, 2008; and Dassault Mandatory Service Bulletin F20-766, Revision 1, dated June 24, 2008; for related information.

Material Incorporated by Reference

(i) You must use Dassault Mandatory Service Bulletin F20-766, Revision 1, dated June 24, 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606; telephone 201-440-6700; Internet <http://www.dassaultfalcon.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on June 24, 2009.

Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2009-14-09 Dassault Aviation: Amendment 39-15959. Docket No. FAA-2009-0380; Directorate Identifier 2008-NM-153-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective August 12, 2009.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Dassault Model Falcon 2000EX airplanes, certificated in any category, serial numbers 102 through 124 inclusive.

Subject

- (d) Air Transport Association (ATA) of America Code 53: Fuselage.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

An internal review of design data has shown that the web of the left hand side (LH) stringer 13 near frame 8 might have been improperly trimmed on a few aircraft.

If not corrected, possible crack initiations could occur in the upper stringer web, and therefore could impair the structural strength of the adjacent door stop. This latent failure could ultimately lead to the loss of redundancy of the door stops, thereby affecting the structural integrity of the fuselage.

Computational analysis has revealed a substantial reduced fatigue life for the stringer abutting onto the improperly trimmed web and has determined the need for an inspection and repair action no later than the first "C" check.

To address this unsafe condition, the present Airworthiness Directive (AD) mandates an inspection and a conditional rework or replacement of the web of the LH stringer 13 between frames 7 and 8.

Required actions include measuring the trimmed length of the web, inspecting for any sharp and unprotected edges of the web, and doing corrective actions if necessary. Corrective actions include reworking the web and applying protection to the web, or replacing the web, if improperly trimmed.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) At the later of the times in paragraphs (f)(1)(i) and (f)(1)(ii) of this AD: Perform a detailed visual inspection to detect any sharp and unprotected edges of the web of the LH stringer 13 between frames 7 and 8, and measure the trimmed length of the web, in accordance with the Accomplishment Instructions of Dassault Mandatory Service Bulletin F2000EX-178, dated July 1, 2008.

(i) Before the accumulation of 3,750 total flight cycles, or within 74 months since the date of issuance of the original French airworthiness certificate or the date of issuance of the original French export certificate of airworthiness, whichever occurs first.

(ii) Within 6 months after the effective date of this AD.

(2) If, during the inspection and measurement required by paragraph (f)(1) of this AD, any sharp or unprotected edge is found, or if the trimmed length is 1.57 inches (40 mm) or greater, before further flight, do all applicable corrective actions, in accordance with the Accomplishment Instructions of Dassault Mandatory Service Bulletin F2000EX-178, dated July 1, 2008.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2008-0143, dated July 31, 2008; and Dassault Mandatory Service Bulletin F2000EX-178, dated July 1, 2008; for related information.

Material Incorporated by Reference

(i) You must use Dassault Mandatory Service Bulletin F2000EX-178, dated July 1, 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606; telephone 201-440-6700; Internet <http://www.dassaultfalcon.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, WA, on June 25, 2009.

Stephen P. Boyd,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-15855 Filed 7-7-09; 8:45 am]



2009-14-12 Pratt & Whitney Canada Corp: Amendment 39-15962. Docket No. FAA-2009-0046; Directorate Identifier 2008-NE-05-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective August 13, 2009.

Affected ADs

- (b) None.

(c) This AD applies to Pratt & Whitney Canada Corp. (P&WC) Models PW305A and PW305B turbofan engines with high pressure compressor (HPC) drum rotor assemblies, post P&WC Service Bulletin (SB) PW300-72-24287 but without P&WC SB PW300-72-24376, installed. These engines are installed on, but not limited to, Bombardier Learjet M60 and Hawker Beechcraft 1000 series airplanes.

Reason

- (d) P&WC has determined that the Post-Service Bulletin (SB) PW300-72-24287 High Pressure Compressor (HPC) drum rotor assemblies P/N 30B2478 and 30B2542 on PW305A and 305B engines with single stage coated labyrinth seals, are susceptible to developing significant cracks in the region of the labyrinth seal.

We are issuing this AD to detect cracks in the HPC drum rotor assembly, which could lead to an uncontained failure of the drum rotor assembly and damage to the airplane.

Actions and Compliance

- (e) Unless already done, do the following actions.

- (1) Within 500 flight hours after effective date of this directive, borescope-inspect the interiors of affected HPC rotor assemblies for cracks. If a crack is found, remove the engine before next flight for HPC drum rotor replacement. Pratt & Whitney Maintenance Manual, Chapter 72-00-00, contains guidance on borescope inspection.

Credit for Previous Inspections

- (2) Inspection of affected HPC drum rotor assembly per P&WC SB PW300-72-24462 and or SB PW305 MM 05-20-00 inspection requirements prior to the effective date of this directive satisfies the requirements of paragraph (e)(1) of this AD.

(3) Repeat borescope inspection per paragraph (e)(1) of this AD, at intervals not exceeding 1,350 flight cycles. If a crack is found, remove the engine before next flight for HPC rotor drum replacement.

Optional Terminating Action

(4) Replacement of the affected HPC rotor assembly P/N 30B2478 or 30B2542 with Post-SB PW300-72-24376 assembly P/N 31B6325-01 or later superseding P/N, will constitute terminating action for the inspection requirements of the above paragraphs (e)(1) and (e)(2) of the corrective action requirements of this AD.

Other FAA AD Provisions

(f) Alternative Methods of Compliance (AMOCs): The Manager, Engine Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

Related Information

(g) Refer to Canadian Airworthiness Directive CF-2007-25R1, dated February 13, 2008, and P&WC SB PW300-72-24462, dated December 13, 1999, for related information. Contact Pratt & Whitney Canada Corp., 1000 Marie-Victorin, Longueuil, Quebec, Canada J4G 1A1, telephone: (800) 268-8000, for a copy of this service information.

(h) Contact Ian Dargin, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: ian.dargin@faa.gov; telephone (781) 238-7178; fax (781) 238-7199, for more information about this AD.

Material Incorporated by Reference

(i) None.

Issued in Burlington, Massachusetts, on June 30, 2009.
Francis A. Favara,
Manager, Engine and Propeller Directorate,
Aircraft Certification Service.



2009-15-02 Airbus: Amendment 39-15965. Docket No. FAA-2008-0832; Directorate Identifier 2008-NM-067-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective August 19, 2009.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to all Airbus Model A318, A319, A320, and A321 airplanes, certificated in any category; except airplanes on which Airbus Modification 27189 was done in production or Airbus Service Bulletin A320-29-1100 was done in service, and on which Airbus Modification 28413 was not done in production.

Subject

- (d) Air Transport Association (ATA) of America Code 29: Hydraulic power.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

In-service experience has shown that a fracture of the gerotor pump of the A320 RAT [ram air turbine] may occur. This may lead to the non-operation of the RAT in case of an in-flight deployment.

The Non-Deployment or Non-Pressurization of the RAT, associated with a double engine failure or a total loss of normal electrical power generation constitutes an unsafe condition.

This AD mandates the replacement of the affected gerotor pump assembly, which will provide the required improved reliability of the RAT.

The implementation of this modification was originally managed by an AIRBUS monitoring campaign. However, the rate of installation of the modification by operators has not met the predicted target. As such and to ensure continued compliance with the

certification requirements it is considered necessary to require compliance by use of [an] AD.

* * * * *

Actions and Compliance

(f) Unless already done, do the following actions.

(1) Within 15 months after the effective date of this AD: Identify the part number (P/N) and serial number (S/N) of the RAT in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-29-1122, dated July 27, 2006.

(2) For airplanes on which a RAT with P/N 680203037 is installed that has a S/N between 0101 and 0354 inclusive: Within 15 months after the effective date of this AD, replace the gerotor pump assembly and re-identify the RAT in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-29-1122, dated July 27, 2006.

(3) For airplanes on which a RAT with P/N 680203037 is installed that does not have a S/N between 0101 and 0354 inclusive, or a RAT with a P/N other than P/N 680203037 is installed: No further action is required by this AD.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: Although Appendix 01 of Airbus Service Bulletin A320-29-1122, dated July 27, 2006, tells you to submit information to the manufacturer, this AD specifies that such submittal is not required.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tim Dulin, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2141; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

Related Information

(h) Refer to MCAI EASA Airworthiness Directive 2008-0034, dated February 20, 2008 [corrected February 21, 2008]; and Airbus Service Bulletin A320-29-1122, excluding Appendix 01, dated July 27, 2006, for related information.

Material Incorporated by Reference

(i) You must use Airbus Service Bulletin A320-29-1122, excluding Appendix 01, dated July 27, 2006; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus, Airworthiness Office – EAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail: account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on July 2, 2009.

Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2009-15-03 Bombardier, Inc.: Amendment 39-15966. Docket No. FAA-2009-0138; Directorate Identifier 2008-NM-216-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective August 19, 2009.

Affected ADs

- (b) This AD supersedes AD 2008-24-12, Amendment 39-15753.

Applicability

(c) This AD applies to Bombardier Model BD-700-1A10 and BD-700-1A11 airplanes, certificated in any category, serial numbers (S/Ns) 9002 through 9222 inclusive; equipped with elevator power control units (PCUs) having part number (P/N) GT411-3800-5 or GT411-3800-7.

Subject

- (d) Air Transport Association (ATA) of America Code 27: Flight controls.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

During scheduled maintenance inspection, a bolt which connects the PCU (power control unit) to the elevator surface was found fractured in the assembly. Further inspection of the assembly revealed that the bearing on the PCU rod end had seized, which resulted in damage to the attachment fitting bushing and fracture of the bolt. Inspection of other in-service airplanes revealed two more seized PCU attachment joints. However, except seizure, no fractured bolt was found on these airplanes. Failure of the bolts in both PCUs on one side could result in disconnection of the elevator control surface which would lead to flutter and loss of the aircraft.

This Airworthiness Directive (AD) is issued to mandate the inspection and lubrication of all part number (P/N) GT411-3800-5 and GT411-3800-7 PCU attachment joints.

The required actions include inspections for damage and seizure (including signs of seizure) of the PCU attachment joints, an inspection for damage (including wear damage, fretting, corrosion, galling, scoring, fretting wear, and parts that do not meet inspection requirements) of the PCU attachment joint components, and applicable corrective actions.

Restatement of Requirements of AD 2008-24-12:

(f) Unless already done: For airplanes on which elevator PCUs with P/N GT411-3800-5 or P/N GT411-3800-7, S/N 0615 and lower, are installed, excluding P/N GT411-3800-7 PCUs having a serial number listed in Table 1 of this AD, and excluding P/N GT411-3800-7 PCUs on which less than 1,000 flight hours have accumulated on the PCUs as of December 15, 2008 (the effective date of AD 2008-24-12), do the actions specified in paragraphs (f)(1), (f)(2), and (f)(3) of this AD.

Note 1: Units listed in Table 1 of this AD have been lubricated by the vendor and the inspections required by paragraphs (f)(1), (f)(2), (f)(3), and (f)(4) of this AD are not required for those units.

Table 1 – Serial Numbers

0030	0097	0156	0188	0218	0369	0438
0031	0101	0161	0190	0222	0406	0453
0033	0105	0163	0191	0223	0407	0491
0041	0108	0164	0197	0240	0408	0495
0046	0109	0165	0198	0262	0413	0504
0060	0110	0171	0199	0265	0420	0506
0062	0111	0173	0202	0281	0427	0513
0066	0119	0174	0205	0296	0429	0533
0081	0130	0178	0206	0301	0430	0536
0083	0138	0179	0208	0310	0431	0586
0087	0141	0181	0210	0323	0433	
0092	0145	0183	0214	0365	0435	

(1) Within 10 flight cycles or 50 flight hours after December 15, 2008, whichever occurs first: Inspect for damage and wear and lubricate the PCU attachment joints in accordance with Bombardier Alert Service Bulletin A700-1A11-27-024, Revision 02, dated November 10, 2008; or Bombardier Alert Service Bulletin A700-27-066, Revision 02, dated November 10, 2008; as applicable.

(2) Within 90 days or 200 flight hours after performing the actions required by paragraph (f)(1) of this AD, whichever occurs first: Repeat the inspection and lubrication of the PCU attachment joints in accordance with Bombardier Alert Service Bulletin A700-1A11-27-024, Revision 02, dated November 10, 2008; or Bombardier Alert Service Bulletin A700-27-066, Revision 02, dated November 10, 2008; as applicable.

(3) Within 45 days or 100 flight hours after performing the actions required by paragraph (f)(2) of this AD, whichever occurs first: Repeat the inspection and lubrication of the PCU attachment joints in accordance with Bombardier Alert Service Bulletin A700-1A11-27-024, Revision 02, dated November 10, 2008; or Bombardier Alert Service Bulletin A700-27-066, Revision 02, dated November 10, 2008; as applicable. Repeat the inspection thereafter at intervals not to exceed 45 days or 100 flight hours, whichever occurs first, until paragraph (f)(4) of this AD is accomplished.

(4) Completion of a disassembly with an inspection for damage, applicable corrective actions, and lubrication of the PCU attachment joint components in accordance with Bombardier Service Bulletin 700-1A11-27-025, Revision 01, dated November 24, 2008; or Bombardier Service Bulletin

700-27-067, Revision 01, dated November 24, 2008; as applicable; constitutes terminating action for the inspections required by paragraphs (f)(1), (f)(2), and (f)(3) of this AD.

(5) Unless already done, if any damage or seizure is found during any inspection required by paragraphs (f)(1), (f)(2), (f)(3), and (f)(4) of this AD, before further flight, replace the affected part in accordance with Bombardier Service Bulletin 700-1A11-27-025, Revision 01, dated November 24, 2008; or Bombardier Service Bulletin 700-27-067, Revision 01, dated November 24, 2008; as applicable.

(6) Actions done before December 15, 2008, in accordance with Bombardier Alert Service Bulletin A700-1A11-27-024 or Bombardier Alert Service Bulletin A700-27-066, both dated October 2, 2008; or Revision 01, both dated October 3, 2008; as applicable; are acceptable for compliance with the corresponding requirements of this AD.

(7) Unless already done, submit a report to Bombardier of all findings found during any inspection required by paragraphs (f)(1), (f)(2), (f)(3), and (f)(4) of this AD, in accordance with the applicable service bulletin listed in Table 2 of this AD.

(i) If the inspection was done on or after December 15, 2008: Submit the report within 14 days after the inspection.

(ii) If the inspection was done before December 15, 2008: Submit the report within 14 days after December 15, 2008.

Table 2 – Service Bulletins for Reports

Service Bulletin	Revision Level	Date
Bombardier Alert Service Bulletin A700-1A11-27-024	02	November 10, 2008
Bombardier Alert Service Bulletin A700-27-066	02	November 10, 2008
Bombardier Service Bulletin 700-1A11-27-025	01	November 24, 2008
Bombardier Service Bulletin 700-27-067	01	November 24, 2008

New Requirements of This AD: Actions and Compliance

(g) Unless already done, do the actions specified in paragraph (g)(1) or (g)(2) of this AD, as applicable, at the time specified.

(1) For airplanes identified in paragraph (f) of this AD: Within 45 days or 100 flight hours after the effective date of this AD, whichever occurs first, complete a disassembly with an inspection for damage, applicable corrective actions, and lubrication of the PCU attachment joint components in accordance with Bombardier Service Bulletin 700-1A11-27-025, Revision 01, dated November 24, 2008; or Bombardier Service Bulletin 700-27-067, Revision 01, dated November 24, 2008; as applicable.

(2) For airplanes not identified in paragraph (f) of this AD on which elevator PCUs with P/N GT411-3800-7 are installed: Within 180 days or 400 flight hours after the effective date of this AD, whichever occurs first, complete a disassembly with an inspection for damage, applicable corrective actions, and lubrication of the PCU attachment joint components in accordance with Bombardier Service Bulletin 700-1A11-27-025, Revision 01, dated November 24, 2008; or Bombardier Service Bulletin 700-27-067, Revision 01, dated November 24, 2008; as applicable.

(3) Actions done before the effective date of this AD in accordance with Bombardier Service Bulletin 700-1A11-27-025, dated October 9, 2008; or Bombardier Service Bulletin 700-27-067, dated

October 9, 2008; as applicable; are acceptable for compliance with the corresponding requirements of this AD.

FAA AD Differences

Note 2: This AD differs from the MCAI and/or service information as follows: Paragraph A.3. of the MCAI requires a one-time inspection; however, since we have changed the compliance time for the terminating action in paragraph A.4. of the MCAI (refer to paragraph (g)(1) of this AD), paragraph (f)(3) of this AD requires repeating the inspections until the terminating action is performed.

Other FAA AD Provisions

(h) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to Attn: Pong K. Lee, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7324; fax (516) 794-5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

(4) Special Flight Permits: As described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), special flight permits are not allowed.

Related Information

(i) Refer to MCAI Canadian Emergency Airworthiness Directive CF-2008-31, dated October 9, 2008, and the service information specified in Table 2 of this AD, for related information.

Material Incorporated by Reference

(j) You must use the service information contained in Table 3 of this AD to do the actions required by this AD, as applicable, unless the AD specifies otherwise.

Table 3 – Material incorporated by reference

Document	Revision Level	Date
Bombardier Alert Service Bulletin A700-1A11-27-024	02	November 10, 2008
Bombardier Alert Service Bulletin A700-27-066	02	November 10, 2008
Bombardier Service Bulletin 700-1A11-27-025	01	November 24, 2008
Bombardier Service Bulletin 700-27-067	01	November 24, 2008

(1) The Director of the Federal Register approved the incorporation by reference of the service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; e-mail thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on July 2, 2009.
 Ali Bahrami,
 Manager, Transport Airplane Directorate,
 Aircraft Certification Service.



2009-15-04 Airbus: Amendment 39-15967. Docket No. FAA-2009-0137; Directorate Identifier 2008-NM-201-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective August 19, 2009.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to Model A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343 series airplanes; and Model A340-211, -212, -213, -311, -312, and -313 series airplanes; all manufacturer serial numbers, certificated in any category, except those on which Airbus Modification 48825 has been embodied in production.

Subject

- (d) Air Transport Association (ATA) of America Code 92.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

Several reports have been received from A330 and A340 operators concerning chafing of the electrical harness behind the lavatory, located at L (level) 53, resulting in a number of short-circuits. This harness contains cables for lighting, plugs, loudspeakers and oxygen controls and indications.

This condition, if not corrected, could lead to the short circuit of wires dedicated to oxygen, which, in case of emergency, could result in a large number of passenger oxygen masks (up to 32% of all seats) not being supplied with oxygen, possibly causing personal injuries.

For the reasons described above, AD 2008-0154 was issued to require a wiring modification of the affected harnesses on right and left sides of the passenger compartment between frames (FR) 39.1 and 39.2 and between FR 53.3 and 53.4, on pre-modification 48825 aircraft (i.e. non-enhanced cabin).

Since that AD was issued, it has been found that due to discrepancies in the referenced Airbus Service Bulletin (SB) at original issue, the modification should have been mandated at Revision 1 of the SB, rather than indicating that application of the SB at original issue is acceptable.

For that reason, this EASA (European Aviation Safety Agency) AD retains the requirements of EASA AD 2008-0154, which is superseded, amends the requirement to specify that the SB must be accomplished at Revision 1 and that for aircraft on which the SB at original issue has already been accomplished, additional work must be done.

Th[e] Revision 1 [of EASA AD 2008-0161] is issued to extend the compliance time, which originally was 20 months, to 24 months * * * after the effective date of this AD. *
* *

The modification includes rerouting the affected electrical harnesses and replacing certain wiring mounts and brackets in the passenger compartment. For all airplanes, additional work is required. The additional work includes interchanging certain fixed brackets and modifying certain wiring routing.

Actions and Compliance

(f) Unless already done, within 24 months after the effective date of this AD, do the following actions, as applicable.

(1) Except as required by paragraph (f)(2) of this AD, modify the affected passenger compartment electrical harnesses, including the "ADDITIONAL WORK," in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A330-92-3066, Revision 02, dated March 19, 2009; or Airbus Mandatory Service Bulletin A340-92-4071, Revision 03, dated March 19, 2009; as applicable.

(2) For airplanes that have already been modified prior to the effective date of this AD in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-92-3066, dated November 27, 2007; or Airbus Service Bulletin A340-92-4071, dated November 27, 2007; as applicable: Accomplish the "ADDITIONAL WORK" in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A330-92-3066, Revision 02, dated March 19, 2009; or Airbus Mandatory Service Bulletin A340-92-4071, Revision 03, dated March 19, 2009; as applicable.

(3) Actions accomplished according to the Airbus service information identified in Table 1 of this AD, including the "ADDITIONAL WORK," as applicable, are acceptable for complying with the requirements of paragraphs (f)(1) and (f)(2) of this AD.

Table 1 – Acceptable service information

Airbus Mandatory Service Bulletin	Revision	Date
A330-92-3066	01	August 1, 2008
A340-92-4071	01	August 1, 2008
A340-92-4071	02	November 28, 2008

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1138; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI EASA Airworthiness Directive 2008-0161R1, dated March 23, 2009, and the service information listed in Table 2 of this AD, for related information.

Table 2 – Related service information

Airbus Mandatory Service Bulletin	Revision	Date
A330-92-3066	01	August 1, 2008
A330-92-3066	02	March 19, 2009
A340-92-4071	01	August 1, 2008
A340-92-4071	02	November 28, 2008
A340-92-4071	03	March 19, 2009

Material Incorporated by Reference

(i) You must use the applicable service information contained in Table 3 of this AD to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus SA–Airworthiness Office–EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80, e-mail airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Table 3 – Material incorporated by reference

Airbus Mandatory Service Bulletin	Revision	Date
A330-92-3066	01	August 1, 2008
A330-92-3066	02	March 19, 2009
A340-92-4071	01	August 1, 2008
A340-92-4071	02	November 28, 2008
A340-92-4071	03	March 19, 2009

Issued in Renton, Washington, on July 2, 2009.

Ali Bahrami,
 Manager, Transport Airplane Directorate,
 Aircraft Certification Service.