

**FEDERAL AVIATION ADMINISTRATION  
AIRWORTHINESS DIRECTIVES**

**LARGE AIRCRAFT  
BIWEEKLY 2015-12**

*6/1/2015 - 6/14/2015*



Federal Aviation Administration  
Continued Operational Safety Policy Section, AIR-141  
P.O. Box 25082  
Oklahoma City, OK 73125-0460

## CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

### MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents  
Government Printing Office  
Mail List Branch SSOM  
Washington, DC 20402

Telephone: (202) 512-1806  
Facsimile: (202) 512-2250

## LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
<b>Biweekly 2015-01</b>			
2014-26-03		Saab AB, Saab Aerosystems	340B
<b>Biweekly 2015-02</b>			
2014-25-51		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-25-52		Airbus	A330-223F, -243F, A330-201, -202, -203, -223, -243, A330-301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, A340-311, -312, -313, A340-541 and A340-642
2014-26-06		ATR–GIE Avions de Transport Régional	ATR42-500 and ATR72-212A
2014-26-07		Dassault Aviation	FAN JET FALCON and FAN JET FALCON SERIES C, D, E, F, and G
2014-26-09	R 2014-03-05	Bombardier, Inc.	BD-700-1A10
2014-26-10		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-26-53		Airbus	A319-115, A319-133, A320-214, A320-232, and A320-233
2015-01-01	R 2011-09-11	The Boeing Company	777-200 and -300 series
<b>Biweekly 2015-03</b>			
2014-23-15	R 2011-14-06	Airbus	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-111, -211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-26-08	R 2011-13-09	Airbus	A330-201, -202, -203, -223, -223F -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343
2015-02-02		Bombardier, Inc	CL-215-6B11 (CL-215T Variant), CL-215-6B11 (CL-415 Variant)
2015-02-03		Airbus	A300 B4-601, B4-603, B4-605R, F4-605R, and C4-605R Variant F
2015-02-04		Dassault Aviation	MYSTERE-FALCON 50
2015-02-05		The Boeing Company	717-200, DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, and DC-10-40F, MD-10-10F and MD-10-30F, DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87), MD-88, MD-90-30
2015-02-06		Bombardier, Inc	CL-600-2B16 (CL-604 Variant)
2015-02-08		Rolls-Royce Corporation (RRC)	AE 2100D2, 2100D2A, 2100D3, 2100P and AE 3007A1, A1/1, A1/3, A1E, A1P, A2, A3, C, C1, and C2
2015-02-11		Airbus	A330-301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, and -313
2015-02-12		Bombardier, Inc	DHC-8-400, -401 and -402
2015-02-13		Empresa Brasileira de Aeronautica S.A. (Embraer)	EMB -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP
2015-02-16	R 2009-06-06	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325, A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F
2015-02-17		Airbus	A330-201, -202, -203, -223, -223F, -243, and -243F, A330-301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes
2015-02-18		Airbus	A330-201, -202, -203, -301, -302, and -303
2015-02-19	R 95-24-04	Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R, A300 C4-605R Variant F

## LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2015-02-20	S 2013-15-10	Rolls-Royce plc (RR)	RB211-Trent 553-61, 553A2-61, 556-61, 556A2-61, 556B-61, 556B2-61, 560-61, 560A2-61, 768-60, 772-60, 772B-60, 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, 895-17, 970-84, 970B-84, 972-84, 972B-84, 977-84, 977B-84, and 980-84
2015-02-23		Bombardier, Inc	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A and CL-601-3R Variants)
2015-02-26	R 2013-24-13	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series, 737-600, -700, -700C, -800, and -900 series
<b>Biweekly 2015-04</b>			
2015-02-24	R 2007-03-18 R2008-17-02 R2012-08-03 R2012-15-14	Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, A300 B4-2C, B4-103, B4-203, A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2015-02-25		Bombardier, Inc.	DHC-8-400, -401, and -402
2015-03-01		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2015-03-02		Airbus	A319-115, A319-133, A320-214, A320-232, and A320-233
2015-03-04		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2015-03-05	R 2012-09-07	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2015-03-06	R 2007-22-10	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213 -311, -312, -313, -541, and -642
<b>Biweekly 2015-05</b>			
2015-02-14	R 2009-20-05	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, -232.
2015-03-03		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, B4-203, A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R. A300 C4-605R Variant F.
2015-04-02		CFM International S.A.	CFM56-7B series
2015-04-03		Rolls-Royce plc	RB211 Trent 768-60, 772-60, and 772B-60
2015-04-06		Rolls-Royce plc	RB211 Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17.
<b>Biweekly 2015-06</b>			
2015-04-07		Boeing	767-200 and -300 series airplanes
2015-05-01		Boeing	757-200, -200PF, -200CB, and -300 series airplanes; and 767-200, -300, -300F, and -400ER series airplanes
2015-05-03		Bombardier	CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2015-05-07	R 2015-02-06	Bombardier	CL-600-2B16 (CL-604 Variant) airplanes
2015-05-08		Lockheed Martin	382, 382B, 382E, 382F, and 382G airplanes
2015-06-01	S 2014-06-03	British Aerospace	Jetstream Series 3101 and Jetstream 3201 airplanes
<b>Biweekly 2015-07</b>			
2015-04-08	R 2014-06-08	Bombardier, Inc	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes
2015-05-02	R 2014-23-15	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-111, -211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2015-06-04	R 2011-13-07	Dassault	FALCON 7X
2015-06-05		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, A300 B4-601, B4-603, B4-620, and B4-622,

## LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2015-06-06 2015-06-07 2015-07-01		BAE Systems The Boeing Company Rolls-Royce plc	A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes. 4101 airplanes 737-100, -200, -200C, -300, -400, and -500 series airplanes RB211-524B-02, RB211-524B-B-02, RB211-524B2-19, RB211-524B2-B-19, RB211-524B3-02, RB211-524C2-19, and RB211-524C2-B-19 turbofan engines
<b>Biweekly 2015-08</b>			
2015-06-08	R 2011-09-03	Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	382, 382B, 382E, 382F, and 382G
2015-07-05		BAE Systems (Operations) Limited	146-100A, -200A, and -300A; and Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2015-07-06		Airbus	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325
2015-07-07 2015-08-02	R 2015-02-04	The Boeing Company Dassault Aviation	777-200, -200LR, -300ER, and 777F series MYSTERE-FALCON 50
<b>Biweekly 2015-09</b>			
2015-06-10		ATR-GIE Avions de Transport Régional	ATR72-212A
2015-07-02		Bombardier, Inc	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A and CL-601-3R Variants), CL-600-2B16 (CL-604 Variants)
2015-08-01 2015-08-03 2015-08-05	R 2013-26-05	The Boeing Company Bombardier, Inc. Dassault Aviation	757-200, -200PF, -200CB, and -300 series DHC-8-400, -401, and -402 FAN JET FALCON, FAN JET FALCON SERIES C, D, E, F, and G; MYSTERE-FALCON 200; MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5
2015-08-06	R 2007-14-05	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325; A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F
2015-08-08	R 2014-26-53 and 2015-03-02	Airbus	A319-115, A319-132, A319-133, A320-214, A320-232, and A320-233
2015-08-09 2015-09-02 2015-09-03		The Boeing Company Bombardier, Inc. Airbus	737-600 and -700 series CL-600-2E25 (Regional Jet Series 1000)
2015-09-07		The Boeing Company	A318-111 and -112, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232 787
<b>Biweekly 2015-10</b>			
2015-08-07 2015-09-05 2015-09-08		Zodiac Aerotechnics The Boeing Company Airbus	See AD 747-400 and 747-400F A300 B4-601, B4-603, and B4-605R; and A300 F4-605R; and A300 C4-605R Variant F; and A310-204 and -304
2015-09-09	R 2004-07-11	The Boeing Company	767-200, -300, and -400ER series
<b>Biweekly 2015-11</b>			
2015-10-02	R 2014-20-11	Zodiac Seats France	9140, 9166, 9173, 9174, 9184, 9188, 9196, 91B7, 91B8, 91C0, 91C2, 91C4, 91C5, 91C9, 9301, and 9501 series passenger seat assemblies
2015-10-03	R 2014-09-05	Airbus Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, and -313
2015-10-04	R 2012-09-09	International Aero Engines AG	IAE V2500-A1, IAE V2525-D5, IAE V2522-A5, V2524-A5, V2527-A5, V2527E-A5, V2527M-A5, V2530-A5, and V2533-A5
2015-11-04		The Boeing Company	707-100 long body, -200, -100B long body, and -100B short body; 707-300, -300B, -300C, -400; 720 and 720B series

## LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces

**Biweekly 2015-12**

2015-10-01		Bombardier, Inc.	DHC-8-401, -402, and -403
2015-11-02	R 95-26-11	Lockheed Martin Corporation	L-1011-385-1, L-1011-385-1-14, L-1011-385-1-15, and L-1011-385-3
2015-11-03		ATR-GIE Avions de Transport Régional	ATR42-200, -300, -320, and -500; ATR72-101, -201, -102, -202, -211, -212, and -212A; ATR42-200, -300, -320, and -500; ATR72-101, -201, -102, -202, -211, -212, and -212A
2015-11-05		The Boeing Company	747-400, 747-400D, 747-400F, 747-8F, and 747-8 series



---

**2015-10-01 Bombardier, Inc.:** Amendment 39-18156. Docket No. FAA-2014-0754; Directorate Identifier 2014-NM-136-AD.

**(a) Effective Date**

This AD becomes effective July 14, 2015.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Bombardier, Inc. Model DHC-8-401, -402, and -403 airplanes, certificated in any category, serial numbers 4001 through 4424 inclusive.

**(d) Subject**

Air Transport Association (ATA) of America Code 29, Hydraulic Power.

**(e) Reason**

This AD was prompted by reports of hydraulic fluid loss from the reservoir of the main landing gear (MLG) alternate extension system. We are issuing this AD to, in the event of a failure of the primary MLG extension system, prevent failure of the alternate MLG extension system to fully extend the MLG into a down-and-locked position, which could result in collapse of both left-hand and right-hand MLG sides during touchdown.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Inspection and Corrective Action**

Within 2,000 flight hours or 12 months after the effective date of this AD, whichever occurs first: Do a general visual inspection of the MLG alternate extension system reservoir lid for correct assembly, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 84-29-34, dated May 9, 2013, and with the attached Parker Service Bulletin 82910012-29-431, dated October 22, 2012, as referenced in Bombardier Service Bulletin 84-29-34, dated May 9, 2013. Do all applicable corrective actions within 2,000 flight hours or 12 months after the effective date of this AD, whichever occurs first.

### **(h) Credit for Previous Actions**

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier All Operator Message 543, dated October 17, 2012, which is not incorporated by reference in this AD.

### **(i) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

### **(j) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2014-15, dated June 6, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2014-0754-0002>.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (k)(5) of this AD.

### **(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 84-29-34, dated May 9, 2013.

(ii) Parker Service Bulletin 82910012-29-431, dated October 22, 2012.

(3) For Bombardier service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email [thd.qseries@aero.bombardier.com](mailto:thd.qseries@aero.bombardier.com); Internet <http://www.bombardier.com>.

(4) For Parker service information identified in this AD, contact Parker Aerospace, 14300 Alton Parkway, Irvine, CA, 92618; phone: 949-833-3000; Internet: <http://www.parker.com>.

(5) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 1, 2015.  
Jeffrey E. Duven,  
Manager, Transport Airplane Directorate,  
Aircraft Certification Service.



---

**2015-11-02 Lockheed Martin Corporation/Lockheed Martin Aeronautics Company:**  
Amendment 39-18165 ; Docket No. FAA-2014-0227; Directorate Identifier 2013-NM-211-AD.

**(a) Effective Date**

This AD is effective July 14, 2015.

**(b) Affected ADs**

This AD replaces AD 95-26-11, Amendment 39-9469 (60 FR 66870, December 27, 1995).

**(c) Applicability**

This AD applies to all Lockheed Martin Corporation/Lockheed Martin Aeronautics Company Model L-1011-385-1, L-1011-385-1-14, L-1011-385-1-15, and L-1011-385-3 airplanes, certificated in any category.

**(d) Subject**

Air Transport Association (ATA) of America Code 53, Fuselage.

**(e) Unsafe Condition**

This AD was prompted by a determination that the fittings at stringer attachments to the upper region of the aft pressure bulkhead are subject to widespread fatigue damage (WFD). We are issuing this AD to prevent simultaneous failure of multiple stringer end fittings through fatigue cracking at the aft pressure bulkhead, which could lead to rapid decompression of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Retained Detailed Visual Inspection**

This paragraph restates the requirements of paragraph (a) of AD 95-26-11, Amendment 39-9469 (60 FR 66870, December 27, 1995), with no changes. Perform a detailed visual inspection to detect cracking of the fittings that attach the aft pressure bulkhead to the fuselage stringers (hereinafter referred to as "fittings") at stringers 1 through 10 (right side) and at stringers 56 through 64 (left side), at the later of the times specified in either paragraph (g)(1) or (g)(2) of this AD.

(1) Prior to the accumulation of 20,000 total flight cycles; or

(2) Within the next 25 flight cycles or 10 days after September 28, 1995 (the effective date of AD 95-18-52, Amendment 39-9366 (60 FR 47465, September 13, 1995)), whichever occurs earlier.

**(h) Retained Corrective Action for Cracked Fitting**

This paragraph restates the requirements of paragraph (c) of AD 95-26-11, Amendment 39-9469 (60 FR 66870, December 27, 1995), with no changes. If any cracked fitting is detected during the inspection required by paragraph (g) of this AD: Before further flight, accomplish the requirements of paragraphs (h)(1) and (h)(2) of this AD.

(1) Replace the cracked fitting with a new fitting, or with a serviceable fitting on which a detailed visual inspection has been performed previously to detect cracking and that has been found to be free of cracks.

(2) Perform a detailed visual inspection to detect cracking in the radius at the lower end of the vertical leg of the bulkhead T-shaped frame between the stringer locations on either side of the stringer having the cracked fitting. If any cracked T-shaped frame is detected: Before further flight, repair in accordance with a method approved by the Manager, Atlanta Aircraft Certification Office (ACO), FAA.

**(i) Retained Repetitive Fitting Inspections**

This paragraph restates the requirements of paragraph (d) of AD 95-26-11, Amendment 39-9469 (60 FR 66870, December 27, 1995), with no changes. Repeat the inspections and other necessary actions required by paragraphs (g) and (h) of this AD at intervals not to exceed 1,800 flight cycles or 3,000 flight hours, whichever occurs earlier, until paragraph (j) of this AD is accomplished.

**(j) Retained Eddy Current Surface Scan (ECSS) Inspections, and Related Investigative and Corrective Actions**

This paragraph restates the requirements of paragraph (e) of AD 95-26-11, Amendment 39-9469 (60 FR 66870, December 27, 1995), with revised compliance times specified in paragraph (k) of this AD, exclusion of an ECSS inspection for certain airplanes, and new service information. Except as provided by paragraph (l) of this AD: At the applicable time specified in paragraph (k)(1) of this AD, accomplish the requirements of paragraphs (j)(1) and (j)(2) of this AD. Repeat the ECSS inspections thereafter at the compliance time specified in paragraph (k)(2) of this AD. Accomplishment of the ECSS inspection constitutes terminating action for the repetitive inspection requirements of paragraph (i) of this AD.

(1) Perform an ECSS inspection to detect cracking of the fittings at stringers 1 through 14 (right side) and at stringers 52 through 64 (left side), in accordance with the Accomplishment Instructions of Lockheed L-1011 Service Bulletin 093-53-105, Revision 1, dated November 17, 1995; or Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013; except for airplanes with a large (47-inch-wide) aft passenger door, an ECSS inspection of stringers 12, 13, 53, and 54 is not required by this paragraph. Except as provided by paragraph (m) of this AD, if any cracking is detected, prior to further flight, replace the fitting with a new fitting without pilot holes, rework the fitting, and perform various follow-on actions (i.e., bolt hole eddy current (BHEC), ECSS, and borescope inspections; and repair) of the inner and outer tee caps, in accordance with the Accomplishment Instructions of Lockheed L-1011 Service Bulletin 093-53-105, Revision 1, dated November 17, 1995; or Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013, except as required by paragraph (p) of this AD. As of the effective date of this AD, use only Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013, for accomplishing the actions required by this paragraph.

(2) Perform an ECSS inspection to detect cracking of the lower (or inner) surface of the upper bonded splice tab of the bulkhead assembly at stringers 1 through 14 (right side) and at stringers 52 through 64 (left side), in accordance with the Accomplishment Instructions of Lockheed L-1011 Service Bulletin 093-53-105, Revision 1, dated November 17, 1995; or Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013. As of the effective date of this AD, use only Lockheed

Service Bulletin 093-53-105, Revision 3, dated May 31, 2013, for accomplishing the actions required by this paragraph.

(i) Except as provided by paragraph (m) of this AD, if any cracking is detected at the upper bonded splice tab, repair in accordance with a method approved by the Manager, Atlanta ACO, FAA.

(ii) Except as provided by paragraph (m) of this AD, if any cracking is detected at a fastener, prior to further flight, perform a BHEC inspection to detect cracking of the forward flange of the inner tee cap, in accordance with the Accomplishment Instructions of Lockheed L-1011 Service Bulletin 093-53-105, Revision 1, dated November 17, 1995; or Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013. If any cracking is detected, prior to further flight, repair in accordance with the Accomplishment Instructions of Lockheed L-1011 Service Bulletin 093-53-105, Revision 1, dated November 17, 1995; or Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013, except as required by paragraph (p) of this AD. As of the effective date of this AD, use only Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013, for accomplishing the actions required by this paragraph.

### **(k) New Revised Compliance Times for Paragraph (j) of This AD**

(1) Do the initial inspections required by paragraph (j) of this AD at the earlier of the times specified in paragraphs (k)(1)(i) and (k)(1)(ii) of this AD.

(i) Prior to the accumulation of 20,000 total flight cycles, or within 30 days after January 11, 1996 (the effective date of date of AD 95-26-11, Amendment 39-9469 (60 FR 66870, December 27, 1995)), whichever occurs later.

(ii) At the later of the times specified in paragraphs (k)(1)(ii)(A) and (k)(1)(ii)(B) of this AD.

(A) Before the accumulation of 13,875 total flight cycles.

(B) Within 365 days or 1,000 flight cycles after the effective date of this AD, whichever occurs first.

(2) Repeat the inspections specified in paragraph (j) of this AD within 2,500 flight cycles after accomplishing the most recent inspection required by paragraph (j) of this AD, and repeat the inspection thereafter at intervals not to exceed 1,750 flight cycles.

### **(l) Retained Inspection Deferral for Paragraph (j) of This AD**

This paragraph restates the requirements of paragraph (f) of AD 95-26-11, Amendment 39-9469 (60 FR 66870, December 27, 1995). Accomplishment of the initial ECSS inspections required by paragraph (j) of this AD may be deferred to a date within 120 days after January 11, 1996 (the effective date of date of AD 95-26-11), provided that, in the interim, a visual inspection as specified in paragraph (g) of this AD is accomplished within 30 days after January 11, 1996 (the effective date of date of AD 95-26-11), and repeated thereafter at intervals not to exceed 50 flight cycles. Once the ECSS inspections begin, the visual inspections may be terminated.

### **(m) Retained Inspection Deferral With Revised Compliance Time and New Deferral**

This paragraph restates the requirements of paragraph (g) of AD 95-26-11, Amendment 39-9469 (60 FR 66870, December 27, 1995), with a revised compliance time, service information, and a new deferred action. As of the effective date of this AD, the deferral specified in paragraphs (m)(1) and (m)(2) of this AD cannot be done. If cracking was found before the effective date of this AD, the deferral specified in paragraphs (m)(1) and (m)(2) of this AD may be done. (1) If two or more adjacent fittings on both sides of the cracked fittings or bonded splice tabs/fasteners are determined to be free of cracks by the ECSS inspection required by paragraphs (j)(1) and (j)(2) of this AD, repeat the ECSS inspection of the adjacent fittings thereafter at intervals not to exceed 600 flight cycles until the cracked fittings or splice tabs/fasteners are replaced or repaired, in accordance with the Accomplishment Instructions of Lockheed L-1011 Service Bulletin 093-53-105, Revision 1, dated

November 17, 1995; or Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013. At the applicable time specified in paragraphs (m)(1)(i) and (m)(1)(ii) of this AD: Replace the cracked fitting and/or splice tab/fasteners, in accordance with the Accomplishment Instructions of Lockheed L-1011 Service Bulletin 093-53-105, Revision 1, dated November 17, 1995; or Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013. As of the effective date of this AD, use only Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013, for accomplishing the actions required by this paragraph.

(i) For any crack found before the effective date of this AD: Within 2,500 flight cycles after finding the crack.

(ii) For any crack found on or after the effective date of this AD: Before further flight after finding the crack.

(2) If two or more adjacent fittings on both sides of the cracked fittings or bonded splice tabs/fasteners are determined to be free of cracks by the ECSS inspection required by paragraphs (j)(1) and (j)(2) of this AD, the follow-on inspection (i.e., BHEC, ECSS, and borescope inspections) of the inner and outer tee caps required by paragraph (j)(1) of this AD may also be deferred until the cracked fittings are replaced as required by paragraph (m)(1) of this AD, but no later than before the accumulation of 20,800 total flight cycles.

#### **(n) New Repetitive Borescope Inspections of Certain End Fittings and Corrective Actions**

For airplanes with a large (47-inch-wide) aft passenger door: At the later of the times specified in paragraphs (n)(1) and (n)(2) of this AD, do a borescope inspection for cracking of the stringer end fittings at stringer locations 12, 13, 53, and 54; and do all applicable related investigative and corrective actions; in accordance with the Accomplishment Instructions of Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013, except as specified in paragraph (p) of this AD. Do all applicable related investigative and corrective actions before further flight. Repeat the inspection of the stringer end fittings thereafter at intervals not to exceed 1,750 flight cycles until the actions required by paragraph (q) of this AD have been done.

(1) Before the accumulation of 13,875 total flight cycles.

(2) Within 365 days or 1,000 flight cycles after the effective date of this AD, whichever occurs earlier.

#### **(o) New Repetitive Borescope Inspections of Fuselage Skin Panels**

For airplanes with a large (47-inch-wide) aft passenger door: At the later of the times specified in paragraphs (o)(1) and (o)(2) of this AD, do an ECSS inspection for cracking of the left and right aft fuselage skin panels; and do all applicable related investigative and corrective actions; in accordance with the Accomplishment Instructions of Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013, except as specified in paragraph (p) of this AD. Do all applicable related investigative and corrective actions before further flight. Repeat the inspection of the aft fuselage skin panels thereafter at intervals not to exceed 1,750 flight cycles until the modification required by paragraph (q) of this AD is done.

(1) Before the accumulation of 13,875 total flight cycles.

(2) Within 365 days or 1,000 flight cycles after the effective date of this AD, whichever occurs first.

#### **(p) New Service Information Exception**

If any cracking is found during any inspection required by this AD, and Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013, specifies contacting Lockheed for appropriate action: Before further flight, repair the cracking in accordance with a method approved by the Manager, Atlanta ACO, FAA. As of the effective date of this AD, for a repair method to be approved

by the Manager, Atlanta ACO, as required by this paragraph, the Manager's approval letter must specifically refer to this AD.

**(q) New Pre-Structural Modification Inspections and Structural Modification**

Before the accumulation of 20,800 total flight cycles: Do the applicable actions specified in paragraphs (q)(1) and (q)(2) of this AD.

(1) Perform pre-structural modification inspections by doing the actions required by paragraphs (j), (n), and (o) of this AD.

(2) Perform a structural modification of the aft pressure bulkhead by removing and replacing all stringer end fittings with new or refurbished fittings at stringers 1 through 14, and 52 through 64, in accordance with the Accomplishment Instructions of Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013.

**(r) New Post-Structural Modification Repetitive Inspections**

Within 13,875 flight cycles after performing the actions required by paragraph (q)(2) of this AD: Do the actions specified in paragraphs (j), (n), and (o) of this AD, and repeat thereafter at intervals not to exceed 1,750 flight cycles.

**(s) No Reporting Requirement**

Although Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013, referenced in this AD specifies to submit certain information to the manufacturer, this AD does not include that requirement.

**(t) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Atlanta ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (u) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(u) Related Information**

For more information about this AD, contact Carl Gray, Aerospace Engineer, Airframe Branch, ACE-117A, FAA, Atlanta Aircraft Certification Office (ACO), 1701 Columbia Avenue, College Park, GA 30337; phone: 404-474-5554; fax: 404-474-5605; email: carl.w.gray@faa.gov.

**(v) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on July 14, 2015.

(i) Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013 (The date of May 15, 2013, on page 1 of Lockheed Service Bulletin 093-53-105, Revision 3, dated May 31, 2013, is incorrect and should be May 31, 2013).

(ii) Reserved.

(4) The following service information was approved for IBR on January 11, 1996 (60 FR 66870, December 27, 1995).

(i) Lockheed L-1011 Service Bulletin 093-53-105, Revision 1, dated November 17, 1995.

(ii) Reserved.

(5) For Lockheed service information identified in this AD, contact Lockheed Martin Corporation/Lockheed Martin Aeronautics Company, L1011 Technical Support Center, Dept. 6A4M, Zone 0579, 86 South Cobb Drive, Marietta, GA 30063-0579; telephone 770-494-5444; fax 770-494-5445; email L1011.support@lmco.com; Internet <http://www.lockheedmartin.com/ams/tools/TechPubs.html>.

(6) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 18, 2015.

John P. Piccola, Jr.,  
Acting Manager, Transport Airplane Directorate,  
Aircraft Certification Service.



---

**2015-11-03 ATR-GIE Avions de Transport Régional:** Amendment 39-18166. Docket No. FAA-2014-0568; Directorate Identifier 2014-NM-075-AD.

**(a) Effective Date**

This AD becomes effective July 14, 2015.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to the airplanes identified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD.

(1) ATR-GIE Avions de Transport Régional Model ATR42-200, -300, -320, and -500 airplanes; and Model ATR72-101, -201, -102, -202, -211, -212, and -212A airplanes; certificated in any category; all manufacturer serial numbers qualified for extended range twin operations (ETOPS) with ATR Modification 04711.

(2) ATR-GIE Avions de Transport Régional Model ATR42-200, -300, -320, and -500 airplanes; certificated in any category; except as specified in paragraph (c)(2)(i) or (c)(2)(ii) of this AD.

(i) Airplanes modified with ATR Modification 04650.

(ii) Airplanes retrofitted as specified in ATR Service Bulletin ATR42-28-0033 or ATR42-28-0034, as applicable.

(3) ATR-GIE Avions de Transport Régional Model ATR72-101, -201, -102, -202, -211, -212, and -212A airplanes; certificated in any category; all manufacturer serial numbers; except as specified in paragraph (c)(3)(i) or (c)(3)(ii) of this AD.

(i) Airplanes modified with ATR Modification 04686.

(ii) Airplanes retrofitted as specified in ATR Service Bulletin ATR72-28-1013, ATR72-28-1022, or ATR72-28-1023, as applicable.

**(d) Subject**

Air Transport Association (ATA) of America Code 28, Fuel.

**(e) Reason**

This AD was prompted by reports of fuel quantity indication malfunctions caused by fuel probe failure. We are issuing this AD to detect and correct affected fuel probes, which could lead to undetected fuel starvation and consequent dual engine in-flight flame-out.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Part Number and Serial Number Inspection**

Within 5,000 flight hours or 24 months, whichever occurs first after the effective date of this AD: Inspect to determine if any fuel probe has any part number and serial number identified in table 1 to paragraph (g) of this AD. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number and serial number of the part can be conclusively determined from that review.

**Table 1 to Paragraph (g) of This AD—Affected Fuel Probes**

<b>Airplane model</b>	<b>Part No.</b>	<b>Serial No.</b>
ATR 42	766-046-2	1046 through 1083 inclusive.
ATR 42	766-047-2	1154 through 1214 inclusive.
ATR 42	766-048-2	1150 through 1197 inclusive.
ATR 42	768-055	1156 through 1227 inclusive.
ATR 42	798-038	1150 through 1238 inclusive.
ATR 72	766-793-1	1469 through 1826 inclusive.
ATR 72	766-795-2	1661 through 2093 inclusive.
ATR 72	766-796-2	1722 through 2152 inclusive.
ATR 72	766-797-2	1663 through 2051 inclusive.
ATR 72	766-983-1	2200 through 2652 inclusive.
ATR 72	768-100	1511 through 1876 inclusive.

**(h) Replacement**

If any fuel probe is found that has any part number and serial number specified in table 1 to paragraph (g) of this AD: Within 5,000 flight hours or 24 months, whichever occurs first after the effective date of this AD, replace the fuel probe with a serviceable fuel probe, using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or ATR-GIE Avions de Transport Régional's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

Note 1 to paragraph (h) of this AD: Guidance on accomplishing the replacement can be found in Job Instruction Card 28-42-72, RAI 10000-001, "Removal and Installation of Fuel Quantity or Fuel Temp/Quantity Probe" of the ATR-42 Aircraft Maintenance Manual; and Job Instruction Card 28-42-72, RAI 10000-002, "Removal and Installation of Fuel Quantity or Fuel Temp/Quantity Probe" of the ATR-72 Aircraft Maintenance Manual.

**(i) Definition of Serviceable Fuel Probe**

For the purposes of this AD, a fuel probe is serviceable if it meets the criterion specified in paragraph (i)(1) or (i)(2) of this AD.

- (1) The fuel probe is not listed in table 1 to paragraph (g) of this AD.

(2) The fuel probe is listed in table 1 to paragraph (g) of this AD, but has control tag "C" marked on the part identification plate, as specified in Zodiac Aerospace Service Bulletin 766983-28-002, Revision 1, dated March 24, 2014.

#### **(j) Parts Installation Limitations**

As of the effective date of this AD, no person may install, on any airplane, a fuel probe having any part number and serial number identified in table 1 to paragraph (g) of this AD, unless control tag "C" is marked on the part identification plate, as specified in Zodiac Aerospace Service Bulletin 766983-28-002, Revision 1, dated March 24, 2014.

#### **(k) Credit for Previous Actions**

This paragraph provides credit for applying the definitions and limitations specified in paragraphs (i)(2) and (j) of this AD, if those provisions were applied before the effective date of this AD using Zodiac Aerospace Service Bulletin 766983-28-002, dated October 15, 2013, which is not incorporated by reference in this AD.

#### **(l) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or EASA; or ATR-GIE Avions de Transport Régional's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

#### **(m) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0075R1, dated April 24, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2014-0568-0002>.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(3) and (n)(4) of this AD.

#### **(n) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Zodiac Aerospace Service Bulletin 766983-28-002, Revision 1, dated March 24, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Zodiac Aerospace, Technical Publication Department, 61 Rue Pierre Curie–CS20001, 78373 Plaisir Cedex, France; phone: +33 (0)1 61 34 19 24; fax: +33 (0)1 61 34 21 13; email: [yann.laine@zodiac aerospace.com](mailto:yann.laine@zodiac aerospace.com); Internet: <http://www.zodiac aerospace.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 18, 2015.

John P. Piccola, Jr.,  
Acting Manager, Transport Airplane Directorate,  
Aircraft Certification Service.



---

**2015-11-05 The Boeing Company:** Amendment 39-18168; Docket No. FAA-2014-0342; Directorate Identifier 2014-NM-007-AD.

**(a) Effective Date**

This AD is effective July 6, 2015.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to The Boeing Company Model 747-400, 747-400D, 747-400F, 747-8F, and 747-8 series airplanes, certificated in any category, as identified in paragraphs (c)(1) and (c)(2) of this AD.

- (1) Airplanes identified in Boeing Service Bulletin 747-21-2550, dated December 6, 2013.
- (2) Airplanes identified in paragraph (h)(2) of this AD.

**(d) Subject**

Air Transport Association (ATA) of America Code 21, Air conditioning.

**(e) Unsafe Condition**

This AD was prompted by reports of very high temperatures, near the floor in the aft lower lobe cargo compartment. We are issuing this AD to prevent overheating of the aft lower lobe cargo compartment, where, if temperature sensitive cargo is present, the release of flammable vapors could result in a fire or explosion if exposed to an ignition source.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Installation for Certain Airplanes (Interim Action)**

Within 12 months after the effective date of this AD, remove the existing markers and install tape and new markers in the bulk cargo compartment, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-21-2544, Revision 2, dated December 11, 2014; or using a method approved in accordance with the procedures specified in paragraph (j) of this AD, as applicable. Accomplishing the actions specified in paragraph (h) of this AD within 12 months after the effective date of this AD terminates the requirements of this paragraph.

**(h) Installation for All Airplanes (Terminating Action)**

Within 60 months after the effective date of this AD, install an additional zone temperature sensor assembly in the aft cargo compartment, as specified in paragraph (h)(1) or (h)(2) of this AD, as applicable. Doing this action within 12 months after the effective date of this AD terminates the requirements of paragraph (g) of this AD.

(1) For airplanes identified in Boeing Service Bulletin 747-21-2550, dated December 6, 2013: Do the actions in accordance with the Accomplishment Instructions of Boeing Service Bulletin 747-21-2550, dated December 6, 2013.

(2) For airplanes having variable numbers RC021 and RC573: Do the actions using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

**(i) Credit for Previous Actions**

This paragraph provides credit for removing the existing markers and installing tape and new markers in the bulk cargo compartment, as required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Service Bulletin 747-21-2544, dated January 15, 2013; or Boeing Special Attention Service Bulletin 747-21-2544, Revision 1, dated September 30, 2013. This service information is not incorporated by reference in this AD.

**(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) If the service information contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

**(k) Related Information**

(1) For more information about this AD that is not incorporated by reference, contact Susan Monroe, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, 1601 Lind Avenue SW., Renton, WA; phone: 425-917-6457; fax: 425-917-6590; email: susan.l.monroe@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

#### **(I) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Service Bulletin 747-21-2544, Revision 2, dated December 11, 2014.

(ii) Boeing Special Attention Service Bulletin 747-21-2550, dated December 6, 2013.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 21, 2015.

John P. Piccola, Jr.,  
Acting Manager, Transport Airplane Directorate,  
Aircraft Certification Service.