

[Federal Register: March 11, 2005 (Volume 70, Number 47)]
[Rules and Regulations]
[Page 12119-12120]
From the Federal Register Online via GPO Access [wais.access.gpo.gov]
[DOCID:fr11mr05-7]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2004-19446; Directorate Identifier 2004-NM-130-AD; Amendment 39-13967; AD 2005-03-11]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 767-200 and -300 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; correction.

SUMMARY: The FAA is correcting a typographical error in an existing airworthiness directive (AD) that was published in the Federal Register on February 11, 2005 (70 FR 7174). The error resulted in an incorrect AD number. This AD applies to certain Boeing Model 767 series airplanes. This AD requires repetitive detailed and eddy current inspections of the aft pressure bulkhead for damage and cracking, and repair if necessary. This AD also requires one-time detailed and high frequency eddy current inspections of any "oil-can" located on the aft pressure bulkhead, and related corrective actions if necessary.

DATES: Effective March 18, 2005.

ADDRESSES: The AD docket contains the proposed AD, comments, and any final disposition. You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, Washington, DC. This docket number is FAA-2004-19446; the directorate identifier for this docket is 2004-NM-130-AD.

FOR FURTHER INFORMATION CONTACT: Suzanne Masterson, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6441; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION: On January 31, 2005, the FAA issued AD 2005-03-11, amendment 39-13967 (70 FR 7174, February 11, 2005), for certain Boeing Model 767 series airplanes. The AD requires repetitive detailed and eddy current inspections of the aft pressure

bulkhead for damage and cracking, and repair if necessary. The AD also requires one-time detailed and high frequency eddy current inspections of any "oil-can" located on the aft pressure bulkhead, and related corrective actions if necessary.

As published, that final rule incorrectly specified the AD number in a single location in the AD as "2005-NM-03-11" instead of "2005-03-11."

No other part of the regulatory information has been changed; therefore, the final rule is not republished in the Federal Register.

The effective date of this AD remains March 18, 2005.

§ 39.13 [Corrected]

In the Federal Register of February 11, 2005, on page 7175, in the first column, paragraph 2. of PART 39–AIRWORTHINESS DIRECTIVES is corrected to read as follows:

* * * * *

2005-03-11 Boeing: Amendment 39-13967. Docket No. FAA-2004-19446; Directorate Identifier 2004-NM-130-AD.

* * * * *

Issued in Renton, Washington, on February 28, 2005.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-4825 Filed 3-10-05; 8:45 am]

BILLING CODE 4910-13-P

[Federal Register: February 11, 2005 (Volume 70, Number 28)]
[Rules and Regulations]
[Page 7174-7176]
From the Federal Register Online via GPO Access [wais.access.gpo.gov]
[DOCID:fr11fe05-3]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2004-19446; Directorate Identifier 2004-NM-130-AD; Amendment 39-13967; AD 2005-03-11]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 767-200 and -300 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD), which applies to certain Boeing Model 767 series airplanes. That AD currently requires repetitive detailed and eddy current inspections of the aft pressure bulkhead for damage and cracking, and repair if necessary. This new AD also requires one-time detailed and high frequency eddy current inspections of any "oil-can" located on the aft pressure bulkhead, and related corrective actions if necessary. An "oil-can" is an area on a pressure dome web that moves when pushed from the forward side. This AD is prompted by reports of cracking at "oil-can" boundaries on the aft pressure bulkhead. We are issuing this AD to detect and correct fatigue cracking of the aft pressure bulkhead, which could result in rapid depressurization of the airplane and possible damage or interference with the airplane control systems that penetrate the bulkhead, and consequent loss of controllability of the airplane.

DATES: This AD becomes effective March 18, 2005.

On March 22, 2004 (69 FR 10321, March 5, 2004), the Director of the Federal Register approved the incorporation by reference of Boeing Alert Service Bulletin 767-53A0026, Revision 5, dated January 29, 2004.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. You can examine this information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to:

http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

DOCKET: The AD docket contains the proposed AD, comments, and any final disposition. You can examine the AD docket on the Internet at *<http://dms.dot.gov>*, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the

Nassif Building at the U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, Washington, DC. This docket number is FAA-2004-19446; the directorate identifier for this docket is 2004-NM-130-AD.

FOR FURTHER INFORMATION CONTACT: Suzanne Masterson, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6441; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION: The FAA proposed to amend part 39 of the Federal Aviation Regulations (14 CFR Part 39) with an AD to supersede AD 2004-05-10, amendment 39-13505 (69 FR 10321, March 5, 2004). The existing AD applies to certain Boeing Model 767 series airplanes. The proposed AD was published in the Federal Register on October 26, 2004 (69 FR 62421), to continue to require repetitive detailed and eddy current inspections of the aft pressure bulkhead for damage and cracking, and repair if necessary, and to require one-time detailed and high frequency eddy current inspections of any "oil-can" located on the aft pressure bulkhead, and related corrective actions if necessary.

Comments

We provided the public the opportunity to participate in the development of this AD. No comments have been submitted on the proposed AD or on the determination of the cost to the public.

Clarification of Alternative Methods of Compliance (AMOC) Language in the Proposed AD

We have revised paragraph (1)(3) of the AD to clarify which portions of the AD the previously approved AMOC applies to. We have replaced "* * *" with "this AD." with "* * *" for the corresponding requirements of this AD."

Changes to Delegation Authority

Boeing has received a Delegation Option Authorization (DOA). We have revised this final rule to delegate authority to approve an alternative method of compliance for any repair required by this AD to the Authorized Representative for the Boeing DOA Organization rather than the Designated Engineering Representative (DER).

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD with the changes described previously. We have determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

Costs of Compliance

There are about 162 airplanes worldwide of the affected design. This new AD affects about 99 airplanes of U.S. registry.

The actions that are required by AD 2004-05-10 and retained in this new AD take about 22 work hours per airplane, at an average labor rate of \$65 per work hour. Based on these figures, the estimated cost of the currently required actions is \$1,430 per airplane, per inspection cycle.

The new actions take about 2 work hours per "oil-can," at an average labor rate of \$65 per work hour. Based on these figures, the estimated cost of the new actions specified in this new AD for U.S. operators is \$130 per "oil-can." The number of "oil cans" varies per airplane, so an estimate per airplane or for the U.S. registered fleet is not available.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD. See the ADDRESSES section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by removing amendment 39-13505 (69 FR 10321, March 5, 2004), and by adding the following new airworthiness directive (AD):

AIRWORTHINESS DIRECTIVE



Aircraft Certification Service
Washington, DC

U.S. Department
of Transportation
**Federal Aviation
Administration**

We post ADs on the internet at "www.faa.gov"

The following Airworthiness Directive issued by the Federal Aviation Administration in accordance with the provisions of Title 14 of the Code of Federal Regulations (14 CFR) part 39, applies to an aircraft model of which our records indicate you may be the registered owner. Airworthiness Directives affect aviation safety and are regulations which require immediate attention. You are cautioned that no person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of the Airworthiness Directive (reference 14 CFR part 39, subpart 39.3).

CORRECTION: [*Federal Register: March 11, 2005 (Volume 70, Number 47); Page 12119-12120; www.access.gpo.gov/su_docs/aces/aces140.html*]

2005-03-11 Boeing: Amendment 39-13967. Docket No. FAA-2004-19446; Directorate Identifier 2004-NM-130-AD.

Effective Date

- (a) This AD becomes effective March 18, 2005.

Affected ADs

- (b) This AD supersedes AD 2004-05-10, amendment 39-13505.

Applicability

- (c) This AD applies to Boeing Model 767-200 and -300 series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin (ASB) 767-53A0026, Revision 5, dated January 29, 2004.

Unsafe Condition

- (d) This AD was prompted by reports of cracking at "oil-can" boundaries on a Boeing Model 747 series airplane's aft pressure bulkhead, which is similar to the aft pressure bulkheads on Boeing Model 767 series airplanes. We are issuing this AD to detect and correct fatigue cracking of the aft pressure bulkhead, which could result in rapid depressurization of the airplane and possible damage or interference with the airplane control systems that penetrate the bulkhead, and consequent loss of controllability of the airplane.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Requirements of AD 2004-05-10

Detailed Inspections and Eddy Current Inspections

(f) Perform a detailed inspection for damage and cracking of the aft side of the aft pressure bulkhead and perform high frequency and low frequency eddy current inspections for cracking of the aft pressure bulkhead, in accordance with the Accomplishment Instructions of Boeing ASB 767-53A0026, Revision 5, dated January 29, 2004, at the later of the times specified in paragraph (f)(1) or (f)(2) of this AD. Thereafter, repeat these inspections at intervals not to exceed 1,800 flight cycles.

Note 1: For the purposes of this AD, a detailed inspection is: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(1) Prior to the accumulation of 25,000 total flight cycles, or within 1,800 flight cycles after the most recent inspection done in accordance with AD 88-19-03 R1, amendment 39-6532, whichever occurs later; or

(2) Within 90 days after March 22, 2004 (the effective date of AD 2004-05-10).

Repair Requirements

(g) If any damage or cracking is detected during any inspections required by paragraph (f) of this AD: Before further flight accomplish the requirements of paragraph (g)(1) or (g)(2) of this AD, as applicable:

(1) For repairs within the limits of the Accomplishment Instructions of Boeing ASB 767-53A0026, Revision 5, dated January 29, 2004, repair in accordance with the ASB.

(2) For any repairs outside the limits, repair in accordance with a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA; or in accordance with data meeting the type certification basis of the airplane approved by an Authorized Representative (AR) for the Boeing Delegation Option Authorization (DOA) Organization who has been authorized by the FAA to make those findings. For a repair method to be approved, as required by this paragraph, the approval must specifically reference this AD.

New Requirements of This AD

"Oil-Can" Inspection and Repair

(h) Before the accumulation of 37,500 total flight cycles, or within 1,800 flight cycles after the effective date of this AD, whichever occurs later: Do a one-time detailed and surface high frequency eddy current inspections at all "oil-can" locations of the aft pressure bulkhead web for damage and cracks, in accordance with Figure 4 of the Accomplishment Instructions of the Boeing ASB 767-53A0026, Revision 5, dated January 29, 2004. All "oil-cans" must meet the limits specified in the service bulletin.

Note 2: An "oil-can" is an area on a pressure dome web that moves when pushed from the forward side.

(1) If no damage and no crack are found, no further action is required by this paragraph.

(2) If any damage or crack is found, before further flight, repair in accordance with the service bulletin, except as required by paragraph (i) of this AD.

(3) If any "oil can" does not meet the limits specified in the service bulletin, before further flight, repair the "oil can" in accordance with the service bulletin, except as required by paragraph (i) of this AD.

(i) Where the service bulletin specifies to contact Boeing for repair data, before further flight, repair the damage or crack in accordance with a method approved by the Manager, Seattle ACO, FAA; or in accordance with data meeting the type certification basis of the airplane approved by an AR for the Boeing DOA Organization who has been authorized by the FAA to make those findings. For a repair method to be approved, as required by this paragraph, the approval must specifically reference this AD.

(j) Inspections and repairs accomplished before the effective date of this AD in accordance with Boeing ASB 767-53A0026, Revision 4, dated March 27, 2003, are considered acceptable for compliance with paragraph (h) of this AD.

Determining the Number of Flight Cycles for Compliance Time

(k) For the purposes of calculating the compliance threshold for the actions required by paragraph (f) and (h) of this AD, the number of flight cycles in which cabin differential pressure is at 2.0 pounds per square inch (psi) or less must be counted when determining the number of flight cycles that have occurred on the airplane. Where the service bulletins and this AD differ, the AD prevails.

Alternative Methods of Compliance (AMOCs)

(1)(1) The Manager, Seattle ACO, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an AR for the Boeing DOA Organization who has been authorized by the FAA to make those findings.

(3) Alternative methods of compliance, approved previously in accordance with AD 2004-05-10, are approved as alternative methods of compliance for the corresponding requirements of this AD.

Material Incorporated by Reference

(m) You must use Boeing Alert Service Bulletin 767-53A0026, Revision 5, dated January 29, 2004, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register previously approved the incorporation by reference of this document on March 22, 2004 (69 FR 10321, March 5, 2004). For copies of the service information, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. For information on the availability of this material at the National Archives and Records Administration (NARA), call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html. You may view the AD docket at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, Nassif Building, Washington, DC.

Issued in Renton, Washington, on January 31, 2005.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-2578 Filed 2-10-05; 8:45 am]

BILLING CODE 4910-13-P