



**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES
LARGE AIRCRAFT**

BIWEEKLY 2010-06

This electronic copy may be printed and used in lieu of the FAA biweekly paper copy.

U.S. Department of Transportation
Federal Aviation Administration
Regulatory Support Division
Delegation and Airworthiness Programs Branch, AIR-140
P. O. Box 26460
Oklahoma City, OK 73125-0460
FAX 405-954-4104

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency

Biweekly 2010-01

2008-04-11 R1		Boeing	707-100 long body, -200, -100B long body, and -100B short body series airplanes; Model 707-300, -300B, -300C, and -400 series airplanes; and Model 720 and 720B
2008-09-12 R1		Bombardier	CL-600-2B19 (Regional Jet Series 100 & 440)
2008-10-09 R1		Boeing	737-100, -200, -200C, -300, -400, and -500
2008-11-01 R1		Boeing	767-200, -300, -300F, and -400ER
2009-20-11	Cor	Boeing	737-300, -400, and -500
2009-24-11		General Electric	See AD
2009-26-03		Boeing	See AD
2009-26-04		Boeing	737-600, -700, -700C, -800, and -900
2009-26-10		Airbus	A380-841, -842, and -861
2009-26-12		Engine Components, Inc. (ECi)	See AD
2009-26-14		CONSTRUCCIONES AERONAUTICAS, S.A. (CASA)	CN-235, CN-235-100, CN-235-200, and CN-235-300
2009-26-15		Embraer	ERJ 170-100 LR, -100 STD, -100 SE, -100 SU, -200 LR, -200 STD, and -200 SU airplanes, certificated in any category, serial numbers 17000156 through 17000169 inclusive; and Model ERJ 190-100 LR, -100 IGW, -100 STD, -200 STD, -200 LR, and -200 IGW
2009-26-16		McDonnell Douglas	MD-11 and MD-11F
2009-26-17		MCDonnell	Model DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, and DC-10-40F airplanes, and MD-10-10F and MD-10-30F

Biweekly 2010-02

2008-10-06 R1		Boeing	747-400, -400D, and -400F
2008-10-10 R1		Boeing	737-600, -700, -700C, -800, and -900
2009-26-06		Honeywell International Inc	Engine: ALF502L and ALF502R series, and LF507-1F and LF507-1H
2009-26-09	S 2007-05-16	General Electric Company	Engine: CF34-1A, -3A, -3A1, -3A2, -3B, and -3B1
2010-01-01	S 2006-05-02	Boeing	747-200F, 747-200C, 747-400, 747-400D, and 747-400F
2010-01-04	S 2009-24-11	General Electric Company	Engine: CF34-1A, CF34-3A, CF34-3A1, CF34-3A2, CF34-3B, and CF34-3B1
2010-01-03		Fire Fighting Enterprises Limited	See AD
2010-01-05		CFM International, S.A	Engine: See AD
2010-01-06		Bombardier, Inc.	DHC-8-400, DHC-8-401, and DHC-8-402
2010-01-07		Airbus	A340-211, -212, -213, -311, -312, -313, -541, and -642
2010-01-08		Boeing	737-600, -700, and -800
2010-01-09		Boeing	737-300, -400, and -500
2010-01-11		Fokker Services B.V.	F.28 Mark 0070 and Mark 0100
2010-01-12		Embraer	ERJ 170-100 LR, -100 STD, -100 SE, -100 SU, -200 LR, -200 STD, and -200 SU
2010-02-02		Dassault	Falcon 7X
2010-02-03		Airbus	A340-211, -212, -213, -311, -312, and -313
2010-02-04		Boeing	737-600, -700, -700C, -800, -900, and -900ER

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency			
Biweekly 2010-03			
2009-21-10 R1		AVOX Systems and B/E Aerospace	Appliance: Oxygen cylinder assemblies
2009-26-13		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343, 340-211, -212, -213, -311, -312, and -313
2010-01-02	S 2005-15-08	Boeing	747-100B SUD, -200B, -300, -400, and -400D
2010-01-10	S 2007-01-15	Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747SR, and 747SP
2010-02-06		Sigma Aero Seat	Appliance: 90xx and 92xx series passenger seats
2010-02-09		Airbus	A318
2010-02-10		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343 series airplanes; Model A340-211, -212, -213, -311, -312, -313 series airplanes; and Model A340-541 and -642
2010-02-11		BAE Systems	BAE 146-100A, -200A, and -300A series airplanes; and BAE SYSTEMS (Operations) Limited Model Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2010-02-12		Fokker Services B.V	F.28 Mark 0070 and 0100
Biweekly 2010-04			
2010-03-05		Boeing	747-200C and -200F
2010-03-07		Embraer	EMB-135BJ, EMB-135ER, -135KE, -135KL, -135LR, EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP
2010-03-08	S 2003-03-02	Boeing	767-200, -300 and -300F
2010-04-01		Dassault Aviation	Falcon 900EX
2010-04-02		Airbus	A310-221, -222, -322, -324, and -325 airplanes, and Model A300 B4-620, B4-622, B4-622R, and F4-622R
2010-04-03		Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325
Biweekly 2010-05			
2009-06-05 R1		Bombardier, Inc	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A & CL-601-3R), CL-600-2B16 (CL-604)
2010-04-04		Bombardier, Inc	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705)
2010-04-08		Embraer	ERJ 190-100 LR, -100 IGW, -100 STD, -200 STD, -200 LR, and -200 IGW
2010-04-09		Airbus	A330-201, -202, -203, -223, and -243, A340-211, -212, and -213 airplanes; and Model A340-311, -312, and -313
2010-04-10	S 2009-10-07	Airbus	A380-841, -842, and -861
2010-04-13		Airbus	A310-203, A310-221, and A310-222, A300 F4-605R and A300 F4-622R
2010-04-16		SICLI	Appliance: Portable fire extinguishers
2010-05-01		ATR-GIE Avions de Transport Régional	ATR42-200, -300, -320, and -500 airplanes; and Model ATR72-101, -201, -102, -202, -211, -212, and -212A
2010-05-04		McDonnell Douglas Corporation	MD-90-30
2010-05-05	S 2007-15-08	BAE Systems	ATP
2010-05-06		Airbus	A340-541 and -642
2010-05-07		Airbus	A340-211, -212, and -213 airplanes; and Model A340-311, -312, and -313

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency

Biweekly 2010-06

2009-22-05	S 2008-23-16	Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2010-04-09	COR	Airbus	A330-201, -202, -203, -223, and -243, A340-211, -212, and -213 airplanes; and Model A340-311, -312, and -313
2010-04-12		Bombardier, Inc.	DHC-8-101, DHC-8-102, DHC-8-103, DHC-8-106, DHC-8-201, DHC-8-202, DHC-8-301, DHC-8-311, and DHC-8-315
2010-05-03		Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP
2010-05-09		Dowty Propellers	Propeller: R354/4-123-F/13, R354/4-123-F/20, R375/4-123-F/21, R389/4-123-F/25, R389/4-123-F/26, and R390/4-123-F/27
2010-05-11		Boeing	747-100, 747-200B, 747-300, and 747SR
2010-05-12		Bombardier, Inc	DHC-8-102, DHC-8-103, DHC-8-106, DHC-8-201, and DHC-8-202
2010-05-13	S 2006-07-12	Boeing	737-100, -200, -200C, -300, -400, and -500
2010-05-14		Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 & 440)
2010-06-01		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; Model A320-111, -211, -212, -214, -231, -232, and -233 airplanes; and Model A321-111, -112, -131, -211, -212, -213, -231, and -232
2010-06-04		Airbus	See AD
2010-06-05		Airbus	See AD
2010-06-51	E	Boeing	737-600, -700, -700C, -800, -900, and -900ER

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2009-22-05 Bombardier, Inc.: Amendment 39-16056. Docket No. FAA-2009-0656; Directorate Identifier 2009-NM-038-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective April 15, 2010.

Affected ADs

- (b) This AD supersedes AD 2008-23-16, Amendment 39-15737.

Applicability

(c) This AD applies to Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes, certificated in any category; serial numbers (S/Ns) 7003 through 7067 inclusive, 7069 through 7990 inclusive, 8000 through 8076 inclusive, 8082, 8086, 8090 through 8092 inclusive, 8096, and 8097.

Subject

- (d) Air Transport Association (ATA) of America Code 30: Ice and rain protection.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

"There have been several cases of wing leading edge anti-ice piccolo duct failure reported on CL-600-2B19 (CRJ) aircraft. Upon investigation, it was determined that ducts manufactured since May 2000 are susceptible to cracking due to the process used to drill holes in the ducts. This cracking may cause air leakage, with a possible adverse effect on the anti-ice air distribution pattern and anti-ice capability, without annunciation to the flight crew [and consequent reduced controllability of the airplane].

The faulty ducts were installed on aircraft SN 7417 through 7990 and 8000 through 8055 in production, and as replacement parts on in service aircraft SN 7014, 7017, 7037, 7046, 7059, 7076, 7105, 7127, 7151, 7157, 7163, 7179, 7203, 7228, 7271, 7347, 7359, 7362, 7378 and 7381. Service Bulletin (SB) 601R-30-029, Revision B and AD CF-2005-26R1 previously covered the above aircraft serial numbers.

It has subsequently been determined that faulty ducts may also have been installed in a number of leading edge assemblies built as spares and whose current locations are not specifically known. As they may have been installed on any of the aircraft serial numbers in the Applicability section of this directive, checking of records and/or inspection * * * is now required for all applicable aircraft.

"This directive, which supersedes and cancels AD CF-2005-26R1 [which corresponds to FAA AD 2005-17-12, amendment 39-14223], mandates the amendment of the Airplane Flight Manual (AFM) procedures, in addition to checking the part numbers and serial numbers of installed and spare wing anti-ice piccolo ducts, as required, and inspecting, replacing or repairing them as necessary. Terminating action is also introduced."

Required actions include revising the airplane flight manual, inspecting to determine if certain anti-ice piccolo ducts are installed, and replacing or repairing the piccolo duct if necessary.

Restatement of Requirements of AD 2005-17-12

Identification of Affected Piccolo Tubes

(f) Unless already done, for airplanes having S/Ns 7013, 7017, 7037, 7046, 7059, 7076, 7105, 7127, 7151, 7157, 7163, 7174, 7179, 7203, 7204, 7228, 7271, 7347, 7362, 7378, 7417 through 7990 inclusive, 8000 through 8076 inclusive, 8082, 8086, 8090 through 8092 inclusive, 8096 and 8097: Before the airplane accumulates 3,000 total flight hours, or within 14 days after September 7, 2005 (the effective date of AD 2005-17-12, which was superseded by AD 2008-23-16), whichever occurs later, determine whether any affected piccolo tube is installed on the airplane. Affected piccolo tubes are identified in paragraph 1.A. of Bombardier Service Bulletin 601R-30-029, Revision A, dated July 7, 2005. Doing the action required by paragraph (p), (q), (r), (w), or (y) of this AD terminates the requirements of this paragraph.

Revision to Airplane Flight Manual (AFM)

(g) Unless already done, for airplanes with an affected or unidentifiable piccolo tube found during the action required by paragraph (f) of this AD: Before the airplane accumulates 3,000 total flight hours, or within 14 days after September 7, 2005, whichever occurs later, revise the Operating Limitations and Abnormal Procedures sections of the Canadair Regional Jet AFM, CSP A-012, to include the information in Canadair Temporary Revision (TR) RJ/155, dated July 5, 2005, as specified in the TR. This may be done by inserting a copy of the TR into the AFM. This TR introduces new procedures for operation in icing conditions. Operate the airplane according to the limitations and procedures in the TR except as required by paragraph (n) of this AD. When this TR has been included in general revisions of the AFM, the general revisions may be inserted in the AFM, provided the relevant information in the general revision is identical to that in the TR. After the AFM revision required by paragraph (n) of this AD has been done, remove the AFM limitation specified in this paragraph.

Optional Inspections

(h) Unless already done, for airplanes with an affected or unidentifiable piccolo tube found during the action required by paragraph (f) of this AD: The operating limitations and abnormal

procedures specified in Canadair TR RJ/155, dated July 5, 2005, as required by paragraph (g) of this AD, may be removed from the AFM, provided all requirements of this paragraph have been satisfied.

(1) A fluorescent dye penetrant inspection for cracks of the piccolo tubes is done and repeated thereafter within 2,000-flight-hour intervals in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 601R-30-029, Revision A, dated July 7, 2005. An inspection done before September 7, 2005, in accordance with Bombardier Service Bulletin 601R-30-029, dated June 17, 2005, is acceptable for compliance with the requirements of paragraph (h)(1) of this AD. Doing the inspection required by paragraph (u) of this AD terminates the actions required by this paragraph.

(2) All applicable corrective actions are done as specified in paragraph (j) of this AD.

AFM Limitations Required for Exceeding Inspection Interval

(i) Unless already done, for airplanes having S/Ns 7013, 7017, 7037, 7046, 7059, 7076, 7105, 7127, 7151, 7157, 7163, 7174, 7179, 7203, 7204, 7228, 7271, 7347, 7362, 7378, 7417 through 7990 inclusive, 8000 through 8076 inclusive, 8082, 8086, 8090 through 8092 inclusive, 8096 and 8097: During any period in which the inspection interval exceeds 2,000 flight hours after the initial inspection specified in paragraph (h)(1) of this AD, the airplane must be operated under the limitations and abnormal procedures specified in paragraph (g) of this AD. Doing the action required by paragraph (p), (q), (r), (w), or (y) of this AD terminates the requirements of this paragraph.

Corrective Action

(j) Unless already done, if any crack is found during any inspection required by paragraph (h) of this AD: Before further flight, do the actions specified in paragraph (j)(1), (j)(2), (j)(3), (j)(4), or (j)(5) of this AD, except as required by paragraph (k) of this AD.

(1) Replace the cracked piccolo tube, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 601R-30-029, Revision A, dated July 7, 2005, with a new piccolo tube that has the same part number as identified in paragraph 1.A. of Bombardier Service Bulletin 601R-30-029, Revision A, dated July 7, 2005, but that does not have a serial number listed in that paragraph.

(2) Replace the cracked piccolo tube, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 601R-30-029, Revision A, dated July 7, 2005, with a new piccolo tube that has a part number identified in the applicable Bombardier illustrated parts catalog but not identified in paragraph 1.A. of Bombardier Service Bulletin 601R-30-029, Revision A, dated July 7, 2005, or with a new piccolo tube identified in paragraph (l) of this AD.

(3) Replace the cracked piccolo tube, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 601R-30-029, Revision A, dated July 7, 2005, with a piccolo tube that has been inspected in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 601R-30-029, Revision A, dated July 7, 2005, is not cracked, and has not accumulated any air time (hours time-in-service) since inspection.

(4) Replace the cracked piccolo tube with a piccolo tube that has been repaired in accordance with a method approved by either the Manager, New York Aircraft Certification Office (ACO), ANE-172, FAA; or Transport Canada Civil Aviation (TCCA) (or its delegated agent); and has not accumulated any air time (hours time-in-service) since the repair.

(5) Reinstall the cracked piccolo tube and operate the airplane in accordance with a method approved by either the Manager, New York ACO, or TCCA (or its delegated agent).

Note 1: Guidance on operating the airplane under certain conditions in accordance with the provisions of the Master Minimum Equipment List (MMEL) can be found in MMEL Entry 30-12-03.

Exception to Service Bulletin Procedures

(k) Unless already done: Where Bombardier Service Bulletin 601R-30-029, Revision A, dated July 7, 2005, specifies that Bombardier may be contacted for information regarding repair, this AD requires repair according to a method approved by either the Manager, New York ACO, or TCCA (or its delegated agent).

Optional Terminating Action for Paragraphs (f), (g), (h), (i), and (j)

(l) Unless already done, for airplanes having S/Ns 7013, 7017, 7037, 7046, 7059, 7076, 7105, 7127, 7151, 7157, 7163, 7174, 7179, 7203, 7204, 7228, 7271, 7347, 7362, 7378, 7417 through 7990 inclusive, 8000 through 8076 inclusive, 8082, 8086, 8090 through 8092 inclusive, 8096 and 8097: Installation, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 601R-30-029, Revision A, dated July 7, 2005, of a complete set of new inboard, center, and outboard piccolo tubes, as identified in paragraphs (l)(1), (l)(2), and (l)(3) of this AD, terminates the requirements of paragraphs (f), (g), (h), (i), and (j) of this AD. When these piccolo tubes have been installed, remove the Operating Limitations and Abnormal Procedures, if inserted in accordance with paragraph (g) of this AD, from the AFM.

(1) For the inboard piccolo tube: Part numbers (P/N) 601-80032-7 (14432-107) and 601-80032-8 (14432-108).

(2) For the center piccolo tube: P/N 14464-105 and 14464-106.

(3) For the outboard piccolo tube: P/N 14463-109 and 14463-110.

Parts Installation

(m) Unless already done, for airplanes having S/Ns 7013, 7017, 7037, 7046, 7059, 7076, 7105, 7127, 7151, 7157, 7163, 7174, 7179, 7203, 7204, 7228, 7271, 7347, 7362, 7378, 7417 through 7990 inclusive, 8000 through 8076 inclusive, 8082, 8086, 8090 through 8092 inclusive, 8096 and 8097: As of September 7, 2005, no person may install, on any airplane, a piccolo tube having a P/N listed in paragraph 1.A. of Bombardier Service Bulletin 601R-30-029, Revision A, dated July 7, 2005, unless the applicable requirements of paragraphs (f) through (l) of this AD have been accomplished for that piccolo tube before the effective date of this AD or the requirements specified in paragraph (v) of this AD have been accomplished. As of December 1, 2008 (the effective date of AD 2008-23-16), the requirements of paragraph (v) of this AD must be followed.

Restatement of Requirements of AD 2008-23-16

Revision to AFM

(n) Unless already done: For all airplanes, within 14 days after December 1, 2008, revise the Operating Limitations and Abnormal Procedures sections of the Canadair Regional Jet AFM, CSP A-012, to include the information in Canadair (Bombardier) TR RJ/155-6, dated September 17, 2008, as specified in that TR. This may be done by inserting a copy of Canadair (Bombardier) TR RJ/155-6 into the AFM. This TR introduces new procedures for operation in icing conditions. After the AFM revision specified in this paragraph has been done, the AFM limitation required by paragraph (g) of this AD must be removed from the AFM.

Note 2: When Canadair (Bombardier) TR RJ/155-6, dated September 17, 2008, has been included in general revisions of the AFM, the general revisions may be inserted in the AFM, provided the relevant information in the general revision is identical to that in Canadair (Bombardier) TR RJ/155-6.

(o) Unless already done: Before further flight after accomplishing paragraph (n) of this AD, operate the airplane according to the limitations and procedures in Canadair (Bombardier) TR RJ/155-6, dated September 17, 2008, except that MMEL Entry 30-12-03, which permits the wing anti-ice system to be inoperative with specific provisions, is not affected by this AD.

Records Check

(p) Unless already done, for airplanes having S/Ns 7003 through 7013 inclusive, 7015, 7016, 7018 through 7036 inclusive, 7038 through 7045 inclusive, 7047 through 7058 inclusive, 7060 through 7067 inclusive, 7069 through 7075 inclusive, 7077 through 7104 inclusive, 7106 through 7126 inclusive, 7128 through 7150 inclusive, 7152 through 7156 inclusive, 7158 through 7162 inclusive, 7164 through 7178 inclusive, 7180 through 7202 inclusive, 7204 through 7227 inclusive, 7229 through 7270 inclusive, 7272 through 7346 inclusive, 7348 through 7358 inclusive, 7360, 7361, 7363 through 7377 inclusive, 7379, 7380, 7382 through 7416 inclusive, 8056 through 8076 inclusive, 8082, 8086, 8090 through 8092 inclusive, 8096 and 8097: Within 30 days after December 1, 2008, review the airplane maintenance records to determine if any anti-ice piccolo ducts or complete leading edge sections have been replaced since May 1, 2000. Doing the review in this paragraph terminates the requirements of paragraphs (f) and (i) of this AD. Doing the action specified in paragraph (w) or (y) of this AD terminates the requirements of this paragraph.

(1) If no anti-ice piccolo ducts and no complete leading edge sections have been replaced since May 1, 2000, no further action is required by this paragraph.

(2) If any anti-ice piccolo duct or complete leading edge section has been replaced since May 1, 2000, or if it cannot be conclusively determined that no anti-ice piccolo ducts and no complete leading edge sections have been replaced since May 1, 2000, before further flight, inspect the serial numbers of the replaced ducts. A review of airplane maintenance records is acceptable in lieu of this inspection if the serial number of the duct can be conclusively determined from that review.

(i) If none of the piccolo duct serial numbers match any of those in Part A, Paragraph 2.A., of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, no further action is required by this paragraph.

(ii) If any of the piccolo duct serial numbers matches any of those in Part A, Paragraph 2.A., of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, or if the serial number cannot be determined, do the actions required by paragraph (s) of this AD.

(q) Unless already done, for airplanes having S/Ns 7014, 7017, 7037, 7046, 7059, 7076, 7105, 7127, 7151, 7157, 7163, 7179, 7203, 7228, 7271, 7347, 7359, 7362, 7378, 7381, 7417 through 7990 inclusive, and 8000 through 8055 inclusive, on which Bombardier Service Bulletin 601R-30-029 has been accomplished: Within 30 days after December 1, 2008, review the airplane maintenance records to determine if any anti-ice piccolo ducts or complete leading edge sections have been replaced since accomplishing Bombardier Service Bulletin 601R-30-029. Doing the action in this paragraph terminates the requirements of paragraphs (f) and (i) of this AD. Doing the action specified in paragraph (w) or (y) of this AD terminates the requirements of this paragraph.

(1) If no anti-ice piccolo ducts and no complete leading edge sections have been replaced since May 1, 2000, no further action is required by this paragraph.

(2) If any anti-ice piccolo duct or complete leading edge section has been replaced since May 1, 2000, or if it cannot be conclusively determined that no anti-ice piccolo ducts and no complete leading edge sections have been replaced since May 1, 2000, before further flight, inspect the serial numbers of the replaced ducts. A review of airplane maintenance records is acceptable in lieu of this inspection if the serial number of the duct can be conclusively determined from that review.

(i) If none of the piccolo duct serial numbers match any of those in Part A, Paragraph 2.A., of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, no further action is required by this paragraph.

(ii) If any of the piccolo duct serial numbers matches any of those in Part A, Paragraph 2.A., of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, or if the serial number cannot be determined, do the actions required by paragraph (s) of this AD.

(r) Unless already done, for airplanes having S/Ns 7014, 7017, 7037, 7046, 7059, 7076, 7105, 7127, 7151, 7157, 7163, 7179, 7203, 7228, 7271, 7347, 7359, 7362, 7378, 7381, 7417 through 7990 inclusive, and 8000 through 8055 inclusive, on which Bombardier Service Bulletin 601R-30-029 has not been accomplished: Within 30 days after December 1, 2008, inspect the serial numbers of the piccolo ducts. A review of airplane maintenance records is acceptable in lieu of this inspection if the serial number of the duct can be conclusively determined from that review. Doing the inspection in this paragraph terminates the requirements of paragraphs (f) and (i) of this AD. Doing the action specified in paragraph (w) or (y) of this AD terminates the requirements of this paragraph.

(1) If none of the piccolo duct serial numbers match any of those in Part A, Paragraph 2.A., of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, no further action is required by this paragraph.

(2) If any of the piccolo duct serial numbers matches any of those in Part A, Paragraph 2.A., of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, or if the serial number cannot be determined, do the actions required by paragraph (s) of this AD.

Inspection of the Wing Anti-Ice Piccolo Ducts

(s) Unless already done, for airplanes having a piccolo duct identified in paragraph (p)(2)(ii), (q)(2)(ii), or (r)(2) of this AD: Within 30 days after doing the action specified in paragraph (p), (q), or (r) of this AD, as applicable, do a fluorescent dye penetrant inspection for cracking of the piccolo ducts, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008. If no cracking is found, repeat the inspection thereafter at intervals not to exceed 2,000 flight hours. Doing the action specified in paragraph (w) or (y) of this AD terminates the requirements of this paragraph.

(t) Unless already done: If any cracking is found during any inspection required by paragraph (s) of this AD, before further flight, do the actions specified in paragraph (t)(1), (t)(2), or (t)(3) of this AD, except where Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, specifies to contact Bombardier for information regarding repair, this AD requires repair according to a method approved by either the Manager, New York ACO, or TCCA (or its delegated agent). Doing the action specified in paragraph (w) or (y) of this AD terminates the requirements of this paragraph.

(1) Replace the cracked piccolo duct, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, with a new piccolo duct that has the same part number as identified in Part A, Paragraph 2.A., of the Accomplishment

Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, but that does not have a serial number listed in that paragraph. (2) Replace the cracked piccolo duct, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, with a new piccolo duct that has a part number identified in the applicable Bombardier illustrated parts catalog but not identified in Part A, Paragraph 2.A., of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008.

(3) Replace the cracked piccolo duct with a piccolo duct that has been repaired in accordance with a method approved by either the Manager, New York ACO, FAA; or TCCA (or its delegated agent).

Repetitive Inspection of the Wing Anti-Ice Piccolo Ducts

(u) Unless already done, for airplanes on which an inspection required by paragraph (h)(1) of this AD has been done, except for airplanes on which the terminating action specified in paragraph (l) of this AD has been done: Within 2,000 flight hours since the last inspection, or 30 days after December 1, 2008, whichever occurs later, do the actions specified in paragraph (s) of this AD. Doing the inspection required by this paragraph terminates the actions required by paragraph (h)(1) of this AD. Doing the action specified in paragraph (w) or (y) of this AD terminates the requirements of this paragraph.

Parts Installation Paragraph

(v) Unless already done: As of December 1, 2008, the requirements specified in paragraphs (v)(1) and (v)(2) of this AD must be followed.

(1) For airplanes on which the terminating action specified in paragraph (w) of this AD had not been done as of December 1, 2008: No person may install a piccolo duct having a part number identified in Part A, Paragraph 2.A., of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, on any airplane, unless the requirements specified in paragraphs (s) and (t) of this AD, as applicable, have been accomplished for that piccolo duct.

(2) For airplanes on which the terminating action specified in paragraph (w) of this AD had been done as of December 1, 2008: No person may install a piccolo duct having a part number identified in Part A, Paragraph 2.A., of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, on any airplane.

Optional Terminating Action

(w) Replacing all piccolo ducts that have serial numbers identified in Part A, Paragraph 2.A., of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, with piccolo ducts that do not have serial numbers identified in Part A, Paragraph 2.A., of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, terminates the requirements of paragraphs (f), (h), (i), (p), (q), (r), (s), (t), and (u) of this AD.

Optional Service Information for Certain Requirements of This AD

(x) Actions accomplished according to Bombardier Service Bulletin 601R-30-029, Revision B, dated August 29, 2005; or Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008; are considered acceptable for compliance with the corresponding actions specified in paragraphs (h)(1), (j)(1), (j)(2), (j)(3), and (l) of this AD.

New Requirements of This AD: Actions and Compliance

Terminating Action

(y) Unless already done, do the following actions: Within 24 months after the effective date of this AD, replace all piccolo ducts that have serial numbers identified in Part A, Paragraph 2.A., of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, with piccolo ducts that do not have serial numbers identified in Part A, Paragraph 2.A., of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-30-032, dated September 18, 2008. Replacing all the piccolo ducts in accordance with this paragraph terminates the requirements of paragraphs (f), (h), (i), (p), (q), (r), (s), (t), and (u) of this AD.

FAA AD Differences

Note 3: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(z) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO, ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(aa) Refer to MCAI Canadian Airworthiness Directive CF-2008-30, dated October 7, 2008, and the service information identified in Table 1 of this AD, for related information.

Table 1 - Related Service Information

Service Information	Revision Level	Date
Bombardier Alert Service Bulletin A601R-30-032, including Appendix A and Appendix B	Original	September 18, 2008
Bombardier Service Bulletin 601R-30-029, including Appendices A and B, dated June 17, 2005	Original	June 17, 2005
Bombardier Service Bulletin 601R-30-029, including Appendix A, dated June 17, 2005, and Appendix B, Revision A, dated July 7, 2005	A	July 7, 2005
Bombardier Service Bulletin 601R-30-029, including Appendix A, dated June 17, 2005, and Appendix B, Revision A, dated July 7, 2005	B	August 29, 2005
Canadair (Bombardier) Temporary Revision RJ/155-6 to the Canadair Regional Jet Airplane Flight Manual, CSP A-012	Original	September 17, 2008
Canadair Temporary Revision RJ/155 to the Canadair Regional Jet Airplane Flight Manual, CSP A-012	Original	July 5, 2005

Material Incorporated by Reference

(bb) You must use the service information contained in Table 2 of this AD, as applicable, to do the actions required by this AD, unless the AD specifies otherwise. If you accomplish the optional actions specified by this AD, you must use the service information contained in Table 3 of this AD, as applicable, unless the AD specifies otherwise.

Table 2 – Material Incorporated by Reference for Required Actions

Service Information	Revision Level	Date
Bombardier Alert Service Bulletin A601R-30-032, including Appendix A and Appendix B	Original	September 18, 2008
Bombardier Service Bulletin 601R-30-029, including Appendix A, dated June 17, 2005, and Appendix B, Revision A, dated July 7, 2005	A	July 7, 2005

Canadair (Bombardier) Temporary Revision RJ/155-6 to the Canadair Regional Jet Airplane Flight Manual, CSP A-012	Original	September 17, 2008
Canadair Temporary Revision RJ/155 to the Canadair Regional Jet Airplane Flight Manual, CSP A-012	Original	July 5, 2005

Table 3 – Material Incorporated by Reference for Optional Actions

Service Information	Revision Level	Date
Bombardier Alert Service Bulletin A601R-30-032, including Appendix A and Appendix B	Original	September 18, 2008
Bombardier Service Bulletin 601R-30-029, including Appendices A and B, dated June 17, 2005	Original	June 17, 2005
Bombardier Service Bulletin 601R-30-029, including Appendix A, dated June 17, 2005, and Appendix B, Revision A, dated July 7, 2005	A	July 7, 2005
Bombardier Service Bulletin 601R-30-029, including Appendix A, dated June 17, 2005, and Appendix B, Revision A, dated July 7, 2005	B	August 29, 2005

(1) The Director of the Federal Register approved Bombardier Service Bulletin 601R-30-029, dated June 17, 2005, including Appendices A and B, dated June 17, 2005; and Bombardier Service Bulletin 601R-30-029, Revision B, dated August 29, 2005, including Appendix A, dated June 17, 2005, and Appendix B, Revision A, dated July 7, 2005; under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) On December 1, 2008 (73 FR 67363, November 14, 2008), the Director of the Federal Register previously approved the incorporation by reference of Bombardier Alert Service Bulletin A601R-30-032, including Appendix A and Appendix B, dated September 18, 2008; and Canadair (Bombardier) Temporary Revision RJ/155-6, dated September 17, 2008, to the Canadair Regional Jet Airplane Flight Manual, CSP A-012.

(3) On September 7, 2005 (70 FR 49164, August 23, 2005), the Director of the Federal Register previously approved the incorporation by reference of Canadair Temporary Revision RJ/155, dated July 5, 2005, to the Canadair Regional Jet Airplane Flight Manual, CSP A-012; and Bombardier Service Bulletin 601R-30-029, Revision A, dated July 7, 2005, including Appendix A, dated June 17, 2005, and Appendix B, Revision A, dated July 7, 2005.

(4) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; e-mail thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(5) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(6) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this

material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on October 19, 2009.
Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



CORRECTION: [*Federal Register: March 3, 2010 (Volume 75, Number 41); Page 9515;*
www.access.gpo.gov/su_docs/aces/aces140.html]

2010-04-09 Airbus: Amendment 39-16202. Docket No. FAA-2009-1107; Directorate Identifier 2009-NM-138-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective March 30, 2010.

Affected ADs

(b) None.

Applicability

(c) This AD applies to the airplanes identified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category; on which Airbus Modification 49520 has been embodied in production, or on which Airbus Service Bulletin A330-21-3096, Revision 01, or Airbus Service Bulletin A340-21-4107, Revision 01, has been embodied in service; except those airplanes on which Airbus Modification 58551 has been embodied in production.

(1) Airbus Model A330-201, -202, -203, -223, and -243 airplanes, all manufacturer serial numbers.

(2) Airbus Model A340-211, -212, and -213 airplanes; and Model A340-311, -312, and -313 airplanes; all manufacturer serial numbers.

Subject

(d) Air Transport Association (ATA) of America Code 21: Air conditioning.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

* * * * *

* * * EASA [European Aviation Safety Agency] AD 2006-0191 [which corresponds to FAA AD 2006-21-08] required the installation of new heat shield panels with drainage over the air conditioning packs in order to avoid an undetected fire in this zone following a fuel leak from the centre tank.

These new heat shield panels have holes. In case of fuel leaking through these holes from the centre tank, any fuel vapour may develop into a potential source of ignition, possibly resulting in a fuel tank explosion and consequent loss of

the aeroplane. Airbus has developed a repair solution for these holes to prevent a fuel vapour ignition source in this area and improve the protection of the hot air equipment.

[T]his AD requires the installation of plugs on the heat shield panels of the Left Hand (LH) and Right Hand (RH) Air Conditioning packs.

Actions and Compliance

(f) Unless already done, within 24 months after the effective date of this AD: Plug the six receptacle holes on the heat shield of the left-hand air conditioning pack and plug the four receptacle holes on the heat shield of the right-hand air conditioning pack, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A330-21-3148, dated January 30, 2009 (for Model A330-201, -202, -203, -223, and -243 airplanes); or Airbus Mandatory Service Bulletin A340-21-4147, dated January 30, 2009 (for Model A340-211, -212, and -213 airplanes; and Model A340-311, -312, and -313 airplanes); as applicable.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1138; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI EASA Airworthiness Directive 2009-0150, dated July 9, 2009; Airbus Mandatory Service Bulletin A330-21-3148, dated January 30, 2009; and Airbus Mandatory Service Bulletin A340-21-4147, dated January 30, 2009; for related information.

Material Incorporated by Reference

(i) You must use Airbus Mandatory Service Bulletin A330-21-3148, including Appendix 1, dated January 30, 2009; or Airbus Mandatory Service Bulletin A340-21-4147, including Appendix 1, dated January 30, 2009; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus SAS–Airworthiness Office–EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80, e-mail airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on February 5, 2010.

Stephen P. Boyd,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2010-04-12 Bombardier, Inc.: Amendment 39-16205. Docket No. FAA-2009-0712; Directorate Identifier 2007-NM-152-AD.

Effective Date

(a) This airworthiness directive (AD) is effective April 8, 2010.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Bombardier, Inc. Model DHC-8-101, DHC-8-102, DHC-8-103, DHC-8-106, DHC-8-201, DHC-8-202, DHC-8-301, DHC-8-311, and DHC-8-315 airplanes, certificated in any category; serial numbers 003 and subsequent.

Subject

(d) Air Transport Association (ATA) of America Codes 32: Landing Gear, 51: Standard Practices/Structures; 52: Doors; 53: Fuselage; 54: Nacelles/Pylons; 55: Stabilizers; and 57: Wings.

Unsafe Condition

(e) This AD results from the determination that, as airplanes age, they are more likely to exhibit indications of corrosion. We are issuing this AD to prevent structural failure of the airplane due to corrosion.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Manual References

(g) This AD refers to the manuals listed in Table 1 of this AD.

Table 1 – Applicable manuals

Bombardier Model	Manual
(1) DHC-8-101, -102, -103, and -106 airplanes	Part 1, Section 3, Structural Inspection Program, of the Bombardier de Havilland Dash 8 Maintenance Program Maintenance Review Board Report Dash 8 Series 100 Program Support Manual (PSM) 1-8-7, Revision 22, dated November 1, 2008.
(2) DHC-8-201 and DHC-8-202 airplanes	Part 1, Section 3, Structural Inspection Program, of the Bombardier de Havilland Dash 8 Maintenance Program Maintenance Review Board Report Dash 8 Series 200 PSM 1-82-7, Revision 13, dated November 1, 2008.
(3) Model DHC-8-301, DHC-8-311, and DHC-8-315 airplanes	Part 1, Section 3, Structural Inspection Program, of the Bombardier de Havilland Dash 8 Maintenance Program Maintenance Review Board Report Dash 8 Series 300, PSM 1-83-7, Revision 22, dated November 1, 2008.

Inspections

(h) At the later of the times specified in paragraphs (h)(1) and (h)(2) of this AD, do each of the Environmental Damage/Corrosion Protection and Control Program (ED/CPCP) inspections identified with both "ED" and "CPCP," or with only "ED," including re-protection tasks, as applicable, which are found in the "Type of Damage" column of the applicable manual found in Table 1 of this AD, in accordance with the applicable manual identified in Table 1 of this AD. Except as provided by paragraph (i) of this AD, repeat each task thereafter at intervals not to exceed the compliance time specified in the "Repeat" column of the applicable manual identified in Table 1 of this AD.

(1) Within 24 months after the effective date of this AD.

(2) At the compliance time specified in the "Threshold" column of the applicable manual identified in Table 1 of this AD since the date of issuance of the original Canadian airworthiness certificate or the date of issuance of the original Canadian export certificate of airworthiness. If there is no value in the "Threshold" column, use the time specified in the "Repeat" column.

(i) After accomplishment of each initial ED/CPCP and ED task required by paragraph (h) of this AD, the FAA may approve the incorporation into the operator's approved maintenance/inspection program of the CPCP specified in the applicable manual identified in Table 1 of this AD; or the equivalent program that is approved in accordance with this AD. In all cases, the initial corrosion task for each airplane area must be completed by the initial compliance time specified in paragraph (h) of this AD.

(1) Any operator complying with paragraph (i) of this AD may use an alternative recordkeeping method to that otherwise required by section 91.417 ("Maintenance records") or section 121.380 ("Maintenance recording requirements") of the Federal Aviation Regulations (14 CFR 91.417 or 14 CFR 121.380, respectively) for the actions required by this AD, provided that the recordkeeping method is approved by the FAA and is included in a revision to the maintenance/inspection program. For the purposes of this paragraph, "the FAA" is defined as the cognizant Principal Maintenance Inspector (PMI) for operators that are assigned a PMI (i.e., part 121, 125, and 135 operators), and the cognizant Flight Standards District Office for other operators (i.e., part 91 operators).

(2) After the initial accomplishment of the ED/CPCP and ED tasks required by paragraph (h) of this AD, any extension of the repetitive intervals specified in the manual must be approved by the Manager, New York Aircraft Certification Office (ACO), FAA.

Corrective Actions

(j) If any corrosion is found during accomplishment of any action required by paragraph (h) of this AD: Before further flight, rework, repair, or replace, as applicable, in accordance with a method approved by either the Manager, New York ACO, FAA; or Transport Canada Civil Aviation (TCCA) (or its delegated agent).

Reporting Requirements for Level 3 Corrosion Findings

(k) If any Level 3 corrosion, as defined in Part 1 of the Bombardier (de Havilland) DHC-6 Twin Otter, Dash 7 & Dash 8 Corrosion Prevention and Control Manual, PSM 1-GEN-5, Revision 3, dated November 30, 1998, is found during the accomplishment of any action required by this AD, do paragraphs (k)(1), (k)(2), and (k)(3) of this AD. Under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

(1) Within 3 days after the finding of Level 3 corrosion, report findings to the Manager, New York ACO, FAA, in accordance with the Bombardier (de Havilland) DHC-6 Twin Otter, Dash 7 & Dash 8 Corrosion Prevention and Control Manual, PSM 1-GEN-5, Revision 3, dated November 30, 1998.

(2) Within 10 days after the finding of Level 3 corrosion, either submit a plan to the FAA to identify a schedule for accomplishing the applicable CPCP task on the remainder of the airplanes in the operator's fleet that are subject to this AD, or provide data substantiating that the Level 3 corrosion that was found is an isolated case. The FAA may impose a schedule other than that proposed in the plan upon finding that a change to the schedule is needed to ensure that any other Level 3 corrosion is detected in a timely manner. For the purposes of this paragraph, "the FAA" is defined as the cognizant Principal Maintenance Inspector (PMI) for operators that are assigned a PMI (i.e., part 121, 125, and 135 operators), and the cognizant Flight Standards District Office for other operators (i.e., part 91 operators).

(3) Within the time schedule approved in accordance with paragraph (k)(2) of this AD, accomplish the applicable task on the remainder of the airplanes in the operator's fleet that are subject to this AD.

Limiting Future Corrosion Findings

(l) If corrosion findings that exceed Level 1 are found in any area during any repeat of any CPCP task after the initial accomplishment required by paragraph (h) of this AD: Within 60 days after such finding, implement a means approved by the FAA to reduce future findings of corrosion in that area to Level 1 or better. For the purposes of this paragraph, "the FAA" is defined as the cognizant PMI for operators that are assigned a PMI (i.e., part 121, 125, and 135 operators), and the cognizant Flight Standards District Office for other operators (i.e., part 91 operators).

Scheduling Corrosion Tasks for Transferred Airplanes

(m) Before any airplane subject to this AD is transferred and placed into service by an operator: Establish a schedule for accomplishing the CPCP tasks required by this AD in accordance with paragraph (m)(1) or (m)(2) of this AD, as applicable.

(1) For airplanes on which the CPCP tasks required by this AD have been accomplished previously at the schedule established by this AD: Perform the first CPCP task in each area in accordance with the previous operator's schedule, or in accordance with the new operator's schedule, whichever results in an earlier accomplishment of that CPCP task. After the initial accomplishment of each CPCP

task in each area as required by this paragraph, repeat each CPCP task in accordance with the new operator's schedule.

(2) For airplanes on which the CPCP tasks required by this AD have not been accomplished previously, or have not been accomplished at the schedule established by this AD: The new operator must perform each initial CPCP task in each area before further flight or in accordance with a schedule approved by the FAA. For the purposes of this paragraph, "the FAA" is defined as the cognizant Principal Maintenance Inspector (PMI) for operators that are assigned a PMI (i.e., part 121, 125, and 135 operators), and the cognizant Flight Standards District Office for other operators (i.e., part 91 operators).

Alternative Methods of Compliance (AMOCs)

(n)(1) The Manager, New York ACO, ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone 516-228-7300; fax 516-794-5531.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

Related Information

(o) Canadian airworthiness directive CF-2007-06, dated April 10, 2007, also addresses the subject of this AD.

Material Incorporated by Reference

(p) You must use the service information contained in Table 2 of this AD, as applicable, to do the actions required by this AD, unless the AD specifies otherwise.

Table 2 – Material incorporated by reference

Document	Revision	Date
Part 1, Section 3, Structural Inspection Program, of the Bombardier de Havilland Dash 8 Maintenance Program Maintenance Review Board Report Dash 8 Series 100 Program Support Manual (PSM) 1-8-7	22	November 1, 2008
Part 1, Section 3, Structural Inspection Program, of the Bombardier de Havilland Dash 8 Maintenance Program Maintenance Review Board Report Series 200 PSM 1-82-7	13	November 1, 2008

Part 1, Section 3, Structural Inspection Program, of the Bombardier de Havilland Dash 8 Maintenance Program Maintenance Review Board Report Dash 8 Series 300, PSM 1-83-7	22	November 1, 2008
Bombardier (de Havilland) DHC-6 Twin Otter, Dash 7 & Dash 8 Corrosion Prevention and Control Manual, PSM 1-GEN-5	3	November 30, 1998

Bombardier de Havilland Dash 8 Maintenance Program Maintenance Review Board Report Dash 8 Series 100 PSM 1-8-7, Revision 22, dated November 1, 2008, contains the following effective pages:

List of Effective Pages:

Page Title/ Description	Page Number(s)	Revision Number	Date Shown on Page(s)
Title Page	None shown	22	November 1, 2008
List of Effective Pages	1-4	None shown*	November 1, 2008
Log of Revisions	1-18	None shown*	November 1, 2008
Record of Revisions	1-2	22	November 1, 2008
Contents	1-4	None shown*	November 1, 2008
Section 3			
Subject 3-0	1-4	None shown*	November 1, 2008
Subject 3-32	1-2	None shown*	November 1, 2008
Subject 3-52	1-2	None shown*	November 1, 2008
Subject 3-53	1-16	None shown*	November 1, 2008
Subject 3-54	1-4	None shown*	November 1, 2008
Subject 3-55	1-8	None shown*	November 1, 2008
Subject 3-57	1-12	None shown*	November 1, 2008

Bombardier de Havilland Dash 8 Maintenance Program Maintenance Review Board Report Dash 8 Series 200 PSM 1-82-7, Revision 13, dated November 1, 2008, contains the following effective pages:

List of Effective Pages:

Page Title/ Description	Page Number(s)	Revision Number	Date Shown on Page(s)
Title Page	None shown	13	November 1, 2008
List of Effective Pages	1-4	None shown*	November 1, 2008
Log of Revisions	1-8	None shown*	November 1, 2008
Record of Revisions	1-2	13	November 1, 2008
Contents	1-4	None shown*	November 1, 2008
Section 3			
Subject 3-0	1-4	None shown*	November 1, 2008
Subject 3-32	1-2	None shown*	November 1, 2008
Subject 3-52	1-2	None shown*	November 1, 2008
Subject 3-53	1-16	None shown*	November 1, 2008
Subject 3-54	1-4	None shown*	November 1, 2008
Subject 3-55	1-6	None shown*	November 1, 2008
Subject 3-57	1-12	None shown*	November 1, 2008

Bombardier de Havilland Dash 8 Maintenance Program Maintenance Review Board Report Dash 8 Series 300 PSM 1-83-7, Revision 22, dated November 1, 2008, contains the following effective pages:

List of Effective Pages:

Page Title/ Description	Page Number(s)	Revision Number	Date Shown on Page(s)
Title Page	None shown	22	November 1, 2008
List of Effective Pages	1-4	None shown*	November 1, 2008
Log of Revisions	1-18	None shown*	November 1, 2008
Record of Revisions	1-2	22	November 1, 2008
Contents	1-4	None shown*	November 1, 2008
Section 3			
Subject 3-0	1-4	None shown*	November 1, 2008
Subject 3-32	1-2	None shown*	November 1, 2008
Subject 3-52	1-2	None shown*	November 1, 2008
Subject 3-53	1-18	None shown*	November 1, 2008

Subject 3-54	1-4	None shown*	November 1, 2008
Subject 3-55	1-8	None shown*	November 1, 2008
Subject 3-57	1-12	None shown*	November 1, 2008

(*Only the title page and Record of Revisions of these documents specify the revision level of these documents.)

Bombardier (de Havilland) DHC-6 Twin Otter, Dash 7 & Dash 8 Corrosion Prevention and Control Manual PSM 1-GEN-5, Part 1, Revision 3, dated November 30, 1998, contains the following effective pages:

List of Effective Pages:

Page title/ description	Page number(s)	Revision number	Date shown on page(s)
Title Page	None shown	None shown*	November 8, 1993.
Record of Revisions	1	3	August 27, 1991.
	2	None shown*	August 27, 1991.
Part 1 List of Effective Pages	1-2	None shown*	November 30, 1998.
Part 1 Table of Contents	1-4	None shown*	November 8, 1993.
Part 1 List of Illustrations	1-2	None shown*	November 8, 1993.
Part 1 List of Tables	1	None shown*	November 8, 1993.
	2	None shown*	August 27, 1991.
Introduction	1-2	None shown*	November 8, 1993.
	3-4	None shown*	November 5, 1992.
Chapter 1	1-1 through 1-10	None shown*	November 8, 1993.
Chapter 2	2-1 through 2-6	None shown*	November 8, 1993.
Chapter 3	3-1 through 3-4	None shown*	November 8, 1993.
Chapter 4	4-1 through 4-44	None shown*	November 8, 1993.
Chapter 5	5-1 through 5-48	None shown*	November 8, 1993.
Chapter 6	6-1 through 6-8, 6-11 through 6-16	None shown*	August 27, 1991.
	6-9	None shown*	November 8, 1993.
	6-10	None shown*	November 5, 1992.
Chapter 7	7-1 through 7-2	None shown*	November 8, 1993.
Chapter 8	8-1 through 8-4	None shown*	November 8, 1993.
Chapter 9	9-1 through 9-4	None shown*	November 30, 1998.

(*Only page 1 of the Record of Revisions of Bombardier (de Havilland) DHC-6 Twin Otter, Dash 7 & Dash 8 Corrosion Prevention and Control Manual PSM 1-GEN- 5, Part 1, Revision 3, contains the revision level of this document.)

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; e-mail thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on February 11, 2010.

Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2010-05-03 The Boeing Company: Amendment 39-16212. Docket No. FAA-2009-0718; Directorate Identifier 2009-NM-025-AD.

Effective Date

(a) This airworthiness directive (AD) is effective April 8, 2010.

Affected ADs

(b) None.

Applicability

(c) This AD applies to all The Boeing Company Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series airplanes, certificated in any category.

Subject

(d) Air Transport Association (ATA) of America Code 51: Standard practices/structures.

Unsafe Condition

(e) This AD results from a Boeing analysis indicating that the wing and horizontal stabilizer side-of-body joints, and the fuselage skin circumferential splices, are susceptible to fatigue cracking due to high cyclic loads on the airplane. The Federal Aviation Administration is issuing this AD to detect and correct fatigue cracking at multiple adjacent locations in the subject areas, which could connect to form large cracks and result in reduced structural integrity leading to rapid decompression and consequent loss of control of the airplane.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspections and Repair if Necessary

(g) Except as provided by paragraphs (h) and (i) of this AD: At the applicable times specified in paragraph 1.E. of Boeing Alert Service Bulletin 747-51A2060, dated October 30, 2008, do one-time inspections for cracks in the wing and horizontal stabilizer side-of-body joints, and the fuselage skin

circumferential splices; do detailed inspections, as applicable, for cracks of the fuselage skin circumferential splices; and do all applicable repairs before further flight, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-51A2060, dated October 30, 2008, except as provided by paragraphs (j) and (k) of this AD. As applicable, repeat the detailed inspection for cracks of the fuselage skin circumferential splices, at the applicable times specified in paragraph 1.E. of Boeing Alert Service Bulletin 747-51A2060, dated October 30, 2008.

Note 1: The inspection specified in Sheet 6 of Figure 31 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-51A2060, dated October 30, 2008, is an external detailed inspection of the fuselage skin as specified in Step 3 of Figure 31, not an inspection of the fuselage stringer.

Exceptions to Compliance Times

(h) Where Boeing Alert Service Bulletin 747-51A2060, dated October 30, 2008, specifies a compliance time after "* * * the date on this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(i) Where Note (a) of Table 2 of paragraph 1.E. of Boeing Alert Service Bulletin 747-51A2060, dated October 30, 2008, specifies that if a certain modification was done then certain inspections may be deferred "until the post modification inspection period as given in Service Bulletin 747-57A2314," this AD allows, for airplanes on which the modification specified in Boeing Service Bulletin 747-57A2314 has been done, deferring the inspections specified in Part 2 of paragraph 3.B., Work Instructions, of Boeing Alert Service Bulletin 747-51A2060, dated October 30, 2008, until the applicable post-modification inspection compliance times required by paragraph (e) of AD 2004-03-09, amendment 39-13453.

Exception to Part 4 Actions

(j) For Group 6 airplanes identified in Boeing Alert Service Bulletin 747-51A2060, dated October 30, 2008: Do the inspections specified in Part 4 of paragraph 3.B., Work Instructions, of Boeing Alert Service Bulletin 747-51A2060, dated October 30, 2008, in accordance with the procedures specified in paragraph (m) of this AD.

Exception to Corrective Actions

(k) If any crack is found during any inspection required by this AD, and Boeing Alert Service Bulletin 747-51A2060, dated October 30, 2008, specifies to contact Boeing for appropriate action: Before further flight, repair using a method approved in accordance with the procedures specified in paragraph (m) of this AD.

Reporting Requirement

(l) At the applicable time specified in paragraph (l)(1) or (l)(2) of this AD, submit a report of positive findings of cracks found during the inspection required by paragraph (g) of this AD to Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Alternatively, operators may submit reports to their Boeing field service representatives. The report must contain, as a minimum, the following information: airplane serial number, flight cycles at time of discovery, location(s) and extent of positive crack findings. Under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the

information collection requirements contained in this AD and has assigned OMB Control Number 2120-0056. (1) If the inspection was done on or before the effective date of this AD: Send the report within 30 days after the effective date of this AD.

(2) If the inspection was done after the effective date of this AD: Send the report within 30 days after the inspection is done.

Alternative Methods of Compliance (AMOCs)

(m)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Ivan Li, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle ACO, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6437; fax (425) 917-6590; Or, e-mail information to 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Material Incorporated by Reference

(n) You must use Boeing Alert Service Bulletin 747-51A2060, dated October 30, 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on February 11, 2010.

Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2010-05-09 Dowty Propellers: Amendment 39-16219. Docket No. FAA-2008-0545; Directorate Identifier 2008-NE-16-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective April 7, 2010.

Affected ADs

- (b) None.

(c) This AD applies to Dowty Propellers Models R354/4-123-F/13, R354/4-123-F/20, R375/4-123-F/21, R389/4-123-F/25, R389/4-123-F/26, and R390/4-123-F/27 propellers. These propellers are installed on, but not limited to, Saab AB, Saab Aerosystems SF340A and SAAB SF340B airplanes.

Reason

(d) European Aviation Safety Agency (EASA) AD No. 2008-0033, dated February 19, 2008, states:

A number of propeller blade outer sleeves have been found with cracks since 1996. Testing has shown that blade retention integrity is not affected by this cracking. However, this condition, if not detected and corrected, can lead to blade counterweight release, possibly resulting in damage to the aircraft and injury to occupants or persons on the ground.

This AD requires initial and repetitive visual inspections of propeller blade root outer sleeves for cracks, and removal before further flight of propeller blades with cracked blade root outer sleeves. We are issuing this AD to prevent blade counterweight release, which could result in injury or damage to the airplane.

Actions and Compliance

- (e) Unless already done, do the following actions.

Propeller Blade Root Outer Sleeve Visual Inspections

(1) At the next 1,600 flight hours (FH) aircraft check after the effective date of this AD, or, after any blade accumulates 15,000 FH time-in-service, whichever occurs later, visually inspect all propeller blade root outer sleeves for cracks.

(2) Thereafter, at intervals not to exceed 1,600 FH, visually inspect all propeller blade root outer sleeves for cracks.

(3) Before further flight, remove any propeller blades found with cracked root outer sleeves during the visual inspections in paragraphs (e)(1) and (e)(2) of this AD.

FAA AD Differences

(f) None.

Alternative Methods of Compliance (AMOCs)

(g) The Manager, Boston Aircraft Certification Office, FAA, Engine and Propeller Directorate, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

Related Information

(h) Refer to European Aviation Safety Agency AD 2008-0033, dated February 19, 2008, and Dowty Propellers Alert Service Bulletin No. SF340-61-A106, Revision 1, dated March 20, 2008, for related information.

(i) Contact Terry Fahr, Aerospace Engineer, Boston Aircraft Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: terry.fahr@faa.gov; telephone (781) 238-7155; fax (781) 238-7170, for more information about this AD.

Material Incorporated by Reference

(j) None.

Issued in Burlington, Massachusetts, on February 23, 2010.
Francis A. Favara,
Manager, Engine and Propeller Directorate,
Aircraft Certification Service.



2010-05-11 The Boeing Company: Amendment 39-16221. Docket No. FAA-2008-0376; Directorate Identifier 2007-NM-322-AD.

Effective Date

(a) This airworthiness directive (AD) is effective April 13, 2010.

Affected ADs

(b) None.

Applicability

(c) This AD applies to The Boeing Company Model 747-100, 747-200B, 747-300, and 747SR series airplanes, certificated in any category; as identified in Boeing Service Bulletin 747-25A3368, Revision 2, dated June 12, 2008.

Note 1: The affected airplanes are those that have been converted by Boeing to the Boeing Special Freighter configuration.

Subject

(d) Air Transport Association (ATA) of America Code 25: Equipment/furnishings.

Unsafe Condition

(e) This AD results from a report of water contamination in the electrical and electronic units in the main equipment center. We are issuing this AD to prevent the malfunction of one or more electrical and electronic units in the main equipment center, which could adversely affect the airplane's continued safe flight.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Install the Closeout Panel and Moisture Curtains

(g) Within 24 months after the effective date of this AD, install the closeout panel and moisture curtains for the main equipment center, by accomplishing all of the applicable actions specified in the Accomplishment Instructions of Boeing Service Bulletin 747-25A3368, Revision 2, dated June 12, 2008.

Credit for Actions Done According to Previous Issue of the Service Bulletin

(h) Actions done before the effective date of this AD in accordance with the Accomplishment Instructions in Boeing Alert Service Bulletin 747-25A3368, dated August 25, 2005, are acceptable for compliance with the corresponding actions required by paragraph (g) of this AD, provided that the additional work specified in the Accomplishment Instructions of Boeing Alert Service Bulletin 747-25A3368, Revision 1, dated June 25, 2007; or Revision 2, dated June 12, 2008; is accomplished. The additional work required is to cap seal all rivets fastening the mounting base assembly to the moisture shroud as given in Figure 10 in Boeing Alert Service Bulletin 747-25A3368, Revision 2, dated June 12, 2008, and to fill any unused pilot holes in the mounting base assembly in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-25A3368, Revision 2, dated June 12, 2008; or cap seal all rivets fastening the mounting base assembly to the moisture shroud as given in Figure 10 of Boeing Alert Service Bulletin 747-25A3368, Revision 1, dated June 25, 2007, and to fill any unused pilot holes in the mounting base assembly in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-25A3368, Revision 1, dated June 25, 2007.

(i) Actions done before the effective date of this AD in accordance with Boeing Alert Service Bulletin 747-25A3368, Revision 1, dated June 25, 2007, are acceptable for compliance with the corresponding actions required by paragraph (g) of this AD.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Marcia Smith, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 917-6484; fax (425) 917-6590. Or, e-mail information to 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

Material Incorporated by Reference

(k) You must use Boeing Service Bulletin 747-25A3368, Revision 2, dated June 12, 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on February 25, 2010.

Jeffrey E. Duven,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2010-05-12 Bombardier, Inc. (Formerly de Havilland, Inc.): Amendment 39-16222. Docket No. FAA-2009-0609; Directorate Identifier 2009-NM-037-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective April 13, 2010.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to Bombardier Model DHC-8-102, DHC-8-103, DHC-8-106, DHC-8-201, and DHC-8-202 series airplanes; certificated in any category; serial numbers 003 through 663 inclusive.

Subject

- (d) Air Transport Association (ATA) of America Code 57: Wings.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

During a puncture voltage test of the aluminum-loaded paint on an in-service DHC-8 aircraft, conducted to validate an SFAR 88 [Special Federal Aviation Regulation No. 88] related task, Bombardier Aerospace (BA) discovered that the top wing fuel tank skin between Yw171.20 and Yw261.00 was painted with a non-aluminized enamel coating due to a misinterpretation of the painting instructions in the Structural Repair Manual (SRM).

With this type of paint application, it is possible that, in the worst case scenario, a lightning strike could puncture the wing skin and create an ignition source in the fuel tank.

Ignition sources inside fuel tanks, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane. Required actions include performing a functional check of the dielectric properties of the fuel tank skin for aluminum-loaded primer and aluminum-loaded enamel coating. For airplanes on which the aluminum-loaded primer and aluminum-loaded

enamel coating have been properly applied, the required actions include restoring the protective finish on the areas where the surface finish was removed. For airplanes on which the aluminum-loaded primer and aluminum-loaded enamel coating have not been applied or have not been properly applied, the required actions include stripping the affected wing skin surfaces to bare metal and applying alodine coating to those areas, performing a detailed visual inspection of the stripped areas for any sign of corrosion or deterioration of the protective alodine coating and re-applying the protective alodine coating, and painting the affected wing skin surfaces with aluminum-loaded primer and aluminum-loaded enamel coating.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) For airplanes on which Bombardier Modification 8/0024 has not been done: Within 18 months after the effective date of this AD, perform a functional check of the dielectric properties of the fuel tank skin between Yw171.20 and Yw261.00 of the upper and lower wing for aluminum-loaded primer and aluminum-loaded enamel coating, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-57-46, Revision A, dated February 6, 2009.

(2) For airplanes on which Bombardier Modification 8/0024 has been done: Within 18 months after the effective date of this AD, perform a functional check of the dielectric properties of the fuel tank skin between Yw171.20 and Yw261.00 of the upper wing for aluminum-loaded primer and aluminum-loaded enamel coating, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-57-46, Revision A, dated February 6, 2009.

(3) If the functional check required by paragraph (f)(1) or (f)(2) of this AD indicates that the aluminum-loaded primer and aluminum-loaded enamel coating have been properly applied, as defined in the Accomplishment Instructions of Bombardier Service Bulletin 8-57-46, Revision A, dated February 6, 2009: Before further flight, restore the protective finish on the areas where the surface finish was removed for the functional check, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-57-46, Revision A, dated February 6, 2009.

(4) If the functional check required by paragraph (f)(1) or (f)(2) of this AD indicates that the aluminum-loaded primer and aluminum-loaded enamel coating have not been applied or have not been properly applied, as defined in the Accomplishment Instructions of Bombardier Service Bulletin 8-57-46, Revision A, dated February 6, 2009: Perform the actions required by paragraphs (f)(4)(i), (f)(4)(ii), and (f)(4)(iii) of this AD, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-57-46, Revision A, dated February 6, 2009.

(i) Before further flight, strip the affected wing skin surfaces to bare metal and apply alodine coating to those areas, in accordance with Bombardier Service Bulletin 8-57-46, Revision A, dated February 6, 2009.

(ii) Within 90 flight hours after performing the actions required by paragraph (f)(4)(i) of this AD, and thereafter at intervals not to exceed 90 flight hours: Perform a detailed visual inspection of the stripped areas for any sign of corrosion or deterioration of the protective alodine coating, and re-apply the protective alodine coating, in accordance with Bombardier Service Bulletin 8-57-46, Revision A, dated February 6, 2009.

(iii) Within 3 months after performing the actions required by paragraph (f)(1) or (f)(2) of this AD, as applicable: Paint the affected wing skin surfaces with aluminum-loaded primer and aluminum-loaded enamel coating, in accordance with Bombardier Service Bulletin 8-57-46, Revision A, dated February 6, 2009.

(5) Accomplishment of the actions required by paragraph (f)(1) or (f)(2) of this AD, as applicable, before the effective date of this AD, in accordance with Bombardier Service Bulletin 8-57-46, dated September 29, 2008, is acceptable for compliance with the corresponding requirements of this AD.

(6) Accomplishment of the actions required by paragraph (f)(1) or (f)(2) of this AD, as applicable, in accordance with AD 2008-13-09, Amendment 39-15572, is acceptable for compliance with the corresponding requirements of this AD, provided the actions are done within the applicable compliance times specified in this AD.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office, ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to Canadian Airworthiness Directive CF-2009-05, dated January 29, 2009; and Bombardier Service Bulletin 8-57-46, Revision A, dated February 6, 2009; for related information.

Material Incorporated by Reference

(i) You must use Bombardier Service Bulletin 8-57-46, Revision A, dated February 6, 2009, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; e-mail thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on February 24, 2010.
Jeffrey E. Duven,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

CORRECTED: In the Federal Register, this AD had a typo in the second row, sixth column of table "Estimated Costs Required by AD 2006-07-12." This copy has been corrected. The Federal Register will issue a correction.

2010-05-13 The Boeing Company: Amendment 39-16223. Docket No. FAA-2009-0452; Directorate Identifier 2007-NM-326-AD.

Effective Date

(a) This AD becomes effective April 13, 2010.

Affected ADs

(b) This AD supersedes AD 2006-07-12, Amendment 39-14539.

Applicability

(c) This AD applies to all The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, certificated in any category.

Subject

(d) Air Transport Association (ATA) of America Code 53: Fuselage.

Unsafe Condition

(e) This AD results from reports of fuselage skin cracks adjacent to the skin lap joints on airplanes that had scribe lines. Scribe line damage can also occur at many other locations, including butt joints, external doublers, door scuff plates, the wing-to-body fairing, and areas of the fuselage where decals have been applied or removed. We are issuing this AD to prevent rapid decompression of the airplane due to fatigue cracks resulting from scribe lines on pressurized fuselage structure.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of Requirements of AD 2006-07-12

Inspection

(g) Do a detailed inspection for scribe lines and cracks in the fuselage skin at certain lap joints, butt joints, external repair doublers, and other areas, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004, except as provided by paragraphs (h), (k), (l), (m), (n), and (o) of this AD. Except as required by paragraph (q) of this AD, do the actions at the time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004, except as required by paragraph (j) of this AD. Acceptable inspection exemptions are described in paragraph 1.E.1. of Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004.

(1) If no scribe line is found, no further work is required by this paragraph.

(2) If any scribe line is found: Do all applicable investigative and corrective actions at the time specified in paragraph 1.E. of Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004, by doing all applicable actions specified in Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004, except as required by paragraph (i) of this AD.

Note 1: A detailed inspection is defined in Note 10 of Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004, under paragraph 3.A., "General Information." Specific magnification requirements may be specified in the steps of the Work Instructions.

Exceptions to and Clarification of Service Bulletin 737-53A1262 Procedures

(h) Paragraph (g) of this AD requires accomplishment of Parts 1 through 11 of Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004. Parts 12 and 13 of Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004, may be accomplished, if applicable, to allow temporary return to service. This AD does not require accomplishment of Part 14 of Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004, although the FAA-approved procedures described in Part 14 are acceptable for continued operation with scribe lines found before the applicable compliance time.

(i) If any scribe line or crack is found during any inspection required by paragraph (g) of this AD, and Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004, specifies to contact Boeing for appropriate action: Before further flight, inspect or repair scribe lines and repair cracks using a method approved in accordance with the procedures specified in paragraph (y) of this AD.

(j) Where Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004, specifies a compliance time after the issuance of that service bulletin, this AD requires compliance within the specified compliance time after May 5, 2006 (the effective date of AD 2006-07-12).

(k) Certain figures are incorrectly identified in Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004. The figure cited in Part 8, step 3, should be Figure 39, not Figure 38. The figure cited in Part 9, step 4, should be Figure 38, not Figure 39.

(l) If the operator's records show that the airplane has never been stripped and repainted under the dorsal fin fairing since delivery from The Boeing Company, then this AD does not require inspections of the butt joint, lap joint, and repair, as specified in paragraph (g) of this AD, in the areas under the dorsal fin fairing.

(m) Figure 37 of Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004, defines "Restricted Zones" at door cutouts as the only affected structure. Paragraph (g) of this AD considers this area to also include Zone 1B.

(n) In Figure 1, sheets 2 and 3, of Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004, the first condition for the initial compliance threshold for Areas B, C, and E is for areas where the cutout modification shown in Boeing Service Bulletin 737-53A1177 was accomplished. Paragraph (g) of this AD considers this condition to also include Zone 1B.

(o) In Figure 1, sheets 2 and 3, of Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004, the second condition for the initial compliance threshold for Areas B, C, and E is for areas where the cutout modification shown in Boeing Service Bulletin 737-53A1177 was not accomplished. Paragraph (g) of this AD considers this condition to apply only to Zone 1A.

Reporting Requirement

(p) For airplanes on which inspections have been done in accordance with Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004: At the applicable time specified in paragraph (p)(1) or (p)(2) of this AD, submit a report of positive findings of cracks found during the inspection required by paragraph (g) of this AD to the Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Alternatively, operators may submit reports to their Boeing Company field service representatives. The report shall contain, as a minimum, the following information: Airplane serial number, flight cycles at time of discovery, location(s) and extent of positive crack findings. Under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements contained in this AD and has assigned OMB Control Number 2120-0056.

(1) If the inspection was done before May 5, 2006: Send the report within 30 days after May 5, 2006.

(2) If the inspection was done after May 5, 2006: Send the report within 30 days after the inspection is done.

New Requirements of This AD

Inspection

(q) As of the effective date of this AD, the actions for Zones 1, 2, and 3, as specified in paragraph (g) of this AD, must be done in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008, and at the applicable times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008, except as specified in paragraph (s) of this AD.

Note 2: Paragraph 1.E.5. of Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008, provides a grace period for airplanes that have exceeded the revised thresholds.

Inspection of Zones 4 and 5

(r) Do a detailed inspection for scribe lines and cracks in Zones 4 and 5, as specified in Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008. Except as provided by paragraph (s) of this AD, do the actions in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008, and at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008, or within 4,500 flight cycles after the effective date of this AD, whichever occurs later.

(1) If no scribe line or crack is found: No further work is required by this paragraph.

(2) If any scribe line or crack is found: Do all applicable investigative and corrective actions at the time specified in paragraph 1.E. of Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008, by doing all applicable actions specified in the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008, except as required by paragraph (s)(1) of this AD.

Exceptions to Specifications of Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008

(s) The following exceptions to Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008, apply to this AD:

(1) If any scribe line or crack is found during any inspection required by this AD, and Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008, specifies to contact The Boeing Company for appropriate action: Before further flight, inspect or repair scribe lines and repair cracks using a method approved in accordance with the procedures specified in paragraph (y) of this AD.

(2) Where Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008, specifies a compliance time after the issuance of that service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

(3) If the operator's records show that the airplane has never been stripped and repainted under the dorsal fin fairing since delivery from The Boeing Company, then this AD does not require inspections of the butt joint, lap joint, and repair, as specified in paragraphs (g), (q), and (r) of this AD, in the areas under the dorsal fin fairing.

(4) For airplanes in Groups 3 and 29, as identified in Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008: At the applicable times specified in paragraphs (s)(4)(i), (s)(4)(ii), and (s)(4)(iii) of this AD, perform a detailed inspection for scribe lines and cracks on the main cargo door along the lower edge of the upper hinge, around external repairs, and around decals, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008, except as provided by paragraph (s)(4)(iv) of this AD, or using a method approved in accordance with the procedures specified in paragraph (y) of this AD. If no scribe line or crack is found, no further work is required by this paragraph. If any scribe line or crack is found, do all applicable related investigative and corrective actions at the time specified in paragraph 1.E. of Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008, by doing all applicable actions specified in the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008, except as required by paragraphs (s)(1), (s)(2), and (s)(3) of this AD.

(i) For areas along the lower edge of the door hinge from body station (BS) 360 to BS 500, the initial compliance threshold is to be determined using Zone 1B.

(ii) For external repairs, the initial compliance threshold is to be determined using Zone 1B.

(iii) For decals, the initial compliance threshold is to be determined using Zone 2.

(iv) When accomplishing scribe line inspections along the lower edge of the main cargo door hinge, consider the hinge-to-skin detail inspection to be equivalent to a lap joint detail inspection and use the lap joint inspection methods in accordance with Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008.

(5) For Group 11 airplanes, as specified in Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008: Stringer 20R between BS 727C and BS 727D+10 is in Zone 1B.

Actions Accomplished in Accordance With Previous Service Information

(t)(1) Actions accomplished before the effective date of this AD in accordance with Boeing Alert Service Bulletin 737-53A1262, dated December 9, 2004, are acceptable for compliance with the corresponding requirements of paragraphs (q) and (r) of this AD.

(2) Actions accomplished before the effective date of this AD in accordance with Boeing Service Bulletin 737-53A1262, Revision 1, dated March 1, 2007; or Revision 2, dated September 20, 2007; are acceptable for compliance with the corresponding requirements of paragraphs (g), (q), and (r) of this AD.

Clarification of Procedures in the Service Bulletin

(u) For airplanes on which inspections are done as of the effective date of this AD: This AD requires accomplishment of Parts 1 through 11, 15, and 16 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008. Parts 12 and 13 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008, may be accomplished, if applicable, to allow temporary return to service. This AD does not require accomplishment of Part 14 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008, although the FAA-approved procedures described in Part 14 are acceptable for continued operation with scribe lines found before the applicable compliance time.

Report

(v) For airplanes on which inspections are done in accordance with the service information identified in Table 1 of this AD: At the applicable time specified in paragraph (v)(1) or (v)(2) of this AD, submit a report of positive findings of cracks found during the inspections required by paragraphs (q), (r), and (s)(4) of this AD to the Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Alternatively, operators may submit reports to their Boeing Company field service representatives. The report must contain, as a minimum, the following information: airplane serial number, flight cycles at time of discovery, location(s) and extent of positive crack findings. Under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements contained in this AD and has assigned OMB Control Number 2120-0056.

(1) For an inspection done before the effective date of this AD: Send the report within 30 days after the effective date of this AD.

(2) For an inspection done after the effective date of this AD: Send the report within 30 days after the inspection is done.

Table 1 – Service Information

Boeing Service Information	Revision	Date
Boeing Alert Service Bulletin 737-53A1262	3	October 16, 2008
Boeing Service Bulletin 737-53A1262	1	March 1, 2007
Boeing Service Bulletin 737-53A1262	2	September 20, 2007

Repair Plan in Lieu of Required Inspections

(w) A repair plan approved by a Boeing Company Authorized Representative or Designated Engineering Representative before the effective date of this AD is acceptable for compliance with the requirements of paragraphs (g)(2), (i), (q), (r), (s)(1), and (s)(4) of this AD, provided the approval was documented via FAA Form 8110-3 or 8100-9, and scribe line damage identified in the title of the form.

Exceptions and Clarification

(x) Paragraph 12.a.(2) of Part 12 of the Accomplishment Instructions of Boeing Service Bulletin 737-53A1262, Revision 1, dated March 1, 2007; Revision 2, dated September 20, 2007; and Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008; specifies internal inspections in accordance with Boeing Service Bulletin 737-53-1179, Revision 2, dated October 25, 2001, except for airplanes inspected internally in accordance with paragraph (b) of AD 2003-14-06, Amendment 39-13225. Inspections accomplished in accordance with AMOCs previously approved to paragraph (b) of AD 2003-14-06, are approved as an acceptable alternative method of compliance to the internal inspections specified in Part 12 of Boeing Alert Service Bulletin 737-53A1262, Revision 1, dated March 1, 2007; Revision 2, dated September 20, 2007; and Revision 3, dated October 16, 2008.

Alternative Methods of Compliance (AMOCs)

(y)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19. Send information to ATTN: Wayne Lockett, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle ACO, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6447; fax (425) 917-6590. Or, e-mail information to 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Material Incorporated by Reference

(z) You must use Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of Boeing Alert Service Bulletin 737-53A1262, Revision 3, dated October 16, 2008, under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on February 24, 2010.

Jeffrey E. Duven,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2010-05-14 Bombardier, Inc.: Amendment 39-16224. Docket No. FAA-2010-0178; Directorate Identifier 2010-NM-039-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective March 24, 2010.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes, certificated in any category, serial numbers (S/Ns) 7003 and subsequent equipped with Thales angle of attack (AOA) transducers having part number (P/N) 45150340 or P/N C16258AA.

Subject

- (d) Air Transport Association (ATA) of America Code 27: Flight Controls.

Reason

- (e) The mandatory continued airworthiness information (MCAI) states:

"The manufacturer has informed Transport Canada that a certain number of the resolver stators, which were installed in the AOA transducers, were not cleaned correctly. This condition can degrade the AOA transducer performance at low temperatures resulting in freezing of the AOA transducer resolver, which may provide inaccurate AOA data to the Stall Protection System (SPS). If not corrected, this condition can result in early or late activation of the stick shaker and/or stick pusher."

The unsafe condition is early or late activation of the stick shaker or stick pusher, which can lead to loss of control of the airplane. The required actions include inspecting to determine if certain AOA transducers are installed, and replacement if necessary.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Actions

(g) Do the following actions. (1) Within 250 flight hours after the effective date of this AD, inspect to determine if the serial number of each AOA transducer having P/N 45150340 or P/N C16258AA is listed in paragraph 1.A. of Bombardier Alert Service Bulletin A601R-27-157, Revision A, dated January 18, 2010. A review of airplane maintenance records is acceptable in lieu of this inspection if the serial number of the AOA transducer can be conclusively determined from that review.

(i) If the serial number is not listed in paragraph 1.A. of Bombardier Alert Service Bulletin A601R-27-157, Revision A, dated January 18, 2010, no further action is required other than compliance with paragraph (g)(2) of this AD.

(ii) If the serial number is listed in paragraph 1.A. of Bombardier Alert Service Bulletin A601R-27-157, Revision A, dated January 18, 2010, and the serial number has the letter "C", no further action is required other than compliance with paragraph (g)(2) of this AD.

(iii) If the serial number is listed in paragraph 1.A. of Bombardier Alert Service Bulletin A601R-27-157, Revision A, dated January 18, 2010, and the serial number does not have the letter "C": Before further flight, replace the AOA transducer with an AOA transducer that is either outside the affected serial numbers identified in paragraph 1.A. of Bombardier Alert Service Bulletin A601R-27-157, Revision A, dated January 18, 2010, or that has the letter "C" after the serial number, in accordance with paragraph 2., Part C, of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-27-157, Revision A, dated January 18, 2010.

(2) As of the effective date of this AD, do not install any replacement AOA transducer having P/N 45150340 or P/N C16258AA, having a serial number listed in paragraph 1.A. of Bombardier Alert Service Bulletin A601R-27-157, Revision A, dated January 18, 2010, on any airplane, unless the transducer has been inspected by the manufacturer and has the letter "C" after the serial number.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(h) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(i) Refer to MCAI Canadian Airworthiness Directive CF-2010-04, dated January 27, 2010; and Bombardier Alert Service Bulletin A601R-27-157, Revision A, dated January 18, 2010; for related information.

Material Incorporated by Reference

(j) You must use Bombardier Alert Service Bulletin A601R-27-157, Revision A, dated January 18, 2010, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; e-mail thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on February 24, 2010.

Jeffrey E. Duven,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2010-06-01 Airbus: Amendment 39-16225. Docket No. FAA-2009-0649; Directorate Identifier 2008-NM-218-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective April 15, 2010.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to Airbus Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; Model A320-111, -211, -212, -214, -231, -232, and -233 airplanes; and Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes; certificated in any category; all manufacturer serial numbers (MSN); equipped with electronic instrument system 1 (EIS1) standard V32 (display management computer (DMC)) part number (P/N) 9615325032), EIS1 standard V40 (DMC P/N 9615325040), or EIS1 standard V50 (DMC P/N 9615325050).

Subject

- (d) Air Transport Association (ATA) of America Code 31: Instruments.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

"Two incidents [of near mid-air collision] have occurred on Airbus A320 Family aircraft during [a] Resolution Advisory with Traffic Alert and Collision Avoidance System (TCAS). One of the Human-Machine Interface (HMI) factors was the lack of visibility of relevant information on the Primary Flight Display (PFD).

"This condition, if not corrected, could result in erroneous interpretation of TCAS Resolution Advisories, leading to an increased risk of mid-air collision.

"EIS1 software standard V60 introduces modifications to the vertical speed indication to further improve the legibility in the case of TCAS Resolution Advisory. This modification consists of a change in the needle colour and thickness and an increase in width of the TCAS green band.

"For the reasons described above, this AD requires the introduction of the new software standard V60 and prohibits reinstallation of earlier software versions V32, V40 and V50."

Actions and Compliance

(f) Unless already done, do the following actions:

(1) Within 60 months after the effective date of this AD, modify the airplane by installing EIS1 software standard V60 (DMC P/N 9615325060), in accordance with the instructions of Airbus Mandatory Service Bulletin A320-31-1286, dated January 22, 2008.

(2) After modifying the airplane as required by paragraph (f)(1) of this AD, no person shall install EIS1 software standard V32 (DMC P/N 9615325032), EIS1 software standard V40 (DMC P/N 9615325040), or EIS1 software standard V50 (DMC P/N 9615325050) on that airplane.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to Attn: Tim Dulin, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2141; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq., the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2008-0198, dated November 4, 2008; and Airbus Mandatory Service Bulletin A320-31-1286, dated January 22, 2008; for related information.

Material Incorporated by Reference

(i) You must use Airbus Mandatory Service Bulletin A320-31-1286, dated January 22, 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus, Airworthiness Office–EAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail: account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on February 25, 2010.

Jeffrey E. Duven,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2010-06-04 Airbus: Amendment 39-16228. Docket No. FAA-2009-0789; Directorate Identifier 2008-NM-185-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective April 15, 2010.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to the airplanes, certificated in any category, identified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD.

(1) Airbus Model A300 B2-1C, A300 B2-203, A300 B2K-3C, A300 B4-103, A300 B4-203, and A300 B4-2C airplanes, all serial numbers incorporating Airbus Modification 02434 or 03599;

(2) Airbus Model A310-203, A310-204, A310-221, A310-222, A310-304, A310-322, A310-324, and A310-325 airplanes, all serial numbers, except airplanes incorporating Airbus Modification 10432;

(3) Airbus Model A300 B4-601, A300 B4-603, A300 B4-605R, A300 B4-620, A300 B4-622, and A300 B4-622R airplanes, all serial numbers, except airplanes incorporating Airbus Modification 10432.

Subject

- (d) Air Transport Association (ATA) of America Code 54: Nacelles/Pylons.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

"Cracks have been found on pylon side panels (upper section) at rib 8 on Airbus A300, A310 and A300-600 aircraft equipped with General Electric engines. Investigation of these findings indicates that this problem is likely to affect aircraft of this type design with other engine installations. This condition, if not corrected, can lead to reduced strength [structural integrity] of the pylon primary structure.

"In order to detect any crack propagation at an early stage, thus avoiding an extensive repair, Airbus issued Service Bulletins (SB) A300-54-0075, A310-54-2018 and A300-54-6015. * * *

"This AD requires the implementation of this * * * inspection programme."

The unsafe condition is reduced structural integrity of the pylon primary structure, which could cause detachment of the engine from the fuselage. Required actions include repetitive detailed visual inspections, or repetitive eddy current and detailed visual inspections, to detect cracks, depending on the airplane configuration, and corrective actions if necessary. The corrective actions include repairing the cracking, and contacting Airbus for repair instructions and doing the repair, as applicable.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) For Configuration 01 airplanes as identified in the applicable service bulletin identified in Table 2 of this AD: At the applicable time specified in Table 1 of this AD, except as required by paragraphs (f)(2) and (f)(3) of this AD, perform a detailed visual inspection of the pylons 1 and 2 side panels (upper section) at rib 8, in accordance with paragraph 3.B. of the Accomplishment Instructions of the applicable service bulletin identified in Table 2 of this AD. Repeat the inspection at the time specified in Table 1 of this AD.

Table 1 – Compliance Times for Configuration 1

For Model –	That have accumulated –	Inspect before the accumulation of –	Or within –	And repeat the inspection at intervals not to exceed –
		Whichever occurs later		
A300 B2-1C, B2-203, and B2K-3C airplanes	≤17,500 total flight cycles ¹	5,350 total flight cycles	2,500 flight cycles ²	4,300 flight cycles.
A300 B2-1C, B2-203, and B2K-3C airplanes	>17,500 total flight cycles ¹	20,000 total flight cycles or 40,000 total flight hours, whichever occurs first	250 flight cycles ²	4,300 flight cycles.
A300 B4-103, B4-203, and B4-2C airplanes	≤18,000 total flight cycles ¹	5,350 total flight cycles	2,000 flight cycles ²	4,300 flight cycles.
A300 B4-103, B4-203, and B4-2C airplanes	>18,000 total flight cycles ¹	20,000 total flight cycles or 40,000 total flight hours, whichever occurs first	250 flight cycles ²	4,300 flight cycles.
A300 B4-601, B4-603, B4-605R, B4-620, B4-622, and B4-622R airplanes	≤18,000 total flight cycles ¹	4,200 total flight cycles	2,000 flight cycles ²	3,600 flight cycles.

A300 B4-601, B4-603, B4-605R, B4-620, B4-622, and B4-622R airplanes	>18,000 total flight cycles ¹	20,000 total flight cycles or 40,000 total flight hours, whichever occurs first	250 flight cycles ²	3,600 flight cycles.
A310-200 airplanes with GE CF6-80A3 or Pratt & Whitney engines	≤18,000 total flight cycles ¹	9,700 total flight cycles or 19,400 total flight hours, whichever occurs first	1,500 flight cycles ²	6,700 flight cycles or 13,400 flight hours, whichever occurs first.
A310-200 airplanes with GE CF6-80A3 or Pratt & Whitney engines	>18,000 total flight cycles ¹	19,500 total flight cycles or 55,500 total flight hours, whichever occurs first	250 flight cycles ²	6,700 flight cycles or 13,400 flight hours, whichever occurs first.
A310-200 airplanes with GE CF6-80C2 engines	≤18,000 total flight cycles ¹	7,800 total flight cycles or 15,600 total flight hours, whichever occurs first	1,500 flight cycles ²	5,800 flight cycles or 11,600 flight hours, whichever occurs first.
A310-200 airplanes with GE CF6-80C2 engines	>18,000 total flight cycles ¹	19,500 total flight cycles or 55,500 total flight hours, whichever occurs first	250 flight cycles ²	5,800 flight cycles or 11,600 flight hours, whichever occurs first.
A310-300 SR ³ airplanes with Pratt & Whitney JT9D engines	≤18,000 total flight cycles ¹	8,600 total flight cycles or 24,000 total flight hours, whichever occurs first	1,500 total flight cycles ²	6,700 flight cycles or 18,700 flight hours, whichever occurs first.
A310-300 SR ³ airplanes with Pratt & Whitney JT9D engines	>18,000 total flight cycles ¹	19,500 total flight cycles or 55,500 total flight hours, whichever occurs first	250 flight cycles ²	6,700 flight cycles or 18,700 flight hours, whichever occurs first.
A310-300 SR ³ airplanes with GE engines	≤18,000 total flight cycles ¹	7,000 total flight cycles or 19,600 total flight hours, whichever occurs first	1,500 flight cycles ²	5,700 flight cycles or 15,900 flight hours, whichever occurs first.
A310-300 SR ³ airplanes with GE engines	>18,000 total flight cycles ¹	19,500 total flight cycles or 55,500 total flight hours, whichever occurs first	250 flight cycles ²	5,700 flight cycles or 15,900 flight hours, whichever occurs first.
A310-300 SR ³ airplanes with Pratt & Whitney 4000 engines	≤18,000 total flight cycles ¹	7,000 total flight cycles or 19,600 total flight hours, whichever occurs first	1,500 flight cycles ²	5,800 flight cycles or 16,200 flight hours, whichever occurs first.

A310-300 SR ³ airplanes with Pratt & Whitney 4000 engines	>18,000 total flight cycles ¹	19,500 total flight cycles or 55,500 total flight hours, whichever occurs first	250 flight cycles ²	5,800 flight cycles or 16,200 flight hours, whichever occurs first.
A310-300 LR ⁴ airplanes with Pratt & Whitney JT9D engines	≤18,000 total flight cycles ¹	5,900 total flight cycles or 29,500 total flight hours, whichever occurs first	1,500 flight cycles ²	6,000 flight cycles or 30,300 flight hours, whichever occurs first.
A310-300 LR ⁴ airplanes with Pratt & Whitney JT9D engines	>18,000 total flight cycles ¹	19,500 total flight cycles or 55,500 total flight hours, whichever occurs first	250 flight cycles ²	6,000 flight cycles or 30,300 flight hours, whichever occurs first.
A310-300 LR ⁴ airplanes with GE engines	≤18,000 total flight cycles ¹	4,800 total flight cycles or 24,100 total flight hours, whichever occurs first	1,500 flight cycles ²	5,100 flight cycles or 25,500 flight hours, whichever occurs first.
A310-300 LR ⁴ airplanes with GE engines	>18,000 total flight cycles ¹	19,500 total flight cycles or 55,500 total flight hours, whichever occurs first	250 flight cycles ²	5,100 flight cycles or 25,500 flight hours, whichever occurs first.
A310-300 LR ⁴ airplanes with Pratt & Whitney 4000 engines	≤18,000 total flight cycles ¹	4,800 total flight cycles or 24,000 total flight hours, whichever occurs first	1,500 flight cycles ²	5,200 flight cycles or 26,300 flight hours, whichever occurs first.
A310-300 LR ⁴ airplanes with Pratt & Whitney 4000 engines	>18,000 total flight cycles ¹	19,500 total flight cycles or 55,500 total flight hours, whichever occurs first	250 flight cycles ²	5,200 flight cycles or 26,300 flight hours, whichever occurs first.

¹ As of the effective date of this AD.

² After the effective date of this AD.

³ "SR" applies to airplanes with average flights less than 4 flight hours.

⁴ "LR" refers to airplanes with average flights of 4 or more flight hours.

(2) For Model A300 and A300-600 airplanes that have accumulated more than 40,000 total flight hours as of the effective date of this AD: Within 250 flight cycles after the effective date of this AD, do the actions specified in paragraph (f)(1) of this AD.

(3) For Model A310 airplanes that have accumulated more than 55,500 total flight hours as of the effective date of this AD: Within 250 flight cycles after the effective date of this AD, do the actions specified in paragraph (f)(1) of this AD.

(4) For Configuration 01 airplanes, as identified in the applicable service bulletin identified in Table 2 of this AD: If a crack is found during any inspection required by this AD, before further flight, install a doubler, in accordance with paragraph 3.C. of the Accomplishment Instructions of the applicable service bulletin identified in Table 2 of this AD.

(5) For Configuration 02 airplanes, as identified in the applicable service bulletin identified in Table 2 of this AD: At the applicable time specified in paragraph 1.E.(2) of the applicable service bulletin identified in Table 2 of this AD, or within 250 flight cycles after the effective date of this AD, whichever occurs later, perform a detailed visual inspection of the pylons 1 and 2 side panels (upper section) at rib 8, in accordance with paragraph 3.B. of the Accomplishment Instructions of the applicable service bulletin identified in Table 2 of this AD.

(6) For Configuration 03 airplanes, as identified in the applicable service bulletin identified in Table 2 of this AD: At the applicable time specified in paragraph 1.E.(2) of the applicable service bulletin identified in Table 2 of this AD, or within 250 flight cycles after the effective date of this AD, whichever occurs later, perform a detailed visual inspection, and a high frequency eddy current inspection as applicable, of the pylons 1 and 2 side panels (upper section) at rib 8, in accordance with paragraph 3.B. of the Accomplishment Instructions of the applicable service bulletin identified in Table 2 of this AD.

(7) For Configuration 02 and 03 airplanes, as identified in the applicable service bulletin identified in Table 2 of this AD: If a crack is found during any inspection required by paragraph (f)(1), (f)(5), or (f)(6) of this AD, before further flight, repair in accordance with paragraph 3.C. of the Accomplishment Instructions of the applicable service bulletin identified in Table 2 of this AD.

(8) For all airplanes, except those in Configuration 01, as identified in the applicable service bulletin identified in Table 2 of this AD: Repeat the inspection specified in paragraph (f)(1), (f)(5), or (f)(6) of this AD, as applicable, at the intervals specified in paragraph 1.E.(2) of the applicable service bulletin identified in Table 2 of this AD.

Table 2 – Service Bulletins

For Model –	Use Airbus Mandatory Service Bulletin –	Revision –	Dated –
A300 B2-1C, B2-203, B2K-3C, B4-103, B4-203, and B4-2C airplanes	A300-54-0075, excluding Appendices 1, 2, and 3	02	June 26, 2008.
A300 B4-601, B4-603, B4-605R, B4-620, B4-622, and B4-622R airplanes	A300-54-6015, excluding Appendices 1, 2, and 3	02	June 26, 2008.
A310 series airplanes	A310-54-2018, excluding Appendices 1, 2, and 3	02	June 26, 2008.

(9) Inspections and corrective actions accomplished prior to the effective date of this AD in accordance with the service bulletins identified in Table 3 of this AD, as applicable, are acceptable for compliance with the corresponding requirements of this AD.

Table 3 – Previous Service Information

Service Bulletin	Revision	Date
Airbus Mandatory Service Bulletin A300-54-0075	01	November 9, 2007
Airbus Mandatory Service Bulletin A300-54-6015	01	November 9, 2007
Airbus Mandatory Service Bulletin A310-54-2018	01	November 16, 2007
Airbus Service Bulletin A300-54-0075	Original	August 11, 1993

Airbus Service Bulletin A300-54-6015	Original	August 11, 1993
Airbus Service Bulletin A310-54-2018	Original	August 11, 1993

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows:

- (1) Although the MCAI/service information allows further flight after cracks are found during compliance with certain actions, this AD requires that you repair the crack(s) before further flight.
- (2) Although the MCAI specifies to send all inspection results to Airbus, this AD does not include that requirement.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

- (1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.
- (2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.
- (3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2008-0181, dated October 1, 2008, and the applicable service bulletins identified in Table 2 of this AD, for related information.

Material Incorporated by Reference

(i) You must use the service information specified in Table 4 of this AD, as applicable, to do the actions required by this AD, unless the AD specifies otherwise.

Table 4 – Service Information

Airbus Mandatory Service Bulletin –	Revision –	Dated –
A300-54-0075, excluding Appendices 1, 2, and 3	02	June 26, 2008
A300-54-6015, excluding Appendices 1, 2, and 3	02	June 26, 2008
A310-54-2018, excluding Appendices 1, 2, and 3	02	June 26, 2008

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus SAS–EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail: account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington on March 4, 2010.

Suzanne Masterson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2010-06-05 Airbus: Amendment 39-16229. Docket No. FAA-2009-0993; Directorate Identifier 2009-NM-089-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective April 15, 2010.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to Airbus airplanes, certificated in any category, as identified in paragraphs (c)(1) and (c)(2) of this AD.

(1) Model A300 B4-2C, B4-103, and B4-203 airplanes, all serial numbers, modified preventively in service (without preliminary crack findings) in accordance with Airbus Service Bulletin A300-53-0297 (Airbus Modification 10453).

(2) Model A300 B4-601, B4-603, B4-605R, B4-620, B4-622, and B4-622R airplanes, all serial numbers, modified preventively in service (without preliminary crack findings) in accordance with Airbus Service Bulletin A300-57-6053 (Airbus Modification 10453).

Note 1: For airplanes on which Airbus Service Bulletin A300-53-0297 or A300-57-6053 (Airbus Modification 10453), as applicable, has been incorporated as a corrective action (repair following crack finding), no action is required by this AD.

Subject

- (d) Air Transport Association (ATA) of America Code 53: Fuselage.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

"One A300-600 aeroplane operator reported that, during a routine inspection, the Right Hand frame 40 forward fitting between stringer 32 and stringer 33 was found cracked. The subject aeroplane had previously been modified in accordance with Airbus SB A300-57-6053 (Airbus Modification 10453).

"This condition, if not corrected, could result in a deterioration of the structural integrity of the frame.

"As no fatigue maintenance tasks (Inspection SB or Airworthiness Limitation Item) presently exist to inspect the affected area for aeroplanes having incorporated Airbus Modification 10453 preventively (without preliminary crack finding), Airbus has developed a new inspection [for cracking, and repair if necessary] to ensure structural integrity of the concerned area of frame 40."

* * * * *

Actions and Compliance

(f) Unless already done, do the following actions.

(1) At the applicable time specified in Table 1 of this AD: Do a one-time detailed visual inspection of the forward fitting at frame 40 on both sides of the airplane, in accordance with Airbus Mandatory Service Bulletin A300-57A6108 (for Model A300 B4-601, B4-603, B4-605R, B4-620, B4-622, and B4-622R airplanes) or A300-53A0387 (for Model A300 B4-2C, B4-103, and B4-203 airplanes), both including Appendices 01 and 02, both dated September 12, 2008.

Table 1 – Compliance Times

Airplane Models/ Configuration	Compliance Time
A300 B4-2C and B4-103 airplanes on which Airbus Service Bulletin A300-53-0297 was done prior to the accumulation of 9,000 total flight cycles	Prior to the accumulation of 18,000 total flight cycles, or within 3 months after the effective date of this AD, whichever occurs later
A300 B4-2C and B4-103 airplanes on which Airbus Service Bulletin A300-53-0297 was done on or after the accumulation of 9,000 total flight cycles	Within 5,500 flight cycles after accomplishment of Airbus Service Bulletin A300-53-0297, or within 6 months after the effective date of this AD, whichever occurs later; except, for airplanes that, as of the effective date of this AD, have accumulated 11,000 flight cycles or more since accomplishment of Airbus Service Bulletin A300-53-0297, within 3 months after the effective date of this AD
A300 B4-203 airplanes on which Airbus Service Bulletin A300-53-0297 was done prior to the accumulation of 8,300 total flight cycles	Prior to the accumulation of 15,000 total flight cycles, or within 3 months after the effective date of this AD, whichever occurs later

A300 B4-203 airplanes on which Airbus Service Bulletin A300-53-0297 was done on or after the accumulation of 8,300 total flight cycles	Within 4,100 flight cycles after accomplishment of Airbus Service Bulletin A300-53-0297, or within 6 months after the effective date of this AD, whichever occurs later; except, for airplanes that, as of the effective date of this AD, have accumulated 8,200 flight cycles or more since accomplishment of Airbus Service Bulletin A300-53-0297, within 3 months after the effective date of this AD
A300 B4-601, B4-603, B4-605R, B4-620, B4-622, and B4-622R airplanes on which Airbus Service Bulletin A300-57-6053 was done prior to the accumulation of 6,100 total flight cycles	Prior to the accumulation of 11,500 total flight cycles, or within 3 months after the effective date of this AD, whichever occurs later
A300 B4-601, B4-603, B4-605R, B4-620, B4-622, and B4-622R airplanes on which Airbus Service Bulletin A300-57-6053 was done on or after the accumulation of 6,100 total flight cycles	Within 3,300 flight cycles after accomplishment of Airbus Service Bulletin A300-57-6053, or within 6 months after the effective date of this AD, whichever occurs later; except, for airplanes that, as of the effective date of this AD, have accumulated 6,600 flight cycles or more since accomplishment of Airbus Service Bulletin A300-57-6053, within 3 months after the effective date of this AD

(2) Except as required by paragraph (f)(3) of this AD: If any crack is found during the inspection required by paragraph (f)(1) of this AD, before further flight, do a temporary or definitive repair, as applicable, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-53-0268, Revision 06, dated January 7, 2002 (for Model A300 B4-2C, B4-103, and B4-203 airplanes); or A300-57-6052, Revision 03, dated May 27, 2002, including Airbus Drawings 15R53810394, Issue A, dated December 21, 1998, and 21R57110247, Issue A, dated June 20, 1997 (for Model A300 B4-601, B4-603, B4-605R, B4-620, B4-622, and B4-622R airplanes).

(3) If any crack found during the inspection required by paragraph (f)(1) of this AD cannot be repaired in accordance with Airbus Service Bulletin A300-53-0268, Revision 06, dated January 7, 2002; or A300-57-6052, Revision 03, dated May 27, 2002: Contact Airbus for repair instructions and before further flight repair the crack using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA) (or its delegated agent.)

Note 2: A repair is considered any modification that restores the original strength of the cracked part.

(4) Submit an inspection report in accordance with Appendix 01 of Airbus Mandatory Service Bulletin A300-53A0387, dated September 12, 2008 (for Model A300 B4-2C, B4-103, and B4-203 airplanes); or Airbus Mandatory Service Bulletin A300-57A6108, dated September 12, 2008 (for Model A300 B4-601, B4-603, B4-605R, B4-620, B4-622, and B4-622R airplanes); to the address identified on the reporting sheet, at the applicable time specified in paragraph (f)(4)(i) or (f)(4)(ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

FAA AD Differences

Note 3: This AD differs from the MCAI and/or service information as follows: Although the MCAI or Airbus Service Bulletin A300-53-0268, Revision 06, dated January 7, 2002; or A300-57-6052, Revision 03, dated May 27, 2002; allows further flight after cracks are found during compliance with the required action, paragraph (f)(3) of this AD requires that the cracks be repaired before further flight.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to Attn: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI EASA Airworthiness Directive 2009-0094, dated April 21, 2009 (Correction: May 29, 2009), and the applicable service information specified in Table 2 of this AD, for related information.

Table 2 – Related Service Information

Document	Revision	Date
Airbus Mandatory Service Bulletin A300-53A0387, including Appendices 01 and 02	Original	September 12, 2008
Airbus Mandatory Service Bulletin A300-57A6108, including Appendices 01 and 02	Original	September 12, 2008

Airbus Service Bulletin A300-53-0268	06	January 7, 2002
Airbus Service Bulletin A300-57-6052, including Airbus Drawings 15R53810394, Issue A, dated December 21, 1998, and 21R57110247, Issue A, dated June 20, 1997	03	May 27, 2002

Material Incorporated by Reference

(i) You must use the service information contained in Table 3 of this AD to do the actions required by this AD, as applicable, unless the AD specifies otherwise.

Table 3 – Material Incorporated by Reference

Document	Revision	Date
Airbus Mandatory Service Bulletin A300-53A0387, including Appendices 01 and 02	Original	September 12, 2008
Airbus Mandatory Service Bulletin A300-57A6108, including Appendices 01 and 02	Original	September 12, 2008
Airbus Service Bulletin A300-53-0268	06	January 7, 2002
Airbus Service Bulletin A300-57-6052, including Airbus Drawings 15R53810394, Issue A, dated December 21, 1998, and 21R57110247, Issue A, dated June 20, 1997	03	May 27, 2002

Airbus Service Bulletin A300-53-0268, Revision 06, dated January 7, 2002, has the following effective pages:

Page No.	Revision level shown on page	Date shown on page
1–6, 9, 10, 25–27	06	January 7, 2002.
7, 8, 11–24, 28–84	05	June 9, 2000.

Airbus Service Bulletin A300-57-6052, Revision 03, dated May 27, 2002, has the following effective pages:

Page No.	Revision level shown on page	Date shown on page
1-56	03	May 27, 2002.
DRAWING 15R53810394		
1-2	A	December 21, 1998.
DRAWING 21R57110247		
1-2	A	May 28, 1997.
3-4	A	June 20, 1997.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus SAS-EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail: account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on March 4, 2010.
 Suzanne Masterson,
 Acting Manager, Transport Airplane Directorate,
 Aircraft Certification Service.



ISSUE DATE: March 12, 2010

AD 2010-06-51; Docket No. FAA-2010-0230; Directorate Identifier 2010-NM-071-AD

Emergency airworthiness directive (AD) 2010-06-51 is sent to all owners and operators of The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes.

Background

The FAA received a report of failure of the aft attach lugs on the left elevator tab control mechanism, which resulted in severe elevator vibration. The flightcrew diverted from the intended route and made an uneventful landing. Subsequent investigation revealed extensive damage to the elevator tab control system. Severe vibration in this attach point is suspected of allowing rapid wear of the joint, and resulted in failure of the attach lugs. This condition, if not corrected, could result in a loss of aircraft control and structural integrity.

Explanation of Relevant Service Information

We have reviewed Boeing Alert Service Bulletin 737-27A1296, dated March 12, 2010. The service bulletin describes procedures for a detailed inspection to detect discrepancies of the inboard and outboard aft attach lugs of the elevator tab control mechanism. Discrepancies include movement or rotation of the spacer, and gaps between the swage ring and the aft attach lug or between the spacer and the aft attach lug. The service bulletin describes procedures for replacing any discrepant elevator tab control mechanism, including performing the detailed inspection on the replacement part before and after installation. For certain airplanes, the compliance time for the inspection is 12 or 30 days, depending on airplane line number, total accumulated flight cycles, and approval for operation under extended twin operations (ETOPS).

FAA's Determination and Requirements of this AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. Therefore, we are issuing this AD to detect and correct a loose bearing in the aft lug of the elevator tab control mechanism, which could result in unwanted elevator and tab vibration. The consequent structural failure of the elevator or horizontal stabilizer could result in loss of aircraft control and structural integrity. This AD requires accomplishing the actions specified in the service information described previously, except as discussed under "Differences Between this AD and the Service Bulletin." This AD also requires reporting the inspection results to Boeing.

Differences Between this AD and the Service Bulletin

The effectivity of Boeing Alert Service Bulletin 737-27A1296, dated March 12, 2010, includes all Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes. The inspection requirements of this AD, however, affect only those airplanes subject to a short compliance time (within 12 or 30 days). Because the suspect components may be installed as replacements on all airplanes subject to this AD, paragraph (l) of this AD requires that the part be inspected before and after installation. We may consider superseding this AD to apply the inspection requirements to the remaining airplanes,

which would be subject to a longer compliance time that would allow enough time to provide notice and opportunity for prior public comment on the merits of the inspection for these airplanes.

Interim Action

This AD is considered to be interim action. The inspection reports that are required by this AD will enable the manufacturer to obtain better insight into the nature, cause, and extent of the issue, and eventually to develop final action to address the unsafe condition. Once final action has been identified, we might consider further rulemaking.

Examining the Docket

You may examine the contents of this AD docket on the Internet at <http://www.regulations.gov>; (on the next business day after we have issued the AD), or in person at U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. This docket number is FAA-2010-0230; the directorate identifier for this docket is 2010-NM-071-AD.

Authority for this Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If this emergency regulation is later deemed significant under DOT Regulatory Policies and Procedures, we will prepare a final regulatory evaluation and place it in the AD Docket. See the "Examining the Docket" section for a location to examine the regulatory evaluation, if filed.

Determination of Rule's Effective Date

This emergency AD is issued under 49 U.S.C. Section 44701 according to the authority delegated to me by the Administrator, and is effective immediately upon receipt.

Because an unsafe condition exists that requires the immediate adoption of this emergency AD, we find that notice and opportunity for prior public comment hereon are impracticable and that good cause exists for making this emergency AD effective in less than 30 days.

2010-06-51 The Boeing Company: Docket No. FAA-2010-0230; Directorate Identifier No. 2010-NM-071-AD.

Effective Date

(a) Emergency airworthiness directive (AD) 2010-06-51, issued on March 12, 2010, is effective immediately upon receipt.

Affected Ads

(b) None.

Applicability

(c) This AD applies to all The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes; certificated in any category.

Subject

(d) Air Transport Association (ATA) of America Code 27: Flight controls.

Unsafe Condition

(e) This AD results from a report of failure of the aft attach lugs on the left elevator tab control mechanism, which resulted in severe elevator vibration. The Federal Aviation Administration is issuing this AD to detect and correct a loose bearing in the aft lug of the elevator tab control mechanism, which could result in unwanted elevator and tab vibration. The consequent structural failure of the elevator or horizontal stabilizer could result in loss of aircraft control and structural integrity.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection and Corrective Action

(g) For Groups 1, 2, and 3; and Group 4, Configuration 2; as identified in Boeing Alert Service Bulletin 737-27A1296, dated March 12, 2010: At the applicable time specified in paragraph 1.E. Compliance of Boeing Alert Service Bulletin 737-27A1296, dated March 12, 2010, except as required by paragraph (i) of this AD, do a detailed inspection of the inboard and outboard aft attach lugs of the left and right elevator control tab mechanisms for gaps between the swage ring and the aft attach lug, and between the spacer and the aft attach lug; and try to move or rotate the spacer using hand pressure, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-27A1296, dated March 12, 2010.

(h) If, during accomplishment of the actions required by paragraph (g) of this AD, any gap is found between the swage ring and the aft attach lug, or between the spacer and the aft attach lug; or if the spacer moves or rotates: Before further flight, do the actions required by paragraphs (h)(1) and (h)(2) of this AD, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-27A1296, dated March 12, 2010.

- (1) Inspect the replacement elevator tab control mechanism for discrepancies, as specified in paragraph (g) of this AD; and, if no discrepancy is found, install the replacement elevator tab control mechanism.
- (2) Re-inspect the installed elevator tab control mechanism, as required by paragraph (g) of this AD.

Exception to Service Bulletin Specifications

- (i) Where Boeing Alert Service Bulletin 737-27A1296, dated March 12, 2010, specifies a compliance time after the date of the original issue of the service bulletin, this AD requires compliance within the specified compliance time after receipt of this AD.

Inspection Done According to Multi Operator Message (MOM)

- (j) An inspection done before receipt of this AD according to Boeing Multi Operator Message Number MOM-MOM-10-0159-01B, dated March 10, 2010, is considered acceptable for compliance with the corresponding inspection specified in paragraph (g) of this AD.

Reporting

(k) At the applicable time specified in paragraph (k)(1) or (k)(2) of this AD: Submit a report of the findings (both positive and negative) of the inspections required by paragraph (g) of this AD to Boeing Commercial Airplanes Group, Attention: Manager, Airline Support, email: rse.boecom@boeing.com. The report must include the inspection results including a description of any discrepancies found, the airplane line number, and the number of flight cycles and flight hours accumulated on the airplane. Under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements contained in this AD and has assigned OMB Control Number 2120-0056.

- (1) If the inspection was done on or after receipt of this AD: Submit the report within 10 days after the inspection.
- (2) If the inspection was done before receipt of this AD: Submit the report within 10 days after receipt of this AD.

Parts Installation

(l) For all airplanes: As of receipt of this AD, no person may install an elevator tab control mechanism, part number 251A2430-(), on any airplane, unless the mechanism has been inspected before and after installation, in accordance with the requirements of paragraph (g) of this AD, and no discrepancies have been found.

Special Flight Permit

(m) Special flight permits, as described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), are not allowed.

Alternative Methods of Compliance (AMOCs)

(n)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Kelly McGuckin, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone 425-917-6490; fax 425-917-6590. Information may be e-mailed to 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically refer to this AD.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Contact Information

(o) For technical information about this AD, contact Kelly McGuckin, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 917-6490; fax (425) 917-6590. For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

Issued in Renton, Washington, on March 12, 2010.

Original signed by:

Ali Bahrami,
Manager,
Transport Airplane Directorate,
Aircraft Certification Service.