



**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES
LARGE AIRCRAFT**

BIWEEKLY 2011-16

This electronic copy may be printed and used in lieu of the FAA biweekly paper copy.

U.S. Department of Transportation
Federal Aviation Administration
Regulatory Support Division
Delegation and Airworthiness Programs Branch, AIR-140
P. O. Box 26460
Oklahoma City, OK 73125-0460
FAX 405-954-4104

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency			
Biweekly 2011-01			
2010-25-06		Boeing	737-200, -300, -400, and -500 series
2010-26-05		Dassault Aviation	Falcon 10, Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F, and G, Mystere-Falcon 20-C5, 20-D5, 20-E5, 20-F5, Mystere-Falcon 200, Mystere-Falcon 50, Mystere-Falcon 900, Falcon 900EX, Falcon 2000 and Falcon 2000EX
2010-26-06		Boeing	737-600, -700, -700C, -800, and -900 series
2010-26-07		Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2010-26-08		Boeing	767-200, -300, -300F, and -400ER series
2010-26-10	S 2006-05-09	Boeing	747-200C, -200F, -400, -400D, and -400F series
2010-26-12		Airbus	A321-211, -212, -231, and -232
2010-26-13		Bombardier	DHC-8-301, -311, and -315
Biweekly 2011-02			
2010-02-05		Airbus	See AD
2010-24-05	COR	Pratt & Whitney Canada	Engine: PW305A and PW305B
2010-24-06	S 2006-12-18	Short Brothers PLC	SD3-60 SHERPA, SD3-SHERPA, SD3-30, and SD3-60
2011-01-01	S 2008-13-15	Embraer	EMB-135BJ
2011-01-02		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, 343, A340-211, -212, -213, -311, -312, and -313
2011-01-05		Boeing	727, 727C, 727-100, 727-100C, 727-200, and 727-200F
2011-01-06	S 2007-02-22	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325
2011-01-07		328 Support Services GmbH	328-100 and -300
2011-01-09		B/E Aerospace	Appliance: Protective breathing equipment (PBE) units
2011-01-10		Bombardier	BD-700-1A10 and BD-700-1A11
2011-01-11		Boeing	MD-90-30
2011-01-12	S 2008-21-03	Boeing	737-300, -400, and -500 series
2011-01-13		Airbus	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F
2011-01-15		Boeing	757-200, -200CB, and -300 series
2011-01-16		Boeing	DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and MD-88
2011-02-01		Boeing	MD-11 and MD-11F
2011-02-03		Boeing	757-200, -200PF, -200CB, and -300 series
Biweekly 2011-03			
2011-02-05		Boeing	727, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2011-02-06		Boeing	767-300 series
2011-02-09		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, and -313
2011-03-01	S 2005-25-05	Pratt & Whitney	JT8D-7, -7A, -7B, -9, -9A, -11, -15, -15A, -17, -17A, -17R, and -17AR series

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency			
Biweekly 2011-04			
2011-02-07	S 2010-12-10	General Electric	Engine: CF6-45A, CF6-45A2, CF6-50A, CF6-50C, CF6-50CA, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50E, CF6-50E1, CF6-50E2, CF6-50C2-F and CF6-50C2-R
2011-03-07		Fokker Services	F.28 Mark 1000, 2000, 3000, 4000, and F.28 Mark 0100
2011-03-08		Bombardier	CL-215-1A10 (CL-215), CL-215-6B11 (CL-215T Variant), and CL-215-6B11 (CL-415 Variant)
2011-03-09		Boeing	MD-90-30
2011-03-10	S 2005-20-32	Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, and -313
2011-03-11		Airbus	A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R, B4-622R, A300 F4-605R, and A300 C4-605R Variant F
2011-03-12		Hawker Beechcraft	400A and 400T
2011-03-13		Bombardier	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900)
2011-03-14		Boeing	737-100, -200, -200C, -300, -400, -500 series, and 737-400 series
2011-04-02		Hamilton Sundstrand	Propeller: 247F series
Biweekly 2011-05			
2011-03-15		Boeing	767-200, -300, -300F, and -400ER series
2011-03-16		Cessna	750
2011-04-01		Fokker	F.28 Mark 0070 and 0100
2011-04-03		Bombardier	CL-600-2B19 (Regional Jet Series 100 and 440)
2011-04-04	S 2005-18-02	Pratt & Whitney	Engine: JT8D-209, -217, -217A, -217C, and -219 turbofan
2011-04-05		Airbus	A340-211, -212, -213; A340-311, -312, -313; A340-541; and A340-642
2011-04-06		Airbus	A340-211, -212, -213; A340-311, -312, -313; A340-541; A340-642
2011-04-07		Fokker	F.28 Mark 0070 and 0100
2011-04-08		Learjet	45
2011-04-10	S 2009-23-10	Boeing	737-300, -400, and -500 series
2011-05-03	S 2005-06-04	Bombardier	CL-600-2B19 (Regional Jet Series 100 & 440)
2011-05-04	S 2008-23-19	Boeing	757-200, -200CB, -200PF, and -300 series
2011-05-05		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, -541, and -642
Biweekly 2011-06			
98-09-27R1		Rolls-Royce plc	Engine: RB211-Trent 768, 772, and 772B turbofan
2011-04-09		Transport Category Airplanes	Transport Category Airplanes
2011-05-10		BAE Systems (Operations) Limited	ATP, HS 748 2A and series 2B
2011-05-11	S 2007-19-19	Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747SR, and 747SP series
2011-05-12		Boeing	777-200, -200LR, -300, and -300ER series
2011-05-13		Saab AB, Saab Aerosystems	SAAB 2000
2011-05-14		Bombardier	DHC-8-400, -401, and -402
2011-06-04		Airbus	A330-243F

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency			
Biweekly 2011-07			
2011-06-03		Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2011-06-05 2011-06-08	S 2007-18-52	Boeing Bombardier	737-600, -700, -700C, -800, -900, and -900ER series CL-600-2B19 (Regional Jet Series 100 & 440), CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900)
2011-06-09	S 2009-11-09	Airbus	A300 B4-601, A300 B4-603, A300 B4-620, A300 B4-622, A300 B4-605R, A300 B4-622R; A300 F4-605R, A300 F4-622R; and A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2011-06-11		Rolls-Royce plc	Engine: RB211-Trent 970-84, 970B-84, 972-84, 972B-84, 977-84, 977B-84, and 980-84 turbofan
2011-06-12 2011-07-01	S 2009-04-17	Boeing General Electric	MD-90-30 Engine: CF6-45A, CF6-45A2, CF6-50A, CF6-50C, CF6-50CA, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50E, CF6-50E1, CF6-50E2, and CF6-50E2B
2011-07-02	S 2005-02-03	Pratt & Whitney	Engine: JT8D-209, -217, -217A, -217C, and -219 series turbofan
Biweekly 2011-08			
2011-07-04		Boeing	DC-9-14, DC-9-15, DC-9-15F, DC-9-21, DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC-9-32F, DC-9-32F (C-9A), DC-9-32F (C9-B), DC-9-33F, DC-9-34, DC-9-34F, DC-9-41, and DC-9-51
2011-07-05 2011-07-06 2011-07-07 2011-07-08 2011-07-10 2011-07-11 2011-08-51	S 2010-10-18 E	Sigma Aero Seat Bombardier, Inc Fokker Services B.V. Airbus Bombardier, Inc. Dassault Aviation Boeing	Appliance: See AD CL-600-2B19 (Regional Jet Series 100 & 440) F.28 Mark 1000, 2000, 3000, and 4000 A340-211, -212, -213, -311, -312 and -313 BD-100-1A10 (Challenger 300) Mystere-Falcon 50 737-300, -400, and -500 series
Biweekly 2011-09			
2011-07-12 2011-08-02 2011-08-03 2011-08-04		Fokker Services B.V. Fokker Services B.V. Airbus Bombardier, Inc	F.27 Mark 050 F.27 Mark 050 A340-541 and -642 CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900)
2011-08-05		Airbus	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2011-08-08		Embraer	ERJ 170-100 LR, -100 STD, -100 SE, -100 SU, ERJ 170-200 LR, -200 SU, -200 STD, ERJ 190-100 STD, -100 LR, -100 ECJ, -100 IGW, ERJ 190-200 STD, -200 LR, and -200 IGW
2011-08-10	S 98-19-12	Rolls-Royce plc	Engine: RB211-Trent 768-60 and RB211-Trent 772-60 turbofan
2011-08-11 2011-08-12	S 2005-13-19	BAE Systems (Operations) Limited Airbus	BAe 146-100A, -200A, -300A, Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A A330-301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, A340-311, -312, and -313
2011-09-01 2011-09-02 2011-09-03 2011-09-05 2011-09-06	S 2002-02-07	Airbus Saab AB, Saab Aerosystems Lockheed Martin Corp Boeing Airbus	A340-541, and -642 340A (SAAB/SF340A) and SAAB 340B 382, 382B, 382E, 382F, and 382G 777-200, -300, and -300ER series A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, and -313

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency			
Biweekly 2011-10			
2011-08-07		Rolls-Royce plc	Engine: RB211-Trent 875-17, RB211-Trent 877-17, RB211-Trent 884-17, RB211-Trent 884B-17, RB211-Trent 892-17, RB211-Trent 892B-17, and RB211-Trent 895-17 turbofan
2011-09-07		Rolls-Royce plc	Engine: RB211-524G2-T-19, -524G3-T-19, -524H-T-36, -524H2-T-19; RB211 Trent 553-61, 553A2-61, 556-61, 556A2-61, 556B-61, 556B2-61, 560-61, 560A2-61; RB211 Trent 768-60, 772-60, 772B-60; RB211 Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17 turbofan
2011-09-10		Airbus	A300 B4-601, B4-603, B4-605R, C4-605R Variant F, and F4-605R airplanes, and A310-204 and -304
2011-09-11		Boeing	777-200 and -300 series
2011-09-12		Bombardier, Inc.	DHC-8-101, -102, -103, -106, -201, -202, -301, -311, -315, DHC-8-401, and -402
2011-09-13		Airbus	A340-211, -212, -213, -311, -312, and -313
2011-09-14		Boeing	747-200B, -300, -400, -400D, and -400F series
2011-09-15		Boeing	777-200, -200LR, -300, and -300ER series
2011-09-17	S 2010-01-07	Airbus	A340-211, -212, -213, -311, -312, -313, -541, and -642
2011-09-18		Dassault Aviation	FALCON 7X
2011-10-01		Dassault Aviation	FALCON 7X
2011-10-04		Rolls-Royce plc	Engine: RB211-Trent 875-17, -Trent 877-17, -Trent 884-17, -Trent 884B-17, -Trent 892-17, -Trent 892B-17, and -Trent 895-17 turbofan
Biweekly 2011-11			
2011-08-51		Boeing	737-300, -400, and -500 series
2011-09-04		Lockheed Martin Corporation	382, 382B, 382E, 382F, and 382G
2011-10-02		Boeing	747-400, 747-400D, and 747-400F series
2011-10-03		Embraer	ERJ 170-100 LR, -100 STD, -100 SE, -100 SU, ERJ 170-200 LR, -200 SU, -200 STD, ERJ 190-100 STD, ERJ 190-100 LR, ERJ 190-100 IGW, ERJ 190-200 STD, ERJ 190-200 LR, and ERJ 190-200 IGW
2011-10-05		Airbus	A310-203, -204, -222, -304, -322, and -324
2011-10-06		Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325
2011-10-07		Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325
2011-10-08	S 98-26-01 S 91-13-01	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325
2011-10-10		Airbus	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F
2011-10-14	S2010-24-08	Dassault Aviation	MYSTERE-FALCON 50
2011-10-15		Airbus	A318-112, A319-111, A319-112, A319-115, A319-132, A319-133, A320-214, A320-232, A320-233, A321-211, A321-213, and A321-231
2011-10-17	S 2007-04-11 S 2007-20-03 S 2007-25-02	Airbus	A300 B2-1A, B2-1C, B4-2C, B2K-3C, B4-103, B2-203, B4-203, A310-203, -204, -221, -222, -304, -322, -324, 325, A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, A300 C4-605R Variant F
2011-11-02		Bombardier, Inc.	DHC-8-400, -401, and -402

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency

Biweekly 2011-12

2010-24-13	COR	Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747SR, and 747SP series
2011-07-06	COR	Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2011-11-05	S 2007-15-05	Boeing	DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, DC-10-40F, MD-10-10F, MD-10-30F, MD-11, and MD-11F
2011-11-06	S 2002-03-10	BAE Systems (Operations) Limited	BAe 146-100A, -200A, -300A, Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2011-11-08		Rolls-Royce plc	Engine: RB211-535E4-37, -535E4-B-37, -535E4-B-75, and -535E4-C-37 turbofan
2011-12-01		Koito Industries, Ltd.	Appliance: Seats and seating systems
2011-12-51	E	Dassault Aviation	FALCON 7X

Biweekly 2011-13

2009-18-19 R1		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343 series, A340-211, -212, -213, -311, -312, and -313 series
2011-12-05		Boeing	727, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2011-12-06		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900)
2011-12-09		Boeing	737-100, -200, -200C, -300, -400, and -500 series
2011-12-11	S 2001-14-19	Boeing	767-200, -300, -300F series, 767-400ER series
2011-12-12		Boeing	MD-90-30
2011-12-13		Boeing	737-600, -700, -700C, -800, -900, and -900ER series
2011-12-14		Fokker Services B.V.	F.28 Mark 0070 and 0100

Biweekly 2011-14

2011-08-09		Embraer	EMB-120, -120ER, -120FC, -120QC, and -120RT
2011-12-51		Dassault Aviation	FALCON 7X
2011-13-04		Rolls-Royce plc	Engine: RB211-Trent 553-61, 553A2-61, 556-61, 556A2-61, 556B-61, 556B2-61, 560-61, and 560A2-61 turbofan
2011-13-06		Bombardier, Inc.	DHC-8-400, -401, and -402
2011-13-07	S 2010-02-02	Dassault Aviation	FALCON 7X
2011-13-08		Bombardier, Inc.	DHC-8-400, -401, and -402
2011-13-09	S 2007-05-08	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343
2011-13-10	S 2009-11-13	Learjet Inc	45
2011-13-11	S 2007-06-18	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233; A321-111, -112, -131, -211, -212, -213, -231, and -232

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency

Biweekly 2011-15

2011-09-09		Bombardier, Inc.	CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A and CL-601-3R Variants), and CL-600-2B16 (CL-604 Variants)
2011-12-13	COR	Boeing	737-600, -700, -700C, -800, -900, and -900ER series
2011-13-01		Rolls-Royce plc	Engine: RB211-524D4-19, -524D4-B-19, -524D4-39, -524D4-B-39, -524D4X-19, -524D4X-B-19, -524H-36, -524H2-19, -524H-T-36, -524H2-T-19, -524G2-19, -524G3-19, -524G2-T-19, and -524G3-T-19
2011-14-01		Airbus	A300 B4-601, B4-603, B4-620, B4-622; A300 B4-605R, B4-622R; A300 F4-605R, F4-622R; A300 C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325
2011-14-03		Boeing	DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87) and MD-88
2011-14-04		Dassault Aviation	FALCON 7X
2011-14-08		B/E Aerospace	Appliance: Continuous Flow Passenger Oxygen Mask Assembly
2011-14-10		Airbus	A330-342
2011-14-11		Boeing	747-400 and -400D series
2011-14-12		Saab AB, Saab Aerosystems	SAAB 2000
2011-15-01		Boeing	DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and MD-88
2011-15-02	S 2008-20-01	Lockheed Martin	382, 382B, 382E, 382F, and 382G
2011-15-03	S 97-26-07	Boeing	747-100, -100B, -100B SUD, -200B, -200C, -200F, -300, -400, -400D, -400F, 747SR, and 747SP series
2011-15-06		General Electric	Engine: GE90-76B; GE90-77B; GE90-85B; GE90-90B; and GE90-94B turbofan

Biweekly 2011-16

2011-14-06	S 2007-20-05	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2011-15-07		328 Support Services GmbH	328-100 and -300
2011-15-08		Airbus	A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R, B4-622R, A300 F4-605R, F4-622R, A300 C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325
2011-15-09	S 2011-05-14	Bombardier, Inc.	DHC-8-400, -401, and -402
2011-16-02		Boeing	747 and 767



2011-14-06 Airbus: Amendment 39-16741. Docket No. FAA-2011-0257; Directorate Identifier 2010-NM-122-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective August 22, 2011.

Affected ADs

(b) This AD supersedes AD 2007-20-05, Amendment 39-15215.

Applicability

(c) This AD applies to all Airbus Model A318-111, -112, -121, and -122 airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; Model A320-111, -211, -212, -214, -231, -232, and -233 airplanes; and Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes; certificated in any category.

Note 1: This AD requires revisions to certain operator maintenance documents to include new inspections. Compliance with these inspections is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by these inspections, the operator may not be able to accomplish the inspections described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (n) of this AD. The request should include a description of changes to the required inspections that will ensure the continued damage tolerance of the affected structure. The FAA has provided guidance for this determination in Advisory Circular (AC) 25.1529-1.

Subject

(d) Air Transport Association (ATA) of America Code 05: Wings.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

* * * * *

The issue 10 of Airbus A318/A319/A320/A321 ALI [Airworthiness Limitation Items] Document and issue 2 of Airbus A319 Corporate Jet ALI Document introduce more restrictive maintenance requirements/airworthiness limitations. Failure to comply with this issue 10 constitutes an unsafe condition.

* * * * *

The unsafe condition is fatigue cracking, accidental damage, or corrosion in principal structural elements and possible failure of certain life limited parts, which could result in reduced structural integrity of the airplane.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of Requirements of AD 2007-20-05: Revise Airworthiness Limitations Section (ALS) To Incorporate Safe Life ALIs

(g) For Model A318-111 and -112 airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; Model A320-111, -211, -212, -214, -231, -232, and -233 airplanes; and Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes: Within 3 months after November 7, 2007 (the effective date of AD 2007-20-05), revise the ALS of the Instructions for Continued Airworthiness to incorporate Sub-part 1-2, "Life Limits," and Sub-part 1-3, "Demonstrated Fatigue Lives," of Airbus A318/A319/A320/A321 ALS Part 1–Safe Life Airworthiness Limitation Items, dated February 28, 2006. Accomplish the actions in Sub-part 1-2, "Life Limits," and Sub-part 1-3, "Demonstrated Fatigue Lives," of Airbus A318/A319/A320/A321 ALS Part 1–Safe Life Airworthiness Limitation Items, dated February 28, 2006, at the times specified in Sub-part 1-2, "Life Limits," and Sub-part 1-3, "Demonstrated Fatigue Lives," of Airbus A318/A319/A320/A321 ALS Part 1–Safe Life Airworthiness Limitation Items, dated February 28, 2006, except as provided by paragraph (i) of this AD.

Revise ALS To Incorporate Damage-Tolerant ALIs

(h) For Model A318-111 and -112 airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; Model A320-111, -211, -212, -214, -231, -232, and -233 airplanes; and Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes; except Model A319 airplanes on which Airbus Modifications 28238, 28162, and 28342 have been incorporated in production: Within 14 days after November 7, 2007, revise the ALS of the Instructions for Continued Airworthiness to incorporate Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 7, dated December 2005 (approved by the EASA on February 7, 2006); Issue 08, dated March 2006 (approved by the EASA on January 4, 2007); or Issue 09, dated November 2006 (approved by the EASA on May 21, 2007). Accomplish the actions in Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 7, dated December 2005; Issue 08, dated March 2006; or Issue 09, dated November 2006; at the times specified in Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 7, dated December 2005; Issue 08, dated March 2006; or Issue 09, dated November 2006; as applicable; except as provided by paragraph (i) of this AD. Doing the actions required by paragraph (j) of this AD terminates the requirements of this paragraph.

Grace Period for New or More Restrictive Actions

(i) For Model A318-111 and -112 airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; Model A320-111, -211, -212, -214, -231, -232, and -233 airplanes; and Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes: For any new or more restrictive life limit introduced with Sub-part 1-2, "Life Limits," and Sub-part 1-3, "Demonstrated Fatigue Lives," of Airbus A318/A319/A320/A321 ALS Part 1–Safe Life Airworthiness Limitation Items, dated February 28, 2006, replace the part at the time specified in Sub-part 1-2, "Life Limits," and Sub-part 1-3, "Demonstrated Fatigue Lives," of Airbus A318/A319/A320/A321 ALS Part 1–Safe

Life Airworthiness Limitation Items, dated February 28, 2006, or within 6 months after November 7, 2007, whichever is later. For any new or more restrictive inspection introduced with Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 7, dated December 2005; Issue 08, dated March 2006; or Issue 09, dated November 2006; do the inspection at the time specified in Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 7, dated December 2005; Issue 08, dated March 2006; or Issue 09, dated November 2006; as applicable; or within 6 months after November 7, 2007, whichever is later.

New Requirements of This AD: Revise ALS To Incorporate Damage-Tolerant ALIs With Revised Compliance Times

(j) Within 9 months after the effective date of this AD: Revise the maintenance program by incorporating all maintenance requirements and associated airworthiness limitations specified in the Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 10, dated October 2009; or Issue 11, dated September 2010. Comply with all applicable maintenance requirements and associated airworthiness limitations included in Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 10, dated October 2009; or Issue 11, dated September 2010; except as provided by paragraph (k) of this AD. Doing the actions required by this paragraph terminates the requirements of paragraph (h) of this AD.

Special Compliance Times for Certain Tasks

(k) For new and more restrictive tasks introduced with Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 10, dated October 2009; or Issue 11, dated September 2010; as specified in table 1 of this AD: The initial compliance time for doing the tasks is specified in table 1 of this AD.

Table 1—Compliance Times for New Tasks

Task	Applicability (as specified in the applicability column of the task)	Compliance time, whichever occurs later	
545102-01-6	Group 19-1A CFM, Group 19-1B CFM, and Model A320-200 airplanes with CFM Industrial (CFM)/International Aero Engine (IAE) engines	The threshold as defined in Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 10, dated October 2009; or Issue 11, dated September 2010	Within 2,000 flight cycles or 5,500 flight hours, after the effective date of this AD, whichever occurs first

545102-01-7	Model A320-100	The threshold as defined in Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 10, dated October 2009; or Issue 11, dated September 2010	Within 2,000 flight cycles or 2,000 flight hours, after the effective date of this AD, whichever occurs first
572050-01-1 or alternative task 572050-02-1	Group 19-1A and Group 19-1B	At the time of the next due accomplishment of any one of the tasks 572004, 572020, or 572053 as currently described in the Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 7, dated December 2005; Issue 08, dated March 2006; or Issue 09, dated November 2006	Within 6 months after the effective date of this AD
572050-01-4 or alternative task 572050-02-4	Model A320-200	At the time of the next due accomplishment of any one of the tasks 572004, 572020, or 572053 as currently described in the Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 7, dated December 2005; Issue 08, dated March 2006; or Issue 09, dated November 2006	Within 6 months after the effective date of this AD
572050-01-5 or alternative task 572050-02-5	Group 21-1A	At the time of the next due accomplishment of any one of the tasks 572004, 572020, or 572053 as currently described in the Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 7, dated December 2005; Issue 08, dated March 2006; or Issue 09, dated November 2006	Within 6 months after the effective date of this AD

572050-01-7 or alternative task 572050-02-7	Model A320-100	At the time of the next due accomplishment of any one of the tasks 572004, 572020, or 572053 as currently described in the Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 7, dated December 2005; Issue 08, dated March 2006; or Issue 09, dated November 2006	Within 6 months after the effective date of this AD
534132-01-1	Model A320 PRE 30748	The threshold/interval as defined in Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 10, dated October 2009; or Issue 11, dated September 2010	Within 100 days after the effective date of this AD, without exceeding the previous threshold/ interval as defined in Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 7, dated December 2005; Issue 08, dated March 2006; or Issue 09, dated November 2006
531118-01-1	Model A318 (except (A318-121 and -122), Group 19-1A, Group 19-1B, Model A320, A321	The threshold/interval as defined in Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 10, dated October 2009; or Issue 11, dated September 2010	Within 100 days after the effective date of this AD, without exceeding the previous threshold/interval as defined in Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 7, dated December 2005; Issue 08, dated March 2006; or Issue 09, dated November 2006
531118-01-1	Model A318-121 and -122 airplanes	The threshold/interval as defined in Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 10, dated October 2009; or Issue 11, dated September 2010	Within 100 days after the effective date of this AD

Note 2: New ALI Task 572050 refers to the outer wing dry bay and is comprised of extracts from three ALI Tasks: 572004, 572020 and 572053. The threshold of ALI Task 572050 for the whole dry bay area is that of the lowest threshold of the source ALI tasks, i.e., that of ALI Task 572053.

No Alternative Life Limits, Inspections, or Inspection Intervals

(l) After the actions specified in paragraphs (g) and (h) of this AD have been accomplished, no alternative life limits, inspections, or inspection intervals may be used, except as provided by paragraphs (i) and (m) of this AD, and except as required by paragraph (j) of this AD.

(m) After the actions specified in paragraph (j) of this AD have been accomplished, no alternative life limits, inspections, or inspection intervals may be used.

FAA AD Differences

Note 3: This AD differs from the MCAI and/or service information as follows: European Aviation Safety Agency (EASA) AD 2010-0071R1, dated May 28, 2010, requires operators to comply with the limitations specified in Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 10, dated October 2009; or Airbus A319 Corporate Jet Airworthiness Limitation Items, Document AI/SE-M2/95A.1038/99, Issue 02, dated March 2009; as applicable. This AD requires incorporating Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 10, dated October 2009; or Issue 11, dated September 2010. Additionally, this AD does not require incorporating Airbus A319 Corporate Jet Airworthiness Limitation Items, Document AI/SE-M2/95A.1038/99, Issue 02, dated March 2009, because that ALI only specifies compliance with the limitations specified in Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 10, dated October 2009; or Issue 11, dated September 2010.

Other FAA AD Provisions

(n) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to Attn: Tim Dulin, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2141; fax (425) 227-1149. Information may be e-mailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

Related Information

(o) Refer to MCAI EASA Airworthiness Directive 2010-0071R1, dated May 28, 2010; Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 7, dated December 2005; Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 08, dated March 2006; Airbus A318/A319/A320/A321 Airworthiness

Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 09, dated November 2006; Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 10, dated October 2009; and Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 11, dated September 2010; for related information.

Material Incorporated by Reference

(p) You must use the service information contained in Table 2 of this AD to do the actions required by this AD, unless the AD specifies otherwise.

Table 2—All Material Incorporated by Reference

Document	Revision	Date
Airbus A318/A319/A320/A321 ALS Part 1 – Safe Life Airworthiness Limitation Items	Revision 00	February 28, 2006
Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96	Issue 7	December 2005
Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96	Issue 08	March 2006
Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96	Issue 09	November 2006
Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96	Issue 10	October 2009
Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96	Issue 11	September 2010

The issue level of Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 10, dated October 2009; and Issue 11, dated September 2010; is indicated only on the title page and in the Record of Revisions of these documents.

(1) The Director of the Federal Register approved the incorporation by reference of Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 10, dated October 2009; and Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96, Issue 11, dated September 2010; under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The Director of the Federal Register previously approved the incorporation by reference of the service information contained in table 3 of this AD on November 7, 2007 (72 FR 56262, October 3, 2007).

Table 3—Material Previously Incorporated by Reference

Document	Revision	Date
Airbus A318/A319/A320/A321 ALS Part 1 – Safe Life Airworthiness Limitation Items	Revision 00	February 28, 2006
Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96	Issue 7	December 2005

Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96	Issue 08	March 2006
Airbus A318/A319/A320/A321 Airworthiness Limitation Items, Document AI/SE-M4/95A.0252/96	Issue 09	November 2006

(3) For service information identified in this AD, contact Airbus, Airworthiness Office–EAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on June 24, 2011.

Ali Bahrami,
 Manager, Transport Airplane Directorate,
 Aircraft Certification Service.



2011-15-07 328 Support Services GmbH (Type Certificate Previously Held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH): Amendment 39-16754. Docket No. FAA-2011-0308; Directorate Identifier 2010-NM-233-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective August 22, 2011.

Affected ADs

(b) None.

Applicability

(c) This AD applies to 328 Support Services GmbH (Type Certificate previously held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH) Model 328-100 and -300 airplanes, certificated in any category, all serial numbers.

Subject

(d) Air Transport Association (ATA) of America Code 55: Stabilizers.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

During maintenance, it has been discovered that at the installation of the fixation brackets for rudder spring tabs and trim tabs an incorrect installation of the fixation brackets may have occurred. * * *

If the orientation of the fixation bracket is reversed or upside down the screws may not reach into the helicoil thread to a sufficient depth.

An incorrect installation, if not detected and corrected, could lead to an in-flight failure of the fixation brackets for rudder spring tabs and trim tabs resulting in and reduced control of the aeroplane.

* * * * *

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection

(g) Within 400 flight hours after the effective date of this AD, do a detailed inspection to determine if the fixation brackets for the rudder spring tabs and trim tabs are installed correctly, in accordance with the Accomplishment Instructions of 328 Support Services Service Bulletin SB-328-55-493, dated April 21, 2010 (for Model 328-100 airplanes); or SB-328J-55-245, dated April 21, 2010 (for Model 328-300 airplanes).

Corrective Action

(h) If, during the inspection required by paragraph (g) of this AD, any incorrect installation of the fixation brackets for rudder spring tabs and trim tabs is detected, before further flight, correct the installation of the fixation brackets for rudder spring tabs and trim tabs, in accordance with the Accomplishment Instructions of 328 Support Services Service Bulletin SB-328-55-493, dated April 21, 2010 (for Model 328-100 airplanes); or SB-328J-55-245, dated April 21, 2010 (for Model 328-300 airplanes).

Reporting

(i) Within 30 days after the inspection required by paragraph (g) of this AD, or within 30 days after the effective date of this AD, whichever occurs later: Send the inspection report to 328 Support Services GmbH by using the Compliance Report attached to 328 Support Services Service Bulletin SB-328-55-493, dated April 21, 2010 (for Model 328-100 airplanes); or SB-328J-55-245, dated April 21, 2010 (for Model 328-300 airplanes). Send the report by mail or fax to: Attention: Dept. C, 328 Support Services GmbH, Customer Services, P.O. Box 1252, D-82231 Wessling, Federal Republic of Germany; fax +49 (0) 8153 88111-6565.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(j) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Information may be e-mailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that

collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave., SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

Related Information

(k) Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2010-0134, dated June 30, 2010; and 328 Support Services Service Bulletins SB-328-55-493 and SB-328J-55-245, both dated April 21, 2010; for related information.

Material Incorporated by Reference

(1) You must use 328 Support Services Service Bulletin SB-328-55-493, dated April 21, 2010, including Compliance Report; or 328 Support Services Service Bulletin SB-328J-55-245, dated April 21, 2010, including Compliance Report; as applicable; to do the actions required by this AD, unless the AD specifies otherwise. Only the even pages of these documents include the document date. The compliance reports attached to these documents do not contain document numbers, revision levels, or dates.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact 328 Support Services GmbH, Global Support Center, P.O. Box 1252, D-82231 Wessling, Federal Republic of Germany; telephone +49 8153 88111 6666; fax +49 8153 88111 6565; e-mail gsc.op@328support.de; Internet <http://www.328support.de>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on July 6, 2011.

Kalene C. Yanamura,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2011-15-08 Airbus: Amendment 39-16755. Docket No. FAA-2011-0309; Directorate Identifier 2010-NM-255-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective August 22, 2011.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to all Airbus Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes, Model A300 B4-605R and B4-622R airplanes, Model A300 F4-605R and F4-622R airplanes, and Model A300 C4-605R Variant F airplanes; and Model A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes; certificated in any category.

Subject

- (d) Air Transport Association (ATA) of America Code 27: Flight controls.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

A specific failure case of the THSA [trimmable horizontal stabilizer actuator] upper primary attachment, which may result in a loading of the upper secondary attachment, has been identified by analysis.

Primary load path failure can be caused by bearing migration from the upper attachment gimbal by failure or loss of a retention bolt.

In case of failure of the THSA upper primary attachment, the THSA upper secondary attachment would engage. Because the upper attachment secondary load path can only withstand the loads for a limited period of time, the condition where it would be engaged could lead, if not detected, to the failure of the secondary load path, which would likely result in loss of control of the aeroplane.

* * * * *

Compliance

- (f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Installation

(g) Within 30 months after the effective date of this AD, install three retention plates on the THSA upper primary attachment, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A300-27-6066 (for Model A300-600 series airplanes) or Airbus Mandatory Service Bulletin A310-27-2103 (for Model A310 series airplanes), both dated June 10, 2010.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(h) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149. Information may be e-mailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

Related Information

(i) Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2010-0224, dated November 4, 2010; and Airbus Mandatory Service Bulletins A300-27-6066 and A310-27-2103, both dated June 10, 2010.

Material Incorporated by Reference

(j) You must use Airbus Mandatory Service Bulletin A300-27-6066, dated June 10, 2010; or Airbus Mandatory Service Bulletin A310-27-2103, dated June 10, 2010; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus SAS-EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this

material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on July 6, 2011.

Kalene C. Yanamura,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2011-15-09 Bombardier, Inc.: Amendment 39-16756. Docket No. FAA-2011-0718; Directorate Identifier 2011-NM-117-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective August 2, 2011.

Affected ADs

(b) This AD supersedes AD 2011-05-14, Amendment 39-16624.

Applicability

(c) This AD applies to Bombardier, Inc. Model DHC-8-400, -401, and -402 airplanes, certificated in any category, serial numbers 4001 and subsequent.

Subject

(d) Air Transport Association (ATA) of America Code 32: Landing Gear.

Reason

(e) The mandatory continued airworthiness information (MCAI) states:

Two cases of the main landing gear (MLG) alternate extension system (AES) cam mechanism failure were found during line checks. The cam mechanism operates the cable to open the MLG door and releases the MLG uplock in sequence. In the case where it is necessary to deploy the MLG using the AES, the failure of the MLG AES cam mechanism on one side will lead to an unsafe asymmetrical landing configuration.

* * * * *

The unsafe condition is possible loss of control during landing.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of Requirements of AD 2011-05-14, With New Service Information

(g) Within 50 flight hours or 10 days after March 25, 2011 (the effective date of AD 2011-05-14), whichever occurs first, do a detailed inspection for proper operation of the MLG AES cam mechanism, in accordance with paragraph A) of Bombardier Repair Drawing 8/4-32-0160, Issue 2, dated January 18, 2011; or Issue 3, dated February 15, 2011. Repeat the inspection thereafter at

intervals not to exceed 50 flight hours or 10 days, whichever occurs first, until the inspection required by paragraph (i) of this AD is accomplished.

(1) If the cam mechanism is found to reset to the normal rested position without any sticking or binding, it is operating properly.

(2) If the cam mechanism has not reset to its normal rested position, or if any sticking or binding is observed, before further flight, remove the cam assembly, in accordance with paragraph A) of Bombardier Repair Drawing 8/4-32-0160, Issue 2, dated January 18, 2011; or Issue 3, dated February 15, 2011; and do the actions in paragraph (g)(2)(i) or (g)(2)(ii) of this AD.

(i) Repair the cam mechanism assembly, including doing detailed inspections for discrepancies (including an inspection to determine proper operation, an inspection for damage, an inspection for corrosion and cadmium coating degradation, and inspections to determine dimensions are within the limits specified in paragraph B) of Bombardier Repair Drawing 8/4-32-0160, Issue 2, dated January 18, 2011; or Issue 3, dated February 15, 2011), in accordance with paragraph B) of Bombardier Repair Drawing 8/4-32-0160, Issue 2, dated January 18, 2011; or Issue 3, dated February 15, 2011; and install the repaired cam assembly in accordance with paragraph C) of Bombardier Repair Drawing 8/4-32-0160, Issue 2, dated January 18, 2011; or Issue 3, dated February 15, 2011.

(ii) Install a new or serviceable cam assembly, in accordance with paragraph C) of Bombardier Repair Drawing 8/4-32-0160, Issue 2, dated January 18, 2011; or Issue 3, dated February 15, 2011.

(3) If the cam mechanism is found damaged or inoperative during the repair specified in paragraph (g)(2)(i) of this AD, or if any discrepancies are found and Bombardier Repair Drawing 8/4-32-0160, Issue 2, dated January 18, 2011; or Issue 3, dated February 15, 2011; does not specify repairs for those discrepancies, or repairs specified in paragraph (g)(2)(i) of this AD cannot be accomplished: Before further flight, repair and reinstall using a method approved by the Manager, ANE-170, New York Aircraft Certification Office (ACO), FAA, or Transport Canada Civil Aviation (TCCA) (or its delegated agent); or install a new or serviceable cam assembly, in accordance with paragraph C) of Bombardier Repair Drawing 8/4-32-0160, Issue 2, dated January 18, 2011; or Issue 3, dated February 15, 2011.

Credit for Actions Accomplished in Accordance With Previous Service Information

(h) Actions done before March 25, 2011, in accordance with Bombardier 8/4-32-0160, Issue 1, dated January 14, 2011, are acceptable for compliance with the corresponding requirements of this AD.

New Requirements of This AD

(i) Within 50 flight hours or 10 days after the effective date of this AD, whichever occurs first, do a detailed inspection for proper operation of the MLG AES cam mechanism, in accordance with paragraph A) of Bombardier Repair Drawing 8/4-32-0160, Issue 3, dated February 15, 2011. Repeat the inspection thereafter at intervals not to exceed 50 flight hours or 10 days, whichever occurs first. Accomplishing this inspection terminates the requirements of paragraph (g) of this AD.

(1) If the cam mechanism is found to reset to the normal rested position without any sticking or binding, it is operating properly.

(2) If the cam mechanism has not reset to its normal rested position, or if any sticking or binding is observed, before further flight, remove the cam assembly, in accordance with paragraph A) of Bombardier Repair Drawing 8/4-32-0160, Issue 3, dated February 15, 2011, and do the actions in paragraph (i)(2)(i) or (i)(2)(ii) of this AD.

(i) Repair the cam mechanism assembly, including doing detailed inspections for discrepancies (including an inspection to determine proper operation, an inspection for damage, an inspection for corrosion and cadmium coating degradation, and inspections to determine dimensions are within the limits specified in paragraph B) of Bombardier Repair Drawing 8/4-32-0160, Issue 3, dated February 15, 2011), in accordance with paragraph B) of Bombardier Repair Drawing 8/4-32-0160, Issue 3,

dated February 15, 2011; and install the repaired cam assembly in accordance with paragraph C) of Bombardier Repair Drawing 8/4-32-0160, Issue 3, dated February 15, 2011.

(ii) Install a new or serviceable cam assembly, in accordance with paragraph C) of Bombardier Repair Drawing 8/4-32-0160, Issue 3, dated February 15, 2011.

(3) If the cam mechanism is found damaged or inoperative during the repair specified in paragraph (i)(2)(i) of this AD, or if any discrepancies are found and Bombardier Repair Drawing 8/4-32-0160, Issue 3, dated February 15, 2011, does not specify repairs for those discrepancies, or repairs specified in paragraph (i)(2)(i) of this AD cannot be accomplished: Before further flight, repair and reinstall using a method approved by the Manager, ANE-170, New York Aircraft Certification Office (ACO), FAA, or Transport Canada Civil Aviation (TCCA) (or its delegated agent); or install a new or serviceable cam assembly, in accordance with paragraph C) of Bombardier Repair Drawing 8/4-32-0160, Issue 3, dated February 15, 2011.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(j) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, ANE-170, New York ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

Related Information

(k) Refer to MCAI Canadian Airworthiness Directive CF-2011-01R1, dated May 20, 2011; Bombardier Repair Drawing 8/4-32-0160, Issue 2, dated January 18, 2011; and Bombardier Repair Drawing 8/4-32-0160, Issue 3, dated February 15, 2011; for related information.

Material Incorporated by Reference

(l) You must use Bombardier Repair Drawing 8/4-32-0160, Issue 2, dated January 18, 2011; or Bombardier Repair Drawing 8/4-32-0160, Issue 3, dated February 15, 2011; as applicable; to do the actions required by this AD, unless the AD specifies otherwise. The issue dates for Bombardier Repair Drawing 8/4-32-0160, Issue 3, dated February 15, 2011, are identified on only the first page of that document.

(1) The Director of the Federal Register approved the incorporation by reference of Bombardier Repair Drawing 8/4-32-0160, Issue 3, dated February 15, 2011, under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The Director of the Federal Register previously approved the incorporation by reference of Bombardier Repair Drawing 8/4-32-0160, Issue 2, dated January 18, 2011, on March 25, 2011 (76 FR 13080, March 10, 2011).

(3) For service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; e-mail thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on July 6, 2011.

Kalene C. Yanamura,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2011-16-02 The Boeing Company: Amendment 39-16760; Docket No. FAA-2008-0402; Directorate Identifier 2007-NM-165-AD.

Effective Date

- (a) This AD is effective August 30, 2011.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to The Boeing Company Model 747 airplanes and Model 767 airplanes, certified in any category, equipped with General Electric Model CF6-80C2 or CF6-80A series engines.

Subject

- (d) Air Transport Association (ATA) of America Code 30: Ice and rain protection.

Unsafe Condition

(e) This AD was prompted by reports of several in-flight engine flameouts, including multiple dual engine flameout events and one total power loss event, in ice-crystal icing conditions. We are issuing this AD to ensure that the flightcrew has the proper procedures to follow in certain icing conditions. These certain icing conditions could cause a multiple engine flameout during flight with the potential inability to restart the engines, and consequent forced landing of the airplane.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Airplane Flight Manual (AFM) Revision

(g) Within 14 days after the effective date of this AD, revise the Limitations Section of the Boeing 747 or 767 AFM, as applicable, to include the following statement. This may be done by inserting a copy of this AD into the AFM.

"Prior to reducing thrust for descent in visible moisture and TAT less than 10 °C, including SAT less than -40 °C, nacelle anti-ice switch must be in the ON position. At or below 22,000 ft, wing anti-ice selector must be in the ON position. When these icing conditions (visible moisture and TAT less than 10 °C, including SAT less

than -40 °C) are no longer present or anticipated, place the nacelle and wing anti-ice selectors in the OFF (or AUTO) position."

Note 1: When a statement identical to that in paragraph (g) of this AD has been included in the general revisions of the AFM, the general revisions may be inserted into the AFM, and the copy of this AD may be removed from the AFM.

Special Flight Permits

(h) Special flight permits, as described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), may be issued to operate the airplane to a location where the requirements of this AD can be accomplished provided the operational requirements defined in the Limitations Section of the AFM are used if icing is encountered.

Related Information

(i) For more information about this AD, contact Rebel Nichols, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; phone: 425-917-6509; fax: 425-917-6590; e-mail: rebel.nichols@faa.gov.

Material Incorporated by Reference

(j) None.

Issued in Renton, Washington, on July 14, 2011.
Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.