

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate

Number **ST01150LA**

This Certificate issued to Orcon Corporation
7560 Bristow Ct., Suite C
San Diego, CA 92154

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part * of the * Regulations.*

*Certification basis is set forth in Type Certificate Data Sheet A6WE.

Original Product Type Certificate Number: A6WE

Make: McDonnell Douglas

Model: DC-9-81, DC-9-82, DC-9-83, DC-9-87 and MD-88

Description of Type Design Change:

Insulation Blankets Installation in accordance with FAA Approved Orcon Corporation Index List, F83001, Revision A, dated February 19, 2001, or later FAA approved revision.

Limitations and Conditions: The installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. The approval of this modification applies to the above noted airplane model series only. A copy of this STC must be included in the permanent records of the modified aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: December 19, 2000

Date reissued: October 5, 2016

Date of issuance: March 19, 2001

Date amended: August 17, 2001, February 28, 2002

By direction of the Administrator



(Signature)
Manager, Cabin Safety, Mechanical &
Environmental Systems Branch
Los Angeles Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.