

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

COPY

Number SR02408NY-D

This certificate issued to

Keystone Helicopter Corp.
110 E. Stewart Huston Drive
Coatesville, PA 19320

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified herein meets the airworthiness requirements of Part 29 of the Federal Aviation Regulations.

Original Product - Type Certificate Number R00024BO

Make: Sikorsky

Model: S-92A

Description of Type Design Change: Installation of a Spectrolab Nightsun II XP Searchlight in accordance with Keystone Helicopter Installation drawing List IDL01231 Rev. F dated 03/20/2008 or later FAA approved revision.

Limitations and Conditions:

1. Keystone Helicopter Instructions for Continued Airworthiness SAR Searchlight System Installation, Report No. IC01231 Rev. C dated January 15, 2008 or later FAA accepted revision is required for this modification.
2. FAA Approved Rotorcraft Flight Manual Supplement, Supplement No. FM01231 Rev. 1 dated 03/30/2008 or later FAA approved revision is required for this modification
3. This approval should not be incorporated in any aircraft of this specific model on which other approved modifications are incorporated, unless it is determined that the interrelationship between this change and any of those previously incorporated approved modification will not introduce any adverse effect upon the airworthiness of the aircraft.
4. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : July 7, 2006

Date reissued :

Date of issuance : April 18, 2007

Date amended : March 30, 2008

By direction of the Administrator

James A. Munda
(Signature)

James A. Munda
DAS Administrator
DAS-800670-NE

(Title)



Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.